


QC-4000



**OPERATORS  
MANUAL**



# TABLE OF CONTENTS

## **CHAPTER ONE -----GETTING STARTED**

Getting Started .....	1-1
Conventions .....	1-1
Starting the QC-4000 .....	1-2
Getting around the QC-4000 .....	1-3
QC-4000 Basics .....	1-4
Opening a QC-4000 Window.....	1-6
Closing a Window.....	1-7
Using the control-menu box in the window.....	1-7
Sizing the QC-4000 windows .....	1-8
Repositioning a Window.....	1-9
Shrinking the QC-4000 to an Icon.....	1-10
Enlarging a window .....	1-11
Restoring an Icon or Window.....	1-12
Quitting the QC-4000 .....	1-13

## **CHAPTER TWO -----THE QC-4000 SCREEN**

The QC-4000 Screen .....	2-1
Status Bar.....	2-2
The Title Bar.....	2-2
The Menu Bar .....	2-4
Menu Conventions .....	2-4
The Menus .....	2-5
File Menu .....	2-5
Edit Menu.....	2-7
Measure Menu.....	2-8
Datum Menu .....	2-8
Probe Menu .....	2-9
Windows Menu .....	2-11
View Menu .....	2-12
Program Menu.....	2-13

# TABLE OF CONTENTS

## **CHAPTER THREE ----- THE QC-4000 WINDOWS**

The Status Bar .....	3-1
The Digital Readout.....	3-1
The Toolbox .....	3-2
Toolbox Icons.....	3-3
The Feature List.....	3-7
Selecting the features from the Feature List: .....	3-8
Changing the feature name.....	3-9
Results Window .....	3-10
Form Information .....	3-10
Results Information.....	3-10
Tolerance Button .....	3-12
Change Button .....	3-12
Changing All Feature names .....	3-15
Changing Relations .....	3-16
Feature Stamp .....	3-20
The Part View.....	3-23
Selecting the features from the Part View .....	3-24
Zooming in on Area .....	3-25
Show Name .....	3-26
Customizing names .....	3-26
Refresh Part View.....	3-26
The Program View .....	3-27
Editing a Program.....	3-28

## **CHAPTER FOUR ----- DEMONSTRATION**

About this Section .....	4-1
Conventions .....	4-1
Selecting a measurement function.....	4-2
Targeting Points .....	4-3
Getting Started .....	4-6
Axis Orientation .....	4-6
To Check Count direction: .....	4-6
To Reverse Axis: .....	4-6
About Reference Marks and Machine Zero.....	4-7
Enabling Reference Marks: .....	4-8
Reference Mark Calibration: .....	4-8
Establishing a Reference Frame .....	4-9

# TABLE OF CONTENTS

## **CHAPER FOUR (CONT'D) ----- DEMONSTRATION**

Point Measurement .....	4-11
Average Point .....	4-13
Line Measurement .....	4-14
Circle Measurement .....	4-16
Distance Measurement .....	4-18
Arc Measurement .....	4-20
Angle Measurement .....	4-21
Advanced Demonstration .....	4-25
Constructing a Feature .....	4-25
Angle Construction .....	4-26
Skewing On Two Circles .....	4-27
Creating features .....	4-28
Create a Point .....	4-29
Create a Line using 2 points .....	4-29
Create a Circle .....	4-30
Create an Arc .....	4-31
Creating a Tangent Circle .....	4-33
Using Measure Magic .....	4-34
Measure Magic Probing Techniques .....	4-34
Continue Reading .....	4-35

## **CHAPTER FIVE ----- CUSTOMIZING THE QC-4000**

Customizing The QC-4000 .....	5-1
The Preference Menu .....	5-1
Preferences .....	5-1
Sound .....	5-2
Measure .....	5-3
Part View .....	5-8
The Toolbox .....	5-12
Results .....	5-13
Locks .....	5-14
Language .....	5-14

# TABLE OF CONTENTS

## **CHAPTER SIX ----- MEASURE MAGIC**

Measure Magic.....	6-1
Before you Begin .....	6-2
Using Measure Magic.....	6-2
Using the Change Button.....	6-4

## **CHAPTER SEVEN ----- USER PROGRAMMING**

User Programming.....	7-1
About User Programs.....	7-2
Creating A Program -- Self Teach.....	7-3
Points to Remember .....	7-3
Start A <u>N</u> ew Session.....	7-4
Skew the Part .....	7-5
Establishing a <u>Z</u> ERO Datum.....	7-5
Start Recording a Program.....	7-6
Name the Program .....	7-6
Establish a Reference.....	7-7
Perform the measurements.....	7-7
End <u>R</u> ecording.....	7-8
Special Steps .....	7-9
Running a Program .....	7-10
Close The Program.....	7-10
Editing User Programs .....	7-10
System Settings .....	7-14
What is Point Filtration? .....	7-16
Using Point Filtration .....	7-17
Importing Autocad DXF Files Into The QC-4000 .....	7-18
Export of the Part View in DXF Format.....	7-19
Creating a part program from a CAD file .....	7-19
Run the Program.....	7-21
Using Record Zoom In A Program.....	7-22
Deleting Programs and Sessions.....	7-25
Programming Summary .....	7-26

# TABLE OF CONTENTS

## **CHAPTER EIGHT----- REFERENCE**

About this Section .....	8-1
What is a Session? .....	8-1
What is a Feature? .....	8-1
Polar Coordinates .....	8-2
Datuming .....	8-3
Frame Command .....	8-3
Skewing .....	8-5
Zero .....	8-6
Use Machine .....	8-7
Set Machine Zero .....	8-8
Multi-Point Measurements .....	8-9
Find Feature .....	8-12
To search for a feature: .....	8-12
Specifying Search Criteria .....	8-13
Feature Types .....	8-13
Logic Operators .....	8-14
To find specified features: .....	8-15
Adding and Removing Features .....	8-16
Adding other Criteria .....	8-16
Removing features .....	8-16
Tolerancing .....	8-17
Tolerancing Information .....	8-18
Tolerance Types .....	8-20
Disclaimer .....	8-20
Tolerance of Location .....	8-20
Size Tolerance .....	8-21
Orientation Tolerances .....	8-22
Form Tolerance .....	8-25
Group Tolerancing .....	8-25
About Print/Pause Pass/Fail .....	8-26
Using Tolerance in a Program .....	8-27
What happens when the program is run? .....	8-29
When Tolerancing Remember: .....	8-30
Tolerance Report Sample .....	8-31
Report Header .....	8-32
Print Selected Features .....	8-33
Exporting to Excel .....	8-35
DDE .....	8-37

# TABLE OF CONTENTS

## **CHAPTER NINE-----SUPERVISOR SETUP**

Supervisor Setup.....	9-1
Display.....	9-2
Axes.....	9-2
LEC.....	9-3
Axis Board Test.....	9-5
NLEC.....	9-6
Locks.....	9-6
CNC I/O Test.....	9-7
Edge IO Test.....	9-8
Footswitch.....	9-8
Software Fence.....	9-8
Machine Zero.....	9-8
Print.....	9-9

## **CHAPTER TEN-----OPTIONS**

Option Overview.....	10-1
Foot Switch.....	10-3
Electronic Protractor.....	10-5
Setting the Q axis encoder (linear or rotary).....	10-5
Non-Linear Error Correction.....	10-8
The Theory.....	10-8
Setting up NLEC.....	10-10
Establish a "Machine 0,0.".....	10-10
Start a "New Session.".....	10-10
Make sure NLEC is not active.....	10-11
Align Grid.....	10-11
Setting Grid Size.....	10-12
Measuring the Grid.....	10-12
Completing the Procedure.....	10-13
Optical Edge Detection.....	10-14
Edge Detection Operation.....	10-14
About Edge Detection.....	10-14
What is Optical Edge Detection?.....	10-14
How Edge Detection Works.....	10-15
The Sensors.....	10-15
Connecting the Edge Detector to the QC-4000.....	10-16
QC-4000 Edge Input/Output Card.....	10-16



# TABLE OF CONTENTS

## **CHAPTER TEN (CONT'D) -----OPTIONS**

Cautions about Fiber Optic Cables .....	10-17
Connecting the Screen Sensor .....	10-17
Connecting the Reference Sensor .....	10-17
Placing the Reference Sensor Outside the Lamp Housing.....	10-18
Placing the Reference Sensor Inside the Lamp Housing.....	10-18
Connecting the Edge Box to the QC-4000 .....	10-19
Powering up the QC-4000 with Edge Detection .....	10-19
Checking the Light Source .....	10-19
Teach the light levels to the QC-4000: .....	10-21
Editing the Teach Command.....	10-21
Teach to Master .....	10-22
Other Edge Features.....	10-25
Show Edge Detector .....	10-25
Edit Edge Point Measurements .....	10-25
Probe Offset .....	10-27
Force Teach .....	10-28
QC-4000 Light Control .....	10-29
The Toolbox.....	10-29
Light control Quick- Sliders.....	10-30
Programming with light control .....	10-31
SPC .....	10-32
Statistical Process Control .....	10-32

## **CHAPTER ELEVEN -----REPORT WIZARD**

Report Wizard .....	11-1
What is it? .....	11-1
How easy is it to use? .....	11-1
Printing Features .....	11-2
Report.....	11-3
Browse .....	11-4
Edit Form .....	11-4
Printer .....	11-4
File .....	11-4
Clipboard .....	11-4
Pre Form Feed .....	11-5
Toleranced Features Only .....	11-5

# TABLE OF CONTENTS

## **CHAPTER ELEVEN (CONT'D) ----- REPORT WIZARD**

Creating a form .....	11-6
Editing the Header.....	11-11
Preferences .....	11-12
Print Gridlines.....	11-12
Print Header .....	11-12
Header On Each Page .....	11-12
Print Column Headings .....	11-12
Numbers Only .....	11-13
Report Summary .....	11-14
Writing to an ASCII File.....	11-15
Append .....	11-16
Auto Number .....	11-17
Overwrite Always.....	11-17
Warn On Overwrite .....	11-17
Menu Explanations.....	11-21
FILE .....	11-21
EDIT .....	11-22
GENERAL.....	11-22
Position .....	11-23
Size .....	11-25
Other .....	11-28

# QC-4000 LICENSE AGREEMENT

## READ THIS DOCUMENT PRIOR TO OPENING ANY PACKAGES



This is a legal agreement between you, the end user, and METRONICS. By opening this package, you are bound by this agreement.

## SOFTWARE LICENSE



- 1. GRANT OF LICENSE.** METRONICS grants you the right to use one copy of the QC-4000 with the computer hardware supplied by METRONICS as one functioning measuring system. Additional copies of the SOFTWARE may be made and utilized only as training and off-line programming tool provided, however, that any such copy is never utilized as software in a measuring system. The use of any copy of the software for any purpose other than training of off-line programming is unlawful and strictly prohibited.
- 2. COPYRIGHT.** The software and accompanying written material is owned by METRONICS, and is protected by United States copyright laws and international treaty provisions. Therefore, you must treat the SOFTWARE like any other copyrighted material except that you may either (a) make one copy of the SOFTWARE solely for backup or archival purposes, or (b) transfer the SOFTWARE to a single hard disk provided you keep the original solely for backup or archival purposes. You may not copy the written materials accompanying the SOFTWARE.
- 3. OTHER RESTRICTIONS.** You may not reverse engineer, disassemble, decompile, or in any way attempt to circumvent the protection system incorporated in the SOFTWARE.
- 4. LIMITATION OF LIABILITY.** In no event shall METRONICS or its suppliers be liable for any special, incidental, or consequential damages whatsoever (including without limitation, damages for loss of business information) arising out of the use or inability to use this software.



Back View



**EXPANSION SLOTS**



---

# Chapter One



## Getting Started

Starting the QC-4000  
Getting Around the QC-4000  
QC-4000 Basics  
Sizing the QC-4000 Windows  
Quitting the QC-4000



QC-4000







## ***GETTING STARTED***

Welcome to the QC-4000, a powerful PC based measuring tool. It is an easy to use system, incorporating pull down menus, mouse, and movable, sizable windows which can be opened and closed as needed.

This manual is divided into several sections and is written to cover basic QC-4000 functions. Along the way, you might need to know a little more about DOS or Windows than we can provide you with, so you may be asked to refer to one of the other User Guides that was shipped with your system.

## ***CONVENTIONS***

### ***The Keyboard***

- The keys on your keyboard may not be labeled exactly as they are in this manual. All key names are shown using small capital letters. For example, the Control key is shown as CTRL; the Escape key is shown as ESC.
- Keys are frequently used in combinations or sequences. For example, SHIFT+ F1 means hold down the SHIFT key while pressing F1, and ALT, F, A means to press and release each of these keys in order: first ALT, then F, and then A.
- *Arrow keys* is the collective name for the UP ARROW, DOWN ARROW, LEFT ARROW, and RIGHT ARROW keys.
- To choose a command from a menu, you can use the mouse or press a key combination. In procedures, key sequences follow the menu and command names. For example: From the File menu, choose Open (ALT, F, O).

## ***STARTING THE QC-4000***

The QC-4000 is installed at the factory. However, there are several ways to start the QC-4000 to the system. Your system may be set up so that the QC-4000 will automatically appear on your screen as soon as you turn your system on. If it is, you may skip this section and continue to "Getting Around the QC-4000".

The following is the most recommended way to boot the QC-4000.

### **From DOS:**

\* Your DOS prompt will look like this: **C:\>\_**

\* Type: **win** after the DOS prompt, then press ENTER.

*(Typing **win** after the DOS will bring up Microsoft Windows.)*

### **From Microsoft Windows:**

\* Once in Windows you will see the QC-4000 Icon.



\* Start the QC-4000 simply by double-clicking on the Icon, or click on the icon one time to select it and choose "Open" from the FILE menu.

## ***GETTING AROUND THE QC-4000***

There are different methods to give commands or move around in the QC-4000. One method is with the mouse. Another is with the keyboard. After becoming familiar with the QC-4000 you might want to use a combination of both the mouse and keyboard commands.

### **Using the Mouse**

The mouse is a tool used for pointing to parts of the screen. Moving the mouse around on your desk, moves the pointer, but does not execute a command until you depress one of the mouse buttons.

To give the QC-4000 a command, you must point the mouse at the information and click, double-click, or drag the pointer.

- \* **Clicking** - Press the **LEFT** mouse button once.
- \* **Double-Clicking** - Press the **LEFT** mouse button twice quickly.
- \* **Dragging** - Hold down the **LEFT** mouse button while moving the Mouse.

### **Using the keyboard**

Commands may also be executed via the keyboard. Notice that the menus have one letter in each word underlined.


- \* Holding down the **ALT** key on the keyboard and pressing the underlined letter will open up a pull down menu.
- \* Once the menu is opened, depress the letter that is underlined in the pull down menu. You do not have to hold the **ALT** key in the pull down menu.
- \* You can also use the *down arrow* key to highlight the command you wish to open, then press ENTER.

*Note: The keyboard command keys will appear inside parentheses ( ) at the end of a mouse command.*

## QC-4000 BASICS

If you are familiar with Windows, feel free to go on to Chapter 2.

When the screen appears, most of the windows in the QC-4000 will be opened. See Figure below. Your window setup may look somewhat different from the following picture. This will be due to the options that you might have. For example, if your QC-4000 does not have the Edge Detector Option, your menu bar will not have PROBE as one of the Menu Titles in the menu Bar.



QC-4000 Screen - Figure 1 - 1

The following section will introduce the parts and features of the QC-4000 screen. You can also customize your windows setup using these elements, which will be explained later in the manual.

- \* The **Control-menu box** resides in the upper-left corner of each window. The Control menu (also called the System Menu) is generally used if you prefer to use your keyboard to move, resize, maximize, minimize, and close windows. Since you can accomplish all these functions by clicking and dragging your mouse, we suggest you use the Control menu box only as a fast way to close any window by double-clicking on it.

You may notice that the Control Menu bars are two different sizes. This is for the keyboard users to differentiate between them. The larger of the bars can be opened by holding down the **ALT** key and pressing the **spacebar**. The smaller bar is opened by holding down the **ALT** key and pressing the (-) minus key.

- \* The **Title Bar** is always located on the top of the window. It's not only where the QC-4000 name resides, it is also where the name of your session will be placed. When you Save and name your session it will appear in the Title Bar after the QC-4000 heading.
- \* The **Maximize and Minimize buttons** are the small up and down arrows at the right hand corner of the title bar. They enlarge the active application window to fill the entire desktop or shrink the window to an icon. The application icon will appear on the lower portion of your desktop. It can be reopened by *double-clicking* on the icon or by clicking on the icon once, and choosing *Restore or Maximize*. After you enlarge a window, the Maximize button changes to a **Restore button**. You can use the Restore button to return the window to its previous size.
- \* The **Menu bar** lists the available menus. Most applications have a File, Edit and Help menu. Because the QC-4000 is capable of having several options, you will also have unique menus that will apply to the options you have in your system.

- \* **Scroll bars** let you view unseen portions of lists and other information that is too large to fit in the allotted space. (The Results Window will only have scroll bars when more than one feature from the Feature List is selected.)
- \* The **window border** is the outside edge of a window. You can lengthen or shorten each side of a window by dragging a border.
- \* The **window corner** can be used to shorten or lengthen two sides of a window at the same time by dragging the corner.


### ***Opening a QC-4000 Window***

Opening a window is accomplished through the Windows Menu. There is an exception of course; this being the Results Window. The Results Window will open automatically after a measurement or by Double-Clicking on an existing feature in the feature list.

1. Select Windows from menu bar by left clicking on WINDOWS. (ALT, W) Notice that the pull-down menu does not have a check mark on the closed windows.
2. Left mouse click on the window name you wish to open. (D,T,S,P,F,R, or G)

Once the menu is open, you can also use the arrow keys to highlight the window you wish to open, then press ENTER.

This will place a check mark next to the word and open that window.



**Note:** Features must appear on the feature list to open the Results Window via the **Double-clicking** method.


## Closing a Window

When you are working with the QC-4000, there may be times that you will not need all the windows appearing at one time. The QC-4000 allows you to **close** all or selected windows to give you more work space.

Like most elements in the QC-4000 or Windows for that matter, there are several methods for doing the same thing. In this section, we'll walk you through the different methods for closing a window. These same "Methods" can be used for all the windows within the QC-4000.

1. Select WINDOWS from menu bar (ALT, W).  
Notice that the pull-down menu has a check mark on all open windows.
2. Left mouse click on the window name you wish to close (D, T, S, P, F, R, or G).

This will remove the check mark next to the word and close that window.



### Using the Control-menu box in the window

- 1a. Click on the *Control-menu box* which resides in the upper-left corner of a window (ALT, -). This will open a pull-down menu.

- 1b. Move the mouse pointer down to CLOSE in the menu and left click on the mouse button. (C)

- 2a. Choose ALT, F4



- 3a Last but not least *Double-click* on the Control-Menu Bar. (You might find this the fastest and easiest way).


## ***SIZING THE QC-4000 WINDOWS***

The windows within the QC-4000 default to a certain position. Sometimes you might want to change the size and shape of the windows to suit your needs. For example, you may want to enlarge your part view and make your feature list smaller. You also might want to make these changes only temporary or change the default so that the windows will open in the same position whenever you turn the QC-4000 on.

**Note:** *Some windows are limited in the ways their size can be changed. For example, the Results Window will shrink down to approximately 1.5 inches by 4 inches. The toolbox cannot be enlarged or sized, it can only rearrange its shape depending on how many tools are in it.*

### **To change to size of a window**

1. Left-click once to select the window you wish to resize.
2. Point to a border or corner that you want to move. The pointer will change to a two-headed arrow.
3. Hold down the *left* mouse button and drag the corner or border until the window is the size you want.



If you drag a **border**, the window size will only change the side you drag. If you drag a **corner**, the two adjoining sides that form the corner will change size at the same time.




## *Repositioning a Window*

When you first open the QC-4000, you will notice that the windows have been defaulted to a certain position. If these position do not suit your needs, you can easily customize the QC-4000 by moving and resizing the individual windows to best suit your needs.

Repositioning a window is just as easy as sizing.

1. Place the mouse arrow over the "Title Bar".
2. Hold down the **left** mouse button.
3. While still holding the mouse button down, drag the window to the desired position.
4. Release the mouse button.

**Note:** *When repositioning a window, only the frame of the window will appear to move. After the mouse button is released, the window will move into the same position as the frame. ( See figure 1-2)*



*Figure 1 - 2*

When you are finished sizing and repositioning your windows, you can save this as the default by choosing "Save Session" from the FILE menu. Choosing YES while exiting the QC-4000 will also save the appearance. Refer to "Quitting the QC-4000" for more information.


## *Shrinking the QC-4000 to an Icon*

You can shrink the QC-4000 to an icon when you have completed a session, but want it available for later use. When you shrink the QC-4000 to an icon, the application is still running in memory, but its window will not take up space of your desktop.

**Note:** Only one copy of the QC-4000 can be run at a time. If you try to open another QC-4000, a message will appear indicating that a QC-4000 program is already running.

### To shrink the QC-4000 to an Icon (Mouse)

1. Click the Minimize button in the upper-right corner of the window.



### To shrink the QC-4000 to an Icon (Keyboard)


1. Press **ALT**, SPACEBAR. This will open up a pull-down menu.
2. Using the down arrow, select Minimize and press ENTER, or press the **N** on the keyboard.

## *Enlarging a window*

**Enlarging** the windows will fill a large portion of the screen, and cover all other windows. Don't be alarmed however, when you restore your window to it's original size, your other windows will still be there.

### **To enlarge a window (Maximize) (Mouse)**

1. Select the window you wish to enlarge.
2. Click the Maximize button (up arrow) in the upper-right corner of the window.



### **To enlarge a window (Maximize) (Keyboard)**

1. Press **ALT**, SPACEBAR. This will open up a pull-down menu.
2. Using the down arrow, select Maximize and press ENTER, or press the x on the keyboard.

## ***Restoring an Icon or Window***

### **To Restore the QC-4000 Icon (Mouse)**

1. Double-click on the QC-4000 Icon. Or click on the Icon one time, then select Restore.

### **To Restore the QC-4000 Icon (Keyboard)**

1. Press **CTRL, ESC**. This will bring up a "Task List".
2. Using the down arrow, Select the QC-4000.
3. Use the **TAB** key until "**Switch to**" is highlighted.
4. Press **ENTER** or **ALT S**. This will "Restore" the QC-4000 to its previous size.

### **To Restore the QC-4000 to its previous size**

Once the window is enlarged or maximized, the single up arrow will change to a *double* arrow. The *double arrow* is now called the "**Restore**" button. When the Restore button is displayed, you cannot move or size the QC-4000 Window.

1. Click on the "Restore" button. This will restore the window back to a previous sizable window.

**Note:** *The procedure for sizing, moving and closing windows within the QC-4000 is the same as the procedure for Windows itself. If you feel you need more information on sizing, moving, or closing, please refer to the "Windows" manual.*

## ***QUITTING THE QC-4000***

When you are finished working with the QC-4000, the user has the choice of "Exiting to Windows", or "Shut Down".

EXIT TO WINDOWS - will bring the user to the Windows Program Manager.

SHUT DOWN - will close the QC-4000 and Windows and will place you in DOS.

No matter which one you choose, you will always be asked to confirm your request to quit. It also asks if you would like to "Save Session". If you press "Yes" the QC-4000 will save any changes made to the session before switching to the Windows Program Manager. If you choose "Shut Down", it will also ask if you want to "Save" any other windows applications that might be running in addition to the QC-4000.

### **To QUIT the QC-4000 (Mouse)**

1. Left click on the FILE menu.
2. Left click on Exit to Windows or Shut Down.

### **To QUIT the QC-4000 (Keyboard)**


1. Press **ALT F** to open the pull-down menu.
2. Select **(x)** to Exit to Windows or **(h)** to Shut Down. You can also use the down arrow key to highlight Exit to Windows or Shut down, then press ENTER.

Choosing YES will save any changes in your session and all locations and sizes of your QC-4000 Windows. Choose NO if you do not want to save changes. If you choose "Shut Down" you will be asked to "Save Changes to session" then you will be asked to "Save changes" to any other Windows applications you may have opened.



---

## *Chapter Two*



## *Fundamentals of the QC-4000*

The QC4000 Screen  
The Status Bar  
The Title Bar  
The Menu Bar  
Menu Conventions  
The Menus





## THE QC-4000 SCREEN

This section is probably the most important one in this manual since it explains the basic concepts and skills you need to work with the QC-4000 successfully. This chapter teaches the essentials of Operating the QC-4000 and what each item means. You can return to it later as a reference.

When the screen appears, most of the windows in the QC-4000 will be opened. Your window setup may look somewhat different from the picture. This will be due to the options that you might have. For example, if your QC-4000 has the Edge Detector Option, your menu bar will have PROBE as one of the selections in your menu.

*Note: The Program View window, will only open if selected.*




Figure 2 - 1

## ***STATUS BAR***

When visible, the **Status Bar** will always appear at the top of the screen under the Title Bar. The information on the status bar will always include the time, date, unit of measure (in/mm), and coordinates (Polar/Cartesian)


The Unit of measure and Coordinates are toggles. Each time these commands are selected, they will toggle between Inch and Millimeter or Cartesian and Polar.



*Figure 2 - 2*

Other commands that may appear on the Status Bar are associated with QC-4000 Options. Since these buttons are menu shortcuts, please feel free to click and play.

## ***The Title Bar***




*Figure 2 - 3*


The **Title Bar** is always located on the top of the window. This is where the QC-4000 name resides. When you perform a "Save Session As" command the name of your session will be placed after "QC-4000."

***To perform a Save Session As Command***

1. Using the Keyboard or mouse, select FILE from the menu.
2. Choose the "Save Session As" command. The following screen appears.

*Figure 2 - 4*

3. Select a drive if necessary, then type the name you wish to call the session. For example, this one will be named (DEMO).
4. Press OK or ENTER. DEMO is now placed in the Title Bar.

*Figure 2 - 5*

## *The MENU Bar*

The QC-4000 Menu Bar consists of several different menu names. File, Edit, Measure, Datum, Windows and View are some examples of what you might find in your menu bar. Different menu items will appear if you have purchased a separate option such as the Edge Detection option.

As you operate the QC-4000, you will get to know these quite well. The menus can be opened by clicking on the *left* mouse button, or by holding the ALT key and depressing the Underlined letter from the keyboard.

If you look at the pull down menus, you will notice that some commands are dimmed, some have ellipses(...), and others have check marks, arrows or key combinations listed next to them. The following information, will explain conventions of the menus and what they mean.

### *Menu Conventions*

*Dimmed command name* - The command is not available at this time. You might have to select a feature before you can use the command. It might also be that the command cannot be used with your application, or can not be executed in a certain mode.

*An ellipsis (...) after the name* - A dialog box will appear when the command is chosen. This dialog box will give information and/or ask for information to complete a function or command.

*A Check Mark ( ✓ ) next to the name* - The command is active. It also indicates that the command is a toggle and will toggle between one state or the other.

*A key combination after the name* - Use the key combination as a shortcut without opening the menu first. The shortcut could be a combination of keypress or the use of a Function key.

*A triangle at the right side of a menu command* ▶ - The triangle means there is an additional cascading menu that lists other commands or functions.

## *The Menu*

As mentioned before, each item in the menu bar consists of a pull down menu. It also helps identify what will be in the pull down menu. For example, if you were to open the MEASURE menu, a list of all measurement functions allowed will appear in the pull down menu. If you opened the WINDOWS menu you will be able to access each window available in the QC-4000 and so on.

The following information gives a brief explanation of all menus. More information about these commands is explained later in the manual. Since **F**ile is first in the menu item, we will discuss the commands under the **F**ile menu.

### **FILE MENU**

- \* **About** - This allows the user to view such things as system settings, the version of QC-4000 software, and the installed options if any.
- \* **The “About Program” Command** - In the QC-4000 it is possible to view the current program data of a saved program in the Edit mode. Information such as File size, Number of Steps and Total Path Length will be displayed when the **About Program** command is select from the **F**ile menu. This information is very useful when adding or deleting program steps, or Optimizing your path.
- \* **New Session** - When you select this, a prompt appears. If you select YES, the QC-4000 deletes all your features, sets the Datum to machine coordinates, and opens a New Session. If you select NO, you will be backed out of the New Session command.
- \* **Open Session** - A prompt will appear asking "Save Changes to Session? Yes/No/Cancel. If Yes is selected, then your session will automatically be saved and a list of previous sessions will appear. Type in the name of the session you wish to open using **.ses** at the end then click "OK" or *double-click* on the session you wish to open.
- \* **Save Session** - This will save changes to the current session
- \* **Save Session As** - This will name an UNTITLED session or duplicate a previously named session under a new name. Choosing the "Save as" command, will create a new session with changes and modifications but will not automatically save the old session.

- \* **Import From DXF** - This allows the user to transfer a CAD drawing from Auto Cad programs, import them into the QC-4000 and from the CAD drawing, create a part program.
- \* **Export To DXF** - Allows the user to measure a part and export the measurement data to a DXF File, thus creating a CAD drawing from the QC-4000.
- \* **SPC Link** - This is an SPC "Option" used to send data to the Quality America SPC software package. This can also be used to export data to other software packages such as Microsoft® Excel™.
- \* **Print Selected Features** - Select this to print the features you have selected from the Feature List or Part View. If only one feature is selected, *that* feature name will appear on the menu.
- \* **Print Part View** - Selecting this will Print the part view. It will only print what is seen in the part view. It is advised to "Zoom to Fit" if you wish to print the whole part.
- \* **Report Header** - Choose this to setup the header you wish to print before your report.
- \* **Report** - Launches the Report Wizard function.
- \* **Preferences** - Allows you to configure and customize certain functions of your system. Your dealer has step up the options in this function necessary for your system to work correctly. You should get to know your system well before using this function.
- \* **Supervisor Setup** - This allows your dealer to configure your system. These configurations are set at the factory or by your dealer. Once set, these options should not be changed.
- \* **Exit to Windows** - This Exits you from QC-4000 into Windows. A prompt appears, asking the user to SAVE Session - YES/NO or CANCEL.
- \* **Shutdown** - This exits you out of the QC-4000 to DOS.

---

**EDIT MENU**

- \* **Cut Selected Features** - This function is used in programming and transferring information **to** other applications. When selected, information will be **Cut** or **removed** from the part view or feature list before transferring. More information can be found later in the manual.
- \* **Copy Selected Features** - This function is also used in programming and transferring information **to** other applications. When selected, information will be copied from the part view or feature list, leaving the original data in its place. More information can be found later in the manual.
- \* **Paste** - This function is used in programming and/or transferring information **from** other applications. More information can be found later in the manual.
- \* **Select All Features** - Selects all features contained in the feature list and part view.
- \* **Deselect All Features** - Deselects features from the feature list and part view.
- \* **Find Feature** - Prompts you to type in the feature name you wish to find. Press **Find**. That feature will be highlighted in the Feature List and Selected on the Part View.
- \* Find Feature also uses an asterisk (\*) as a wild card to find multiple common features. For example, if you wanted to find and select *all* circle features, you would type C when prompted. This will highlight all the circle features within the part view and feature list.
- \* **Delete Selected Features** - Deletes the features selected. If only one feature is selected, the menu will read "Delete Circle 1" for example.

**MEASURE MENU**

- \* **Measure Magic** - The Measure Magic function allows the operator to simply enter points into the function and as a result of various rules, will automatically create the correct geometric feature. It is enabled by selecting the Magician's Hat on the toolbox. Single clicking the *right* mouse button to enter a point and then again double-clicking the *right* mouse button to end your measurement.
- \* **Point** - Enables the POINT measurement function
- \* **Line** - Enables the LINE measurement function
- \* **Circle** - Enables the CIRCLE measurement function
- \* **Arc** - Enables the ARC measurement function
- \* **Height** - Enables the HEIGHT measurement function. This will only appear if Z axis is present.
- \* **Distance** - Enables the DISTANCE measurement function
- \* **Angle** - Enables the ANGLE measurement function
- \* **Create** - This function allows you to create features by typing the Nominals of Points, Lines, Circles and Arcs. Once a feature is selected, a screen will appear to enter information needed to create the feature.
- \* **Units** - Allows you to choose the unit type you wish to measure in.  
**Includes:**
  - Inch
  - MM
  - Cartesian
  - Polar

**DATUM MENU**

- \* **Probe Frame** - Allows you to perform part alignment by targeting points on 2 intersecting lines, using at least 2 points per line, resulting in a Skew line and a 0,0 reference at the intersection.
- \* **Set Machine Zero** - A prompt will appear, "GOTO" your machine zero point and press OK. This will set a machine zero. This is necessary under certain conditions such as, NLEC, CNC, or using programs with fixtured parts.



- \* **Zero** - Allows you to set a *Zero Datum*. If "Use Machine" is pressed, the current zero will be cleared, and the word "Machine" will appear after Zero. If you choose to zero on a feature, the Datum menu will appear as Zero |(Feature type) and will create a Zero Point feature on the feature list.
- \* **Skew** - Enables you to skew a part. This can be done by probing or constructing. If the "Use machine" button is pressed, then any current skew will be cleared, and the X and Y axis will be set back to the machine axes.
- \* **Level** - Levels the part, enabling accurate height measurements for systems equipped with a Z axis.

### **PROBE MENU**

**Note:** *The PROBE menu is only visible if you have the Optical Edge Option.*

- \* **Crosshair** - Places the QC-4000 in crosshair mode. In this mode, the display is updated continuously. To target a point in crosshair mode, you must place the crosshair on the edge you wish to target and press Enter Pt.
- \* **Edge** - Selecting EDGE will turn on the Edge Detector. In this mode, the display is updated and a "Beep" is generated after every edge crossing. An edge crossing occurs when the light sensor crosses from a light area to a dark area, or from dark to light. This mode facilitates easy targeting of points that lie on shadow boundaries.

**NOTE:** *If "Force Teach" is not defaulted, a Teach must be performed before using the Edge Detector.*

- \* **Auto Confirm** - There are two targeting modes available for Edge Detector, "Auto" mode and "Manual" mode. When Auto Confirm is selected, it will automatically confirm an edge crossing. In other words, the crossing is automatically accepted and entered into a feature measurement without the user pressing Enter Pt each time an edge is crossed.

*If Auto Confirm is off, the QC-4000 will "beep" at an edge crossing, but the user must enter every point manually by pressing Enter Pt.*

- \* **Light Levels** - This is used to check the light intensities of the Screen and Reference fibers of the Edge Detector. The numbers tell how much light is coming from each sensor. The values range from 0 (not enough light) to 12 (too much light.) More information about the light levels can be found in the edge detector section of this manual.
- \* **Teach** - The Edge Detector needs to know what light intensity levels to expect for both light and dark on your system's screen. Choosing the TEACH function will instruct the user to calibrate the Edge Detector. The following prompts appear - "*Move the Edge Sensor into a Dark area on the screen and then press OK.*" After the user follows this instruction and presses "OK", a new prompt will appear. "*Move the Edge Sensor into a light area on the screen and then press OK.*" The Edge Detector now knows the difference between light and dark on your systems screen. This calibration should be repeated every time you turn on the QC-4000 or change your magnification.
- \* **Teach to Master** - This operation fine tunes your Edge Detector to properly read the "fuzzy" non-distinct edges. Please refer to the Edge Detector Section for more information.
- \* **New Calibration** - When you switch back and forth between Crosshairs and Edge Detector or change the magnification of your system, the QC-4000 **must** be calibrated. "New Calibration" allows up to nine individual calibration setups to be created.

Each name can consist of up to 9 characters. After they are created, they will appear in the menu as individual selections. An operator can easily change magnification, and select the corresponding calibration setup without having to go through the calibration procedure again. Please refer to the Calibration section of the manual for more information.

- \* **Edit Calibration** - Once you have your calibrations set, you may want to change the name or delete a certain calibration setup from the menu. These modifications can be done by selecting "Edit Calibration". More information can be found in the Calibration section.
- \* **C1 Default Calibration** - When you first turn on your system, you will notice that the first calibration is already present. C1 stands for Calibration one. In other words, the first calibration setup. Up to nine individual Calibrations can be created. They will be listed as C1 to C9. Please refer to the Calibration section of the manual.

## **WINDOWS MENU**

The windows menu is a way of opening and closing the individual windows within the QC-4000. The QC-4000 contains seven informational windows that can be on the screen simultaneously. All windows are moveable, sizable and closeable. The viewing of these windows can be controlled under the windows menu. The window menu consists of the DRO, Toolbox, Status Bar, Part View, Feature List, Results Window, and Program View. A check mark next to the window in the menu indicates the window is opened.

- \* **DRO** - The DRO window is a window that consists of a live digital readout of the X and Y axis. Next to the X and Y axis display, you see an X and Y button. Placing your mouse pointer over the X or Y buttons and *left* clicking the mouse button will zero the X and/or Y at the location of the position indicator. If your system is configured with a third or fourth axis, the DRO will include a Z and Q axis display.
- \* **Toolbox** - The Toolbox consists of icons that represent the basic measuring functions, as well as other possible functions and commands. Clicking on a Toolbox Icon, will initiate that measurement function.
- \* **Status Bar** - The Status Bar contains the time, date, unit of measure (in/mm) and coordinates (Polar/Cartesian). Other options that appear on the status bar are menu shortcuts.
- \* **Part View** - The Part View Window is not only movable, sizable and closable, it is also scrollable. The Part view on the QC-4000 is the graphical representation of the part being measured. In essence, it is the graphical display of all the displayable objects within the feature list.
- \* **Feature List** - The Feature List is where the measured, created or constructed features will be placed after an application is completed. The Feature list can be used to select features located in the part view.
- \* **Results Window** - The Results Window is where you'll find individual numeric details about a given feature. The Results Window will open automatically when measuring or constructing features. The Results window also contains two pull-down menus. One to activate "Tolerancing", and the other is "change."
- \* **Program View** - Selecting this allows the operator to view and/or Edit steps within a program. Please refer to the programming section.

## ***VIEW MENU***

The Zoom commands are essential to get a close-up look of a particular feature or Zoom out to view the complete Part view at one time. The Zoom in and Zoom out commands change the view at 50% increments

**Note:** *Zooming in or out does not effect the way your part view will print.*

- \* **Zoom In** - When activated, it will incrementally make the features in the part view appear larger.
- \* **Zoom Out** - This allows you to incrementally zoom out (make smaller) all the features within the part view.
- \* **Zoom to Fit** - Returns the part view to its original 1 to 1 view.
- \* **Zoom In On Area** - When this is selected, the mouse pointer will transform into a magnifying glass. While holding down the *left* mouse button, "**Drag**" the mouse around the feature or features you wish to zoom in on. Once the area is completely enclosed within the box, (marquee) release the mouse button. The part view will now zoom in on the area that you selected. (See Part View - Chapter 3)
- \* **Zoom to "Selected Features"** - This is used to make "Selected" features appear larger.
- \* **Center on Position Indicator** - The position indicator is the colored crosshair, Rectangle, or Circle that appears in your part view, to show the current position of your stage. If your indicator disappears from the field of view because of stage movement, selecting the "Center on position indicator" automatically places the position indicator in the center of the part view.
- \* **Record Zoom** - Inserting this command into a program after completing a zoom, will store the zoom into the program. Zooming is *not* a required function for running a program. This command is a visual aid for the operator.

*Auto Zoom Enabled* - If a part is properly aligned when running a program the part view window will be zoomed to fit all the features when the program is run, and no zooming will take place without the Record Zoom function.

*Auto Zoom Disabled* - If "Record Zoom" is used to zoom on a selected feature when auto zoom is disabled, then the user must use another record zoom to restore the part view to its original state.

- \* **Show Hidden Features** - This function will show any feature that has been defaulted or changed to invisible. Show hidden features acts as a toggle. If selected, hidden features will always be visible.
- \* **Show Feature Names** - When selected, "Show Feature Name" places the name of the features shown in the feature list next to all the features in the part view. This is a toggle and when deselected, will remove all the names from the part view.

**Note:** If "Show name" is selected from the "CHANGE" button, then the feature name will appear for that feature, even when "Show hidden features" is deselected.

- \* **Show Position Indicator** - As you may know by now, the position indicator is the colored crosshair, Rectangle, or Circle that appears in your part view. There may be times that you will not want the Position Indicator to show (Print Part View). Deselecting "Show Position Indicator" will temporarily remove the Indicator from the Part View.
- \* **Refresh Part View** - Also known as "Clean Up". Some complex parts that have invisible features can result in the part view looking incorrect. Selecting "Refresh Part View" will *Redraw* all the features in the part view correctly. This also can be accomplished by closing or resizing the window.

### **PROGRAM MENU**

The PROGRAM menu is unlike the other menus, in that different menu selections will appear as the user enters different modes of programming. The following, lists all program menus and the mode the user must be in for the selection to appear. The mode will appear in {brackets} and will indicate if the selection will appear **{Prior}** to recording a program, **{During}** a programming session, **{After}** programming or while **{Editing}** a program.

- \* **Record New **{Prior}**** - Prompts the user to name the program, and initiates the programming sequence.
- \* **Record Into "Program Name" **{Editing}**** - It allows the user to Edit program steps into a previously recorded program.
- \* **Open **{Prior}**** - Allows the operator to open a previously recorded program.
- \* **Save "Program Name"**{After}**** - Allows the user to "Save" changes made to program.


- \* **Save As {After}** - Using the Save As command will allow the user to create more than one version of a program. The user can take a previously recorded program, edit it, and save it under a different name. This will retain the original program, and create a new program under the given name.
- \* **Run {Prior}** - The QC-4000 will automatically execute the program selected by the user.
- \* **Run "Program Name" {After}** - This menu selection appears after the operator has "Opened" a previously recorded program. It will execute that specific program.
- \* **Run "Program Name" at selected step {Editing}** - This allows the user to execute a program from a specified point in the program. This is accomplished by highlighting a specific step on the Program View Window, then selecting "Run program name at select step".
- \* **Auto Program From Features {Prior}** - This is an "Advanced User" command. It allows the user to automatically create a program from the features in the feature list that have been measured or Imported and edited. Please refer to programming section for more information.
- \* **Edit "Program Step" {Editing}** - This will only appear if a Program View Window is opened. Choosing the EDIT command, will open the path steps for examination and/or changes. (This can also be done by Double-Clicking on the Program step). The operator can then delete a step from the program or relocate a step a by choosing those commands from the EDIT Menu.
- \* **Special Steps {During & Editing}** - This menu command contains a cascading menu that consists of the following:
  - Delay** - Pause a program for a specified number of seconds.
  - User Message** - Inserts an alpha-numeric string that will be displayed during program execution.
  - Run DOS/Windows Program** - Allows the user to execute a DOS/Windows program while running a QC-4000 program.
  - DDE** - Enables a DDE Link while executing a QC-4000 program.
  - Light Control** - Allows control of an external light source. Selecting this will introduce another screen that will allow the user to adjust the light.

- \* **Close "Program Name" {After}** - This command allows the user to "Close" the current program without saving changes.
- \* **Regenerate Features {After}** - After Editing a feature into a program, the new feature will appear at the bottom of the feature list. Choosing "Regenerate Features" will relocate that feature to its proper place on the feature list and in the Part View. In other words, it will place the new feature in the Part View and the feature will appear on the feature list in the proper sequence for the program to run.
- \* **Optimize Path** - You've heard of the saying "The shortest distance between two points is a straight line." The Optimize Path function will rearrange selected program steps so that the distance (path) between the points to be measured is minimized.

First, the Part View window must be open and **Show Path** must be selected from the **Program** menu. Optimizing your whole part program may not be necessary. The Show Path command allows the user to view the program path thus making it easier to decide which features to select.

Before performing Optimize Path, select **About Program** from the **File** menu. Note the total path length.


1. Select **Show Path** from the **Program** menu. ("Show Path" will appear only if you have CNC or VED options).
2. Select the features you wish to optimize.
3. Select **Optimize Path** from the **Program** menu. The message "Performing Program Path Optimization" will appear.



*Figure 2 - 6 (Original Path)*

**Note:** The Path (lines), will appear only if you have CNC or VED options.

When the Optimization is complete, the program path will be more direct than before. Once you've optimized the path, go back to About Program and you will notice the total path length is now somewhat smaller. This could save a considerable amount of time when running the program.



*Figure 2 - 7 (Optimized Path)*

- \* ***End Recording.{During}*** - This command concludes the programming session.
- \* ***Pause Program Execution {During}***- This command stops or "Pauses" a program execution, allowing the user to EDIT program steps or enter messages. To continue execution, choose "Run program at selected step" from the PROGRAM menu.


This concludes the Fundamentals of the QC-4000. Please continue reading to learn more exciting facts about your system.







## Chapter Three



### *The QC-4000 Windows*

The Status Bar  
The Digital Readout  
The Toolbox  
Feature List  
Results Window  
The Change Button  
Part View  
Program View



QC-4000



## QC-4000 Windows

The QC-4000 contains seven informational windows that can be on the screen simultaneously. All windows are moveable, sizable and closeable. The following section will introduce you to all the windows and how they work.

### The Status Bar

When visible, the **Status Bar** will always appear at the top of the screen under the Title Bar. The information on the status bar will always include the time, date, unit of measure (in/mm), and coordinates (Polar/Cartesian)

The Unit of measure and Coordinates are toggles. Each time these commands are selected, they will toggle between Inch and Millimeter or Cartesian and Polar.



Other commands that may appear on the Status Bar are associated with QC-4000 Options. Since these buttons are menu shortcuts, please feel free to click and play.

### The Digital Readout




The DRO window is a window that consists of a live digital readout of the X and Y axis. Next to the X and Y axis display, you see an X and Y button. If your system is configured with a third or fourth axis, then the DRO will include Z and Q axes display along with Z and Q buttons.

Placing your mouse pointer over the X or Y buttons and clicking on *left* mouse button, will **zero** the X and/or Y at the location of the position indicator.

In the Crosshair Mode, the display will update continuously, and the crosshairs are the targeting mechanism.

In the Edge Mode, the display will update after every edge crossing.

## The Toolbox



This section, will introduce the icons found in the Toolbox, along with a brief description of their use. The *measurement function* icons work in the same fashion. For example, Clicking on any measurement icon once, will bring up that window and enable that particular measurement. Once "OK" is depressed, the measurement is complete and the window will disappear. Double-Clicking on an icon will allow "Auto Repeat" measurements. After you measure a feature and press "OK," the window will re-initiate on the screen until you press "Cancel". This allows the user to keep measuring the like features without the repetitiveness of selecting the same icon over and over.

Command function such as Zoom or skew are usually performed once; double-clicking on these icons or will not initiate "Auto Repeat."

**NOTE:** *The toolbox is defaulted with some icons already showing. To add or remove any icons, you must do so from the Toolbox Maker in the PREFERENCE menu under FILE. Please refer to Chapter 5 "Customizing the QC-4000."*

## *Toolbox Icons*



### ***Measure Magic***

This magical function automatically creates the correct geometric features simply by entering points. Of course, there are some simple rules and probing techniques to follow, but measuring a part will become so fast and easy you'll probably want to use it most of the time. Double-Clicking on this will enable auto repeat measurement until the cancel button is pressed.



### ***Point***

Enables the Point measurement function. A Point will appear on the Part View as a small crosshair.



### ***Line***

Enables the Line measurement function. A Line will appear on the Part View as a solid line. (Normal)



### ***Circle***

Enables the Circle measurement function. It will appear on the Part View as a Normal feature



### ***Arc***

Enables the Arc measurement function.



### ***Distance***

Enables the Distance Measurement function. Distance will appear on the Part View as a Phantom with an arrow showing the direction of measurement.

***Height***

Enable the measurement of Height. This is only in a 3 axis.

***Angle***

Enables the Angle measurement function. An Angle measurement generates 4 features on the part view and in the feature list; the angle, the vertex point and the two lines that were measured to generate the angle.

***Units***

Pressing the Units Icon will toggle you between Inch and Millimeter.

***Polar/Cartesian***

Use this Icon to toggle between the Polar Mode and the Cartesian Mode.

***Zero***

This icon allows the user to set a new Datum Point (Zero Coordinate System).

***Skew***

Skewing electronically aligns a part to indicate the rotation of the part's axes relative to the measuring machine's axes. After the part is skewed, the Header of the DRO will read "Skewed on Line 2" or whichever line you skewed on, indicating that alignment has been completed.

***Zoom In***

This will incrementally zoom in (enlarge) all the features within the part view.

***Zoom Out***

This will incrementally zoom out (reduce) all the features within the part view.

***Center on Position Indicator***

The position indicator is the red crosshair that appears on your part view. If your indicator goes off the page because of stage movement, selecting the this icon automatically scrolls the part view to the place of the position indicator.

***Zoom to Selected Features***

This is used to make "Selected" features appear larger. The features must be selected on the feature list or from the part view. If no feature is selected this Option will appear "Gray" on the menu and toolbox and will not be selectable.

***Zoom to Fit***

Redraws the features to original size -- 1 to 1.

***Zoom in on Area***

When Zoom In on area is selected, the mouse pointer appears as a magnifying glass with a crosshair (+) in the center. There are 2 methods for using Zoom in.

1. *Dragging* - Hold down the *left* mouse button and drag the magnifying glass around the feature or features in the part view that you wish to enlarge.

2. *Clicking* - Place the magnifying glass over the feature in the part view that you wish to enlarge, then click the *left* mouse button.

***Teach***

Initiates the Edge Detector Teach function. The user will be prompted to move the edge sensor to the dark and light areas on the screen and then press "OK." Once the TEACH function is complete, the Edge Detector will know the difference between light and dark on your systems screen. *The Teach function should be repeated every time you turn on the QC-4000 or change your magnification.*



***Default Calibration***

Using the Default Calibration button (**Defa**) in the toolbox is another menu shortcut. Depressing any calibration button will automatically initiate that calibration setup. Up to nine individual Calibrations can appear in the Toolbox.

***Program Button***

After a program is run, you can configure your toolbox with the program name.

If you have created other programs or calibrations and wish for them to appear in the Toolbox, you can do so from the Toolbox Maker under the *Preferences* menu.

*Note: When naming calibrations and programs you should keep in mind that on the average, only 3½ letters can fit on a button. This average is dependent on which letters are used. Names will be displayed in their entirety on menu, but will be cropped to fit the buttons in the toolbox*


***Print Selected Features***

This is a menu shortcut for printing selected features. Depressing this will send selected feature information out to a printer or computer via the RS-232.

***Report***

Selecting this from the toolbox will initiate Report Wizard.


## *The Feature List*



The Feature List is where a list of measured, created, constructed, or imported features reside. The number in the title bar indicates the number of features contained in the list.

When a feature is placed on the feature list, it will contain a graphical representation of the feature type, the feature name and the sequential number in which it was measured within that session.

### **Example:**

A feature appears in the feature list, as  **Circle 1**

A feature ID consists of the following:

 = A graphical representation of feature type

**Circle** = The Feature type name

**1** = The sequence in which the feature was measured.

The features that appear in the Feature List, can be used to construct new features as well as selecting features in the part view.

***Selecting the features from the Feature List:***

- \* **To Select a single feature from the Feature List:**
  - a) Place the mouse pointer over the feature you wish to select.
  - b) Click the *left* mouse button once. This will highlight the feature selected.
  
- \* **To select a single feature on the Feature List from the menu.**
  - a) Select "Find Feature" from the EDIT menu.
  - b) Type in the feature you wish to select.
  - c) Click on the "Find" button or press Enter on the keyboard.
  
- \* **To select multiple features in consecutive order:**
  - a) Place the mouse pointer over the first feature you wish to select.
  - b) Hold down the *left* mouse button and drag the mouse until the 2 or more features have been highlighted.
  - c) Release the mouse button. Notice that the features in the feature lists remain highlighted and the selected features in the part view now appear in color.

OR

  - a) Click on and highlight the first feature you wish to select.
  - b) Move the mouse pointer to the last feature you want selected. Hold down the **Shift** key and click the *left* mouse button. This will select the features in consecutive order in just two clicks.
  
- \* **To select multiple features not in consecutive order:**
  - a) Click on any feature in the feature list.
  - b) Hold down the **Ctrl** key while clicking on any other feature
  - c) you want selected.
  
- \* **To select all features in the feature list:**
  - a) Drag your pointer down the feature list as explained above.


OR

  - b) Choose "Select All Features" in the EDIT menu.

### *Changing the feature name*

The features on the feature list have default parameters that will be displayed in the Results Window. These parameters can not be changed. For ease of operation, the user is allowed to change the feature name.


- a) Select *Circle 1* from the feature list so that it appears on the Results Window.
- b) Click on the CHANGE button in the Results Window. A menu will appear.



**Figure 3 - 1**

- c) Select "Feature Name" from the menu.
- d) Type in the name you wish to call your feature. For this example, type in **Big Circle**.
- e) Click on "OK" or press **ENTER** on the keyboard.


This will put Big Circle on the feature list in place of Circle 1.



**Figure 3 - 2**

Changing the feature name will **not** change its sequential value. If you were to measure a circle feature after changing Circle 1's name to Big Circle, it would appear on the bottom of the feature list **Circle 9**.

## *Results Window*



The Results Window is where you'll find individual numeric details about a given feature. The Results Window will open automatically by measuring or constructing features or by double clicking the *left* mouse button while in the feature list. The Results window also contains two pull-down menus. One to activate "Tolerancing," and the other is "Change."

### *Form Information*

When you create a 50-point circle for example, all 50 points will probably not lie exactly on the final best-fit circle. So how far were the individual points from the circle? Form information helps to answer this question.

When you create a circle, you'll see two numbers labeled +T and -T in the Results Window. These numbers tell you how close the worst "outside" and "inside" points were to the circumference of the best-fit circle. The +T measurement tells you how far the "Worst outside point" was from the circle's circumference, while -T tells you how far the "worst inside point" was from the circumference.

### *Results Information*

Most features and relations have a fair amount of data associated with them. This data is displayed in the Results Window. The meaning of the +T and -T form Tolerance data was described partially before, but what do the rest of the components mean? Here are explanations of this data for each feature type.

*NOTE: When in Polar Mode, all X, Y coordinates are shown in the form R, A.*

***Point***

X, Y: Point's coordinates

***Line***

Angle the line makes with the Reference Frame's positive X axis.

X, Y: Point on the line which lies closest to the Absolute Datum. This point, however, is shown relative to the current datum.

+T: Straight-line distance from worst point (on side of line *away* from the current datum) to best-fit line.

-T: Straight-line distance from worst point (on side of line *facing* the current datum) to best-fit line.

***Circle***

r, d: Radius and diameter.

X, Y: Center's coordinates.

+T: Distance from worst point *outside* best-fit circle to best-fit circle.

-T: Distance from worst point *inside* best-fit circle to best-fit circle.

***Arc***

r: Radius of the Arc

X, Y: Coordinates of Arc's center

L: Length of the Arc expressed in degrees

+T: Distance from worst point *outside* best-fit circle to best-fit circle.

-T: Distance from worst point *inside* best-fit circle to best-fit circle.

***Distance***

X, Y: Horizontal and vertical distance

L: The actual length. This is a pure number

***Angle***

A: Included angle.

*The result of an angle will always be the included angle. This can be changed however by using the Change button in the Results Window. Refer to "Change Button" in the next section.*


***Tolerance Button***

Choosing the Tolerance button, allows the operator to access the various Tolerances. These include Cartesian, True Position, MMC and LMC. Please refer to "Tolerancing" in the Reference section of this manual.

***Change Button***

The Change button in the Results window is used to "Change" the elements of the Feature List or Part View. This is a great way to modify your Part View or the names in your feature list.

Left clicking on the CHANGE button, will open up the following menu.



***Figure 3 - 3***

As you can see, the CHANGE pull down menu consists of Phantom, and Hidden along with Show Name, Change All and Feature Name. A feature can only be Normal or Phantom and Visible or Hidden. These functions act as toggles and a check mark will be placed next the word in the menu.

Like most things, there are exceptions to the rules. Depending on what type of feature or how many features are selected, you will see different menus under the CHANGE button.

The following is a list of items you will find under the CHANGE button and when they will appear.

***Normal*** - *The feature will appear as a solid feature.* This will appear under the Change All menu item when multiple features are selected.

**Phantom** - *The feature will appear as broken lines.* The QC-4000 is defaulted to show all *Relations* (Distances and Angles) as *Phantoms*. This is because *Relations* are not true geometric entities such as *Circles* or *Lines*, they are positional information between to features. *Phantom* will **always** appear under the *Change* button.

**Visible** - *This will make Invisible or Hidden features reappear in the Part View.* **Visible** will appear under the *Change All* menu.

**Hidden** - *Choosing this function will make de-selected features disappear from the Part View.* The feature will appear on the *Part View* if it is selected, or if you choose *Visible* or *Show hidden features*. This will allow for a less cluttered *Part View* to check features or during program execution. **Hidden** will appear under the *Change All* menu when more than one feature is selected.

**Show Name** - *Enters the name of a selected feature into the Part View.* Selecting "Show feature Names" from the *VIEW* menu, will place all the names of the features into the part view.

**Hide Name** - This function as you might have guessed, will "Hide" a selected feature name from the part view and will appear under the *Change All* menu.

**Note: The View Menu overrides any CHANGE button item.**  
*Example - If "Show Feature Name" or "Show Hidden Features" is selected in the VIEW menu, than de-selecting Show Name or Visible from the CHANGE menu will not "Hide" features or feature names.*

✓ <b>N</b> ormal <b>P</b> hantom
✓ <b>V</b> isible <b>H</b> idden
✓ <b>S</b> how Name <b>H</b> ide Name
<b>C</b> hange Names...

**Figure 3 - 4**




**Change All**

This menu selection, has a cascading menu of its own. Choosing this function Changes ALL selected features.

**Feature Name** - Allows the user to customize the names in the feature list.

**To Change a feature name:**

1. Select a feature from the Feature List or Part View.
2. Left Click on the CHANGE button.
3. Select **Feature Name** from the menu. The following screen appears.



The dialog box is titled "Change Feature Name". It contains two rows of input fields. The first row is labeled "From:" and contains the text "Circle 1". To the right of this row is an "OK" button. The second row is labeled "To" and contains a text input field with "Big Circle" entered. To the right of this row is a "Cancel" button.

**Figure 3 - 5**

4. Using the keyboard, type the new name of the feature.
5. Left Click on OK or press ENTER.


The new feature name will now appear on the feature list.

### *Changing All Feature names*

The QC-4000 allows the operator to sequentially renumber all the features selected in the feature list. This is usually used when editing a program.

When more than one feature is highlighted, and **Change All/Feature Names** is selected, a new screen will appear.


Enter the starting number of your sequence then press **OK**.



The dialog box is titled "Change Feature Names". It contains a label "Starting Number:" followed by an empty rectangular input field. To the right of the input field are two buttons: "OK" and "Cancel".

**Figure 3 - 6**


Your feature list will re-sequence all selected features in the feature list.




## Changing Relations

### Changing an Angle


When measuring an ANGLE feature, the result will always be the **Included** Angle. Under the CHANGE button, the angle feature may be displayed in four different ways.




Included Angle = less than  $180^\circ$



Excluded angle =  $360^\circ$  minus the included angle



Complementary Angles =  $180^\circ$



$180^\circ$  plus the included angle

Figure 3-7 Types of Angles

### ***Changing a Distance***


It is sometimes necessary to have a Distance measurement and a Line measurement in the same coordinates in the Part View. Having a Distance measurement on top of a Line measurement may become confusing to the user. As a convenience function, the QC-4000 allows the user to change Distances to Lines or Lines to Distances to complete an application.

Under the CHANGE button, a Distance Feature may be changed two different ways:

***Distance to Line*** - This allows the operator to "Change" a Distance feature to a Line feature. Because a Distance is not a "True Entity," the QC-4000 will not allow a user to take points or create other features from a Distance Measurement. By "Changing" a Distance to a Line, the user will be

***Reverse Direction*** - A Distance function calculates the distance between two points entered into the function. The result in the Part View will be the Distance measurement including an arrow to show the user what direction the distance was probed.


Choosing Reverse Direction will reverse the direction of the *Distance* between two features. It will also reverse the numbers in the Results window to correspond with the direction change. (Positive to Negative or visa versa.)




### ***Changing Constructed Distances***

When constructing a Distance, the result will always be the center point measurement of the two features used in the construction. The QC-4000 allows the operator to *CHANGE* the distance to the "Nearest" two points, or the "Farthest" two points. Below, is a diagram of what you would see if you were to make these changes between two circles.


**Center** - If a *Distance* is selected, this will give you the Center point distance between two Circles or a Circle and another feature.



**Nearest** - If a *Distance* is selected, this will give you the Nearest distance between two Circles or a Circle and another feature.



**Farthest** - If a *Distance* is selected, this will give you the Farthest distance between two Circles or a Circle and another feature.




### ***Changing Constructed Lines***

As mentioned earlier, it is sometimes necessary to change a Line to a Distance or visa versa. Depending on what type of features were used to construct the line, the QC-4000 will allow some different changes. For example, if you were to construct a Line feature using a previously probed line along with a Circle feature, you would be able to change a perpendicular line to a parallel line.

***Changing Tangents***


When constructing circle tangents to two lines, the result will always be Tangent #1 (See figure 8). The change button allows the user to change the view of the tangent.



*Figure 3 - 7 Types of Tangents*

## ***FEATURE STAMP***



Feature Stamps are also found in the Results Window. The button is the graphic representation of the of the information found within the Results Window. If you depress these buttons in the Results window, you will see the representation of that feature as it appears on the part view. The view includes the name of the feature (line 1), the Targeted Points (if probed), as well as the feature itself.









**Figure 3 - 8**

*Feature Stamp located in the Results Window*

The following is a table of Feature Stamps, what it represents, and what you would see when you depress the Feature Stamp button.

<b>Feature Stamp</b>	<b>Represents</b>	<b>Part View Representation</b>
<p><b>Line</b></p> 	<ol style="list-style-type: none"> <li>The Line</li> <li>The angle the line makes with the positive X axis</li> <li>An endpoint of the line that is the closest to the current origin.</li> </ol>	




Feature Stamp	Represents	Part View Representation
<p data-bbox="428 275 500 300"><b>Point</b></p> 	<p>a. A point</p>	
<p data-bbox="428 554 500 579"><b>Circle</b></p> 	<p>a. The X &amp; Y location of the center point of the circle.</p> <p>b. The Radius of the circle.</p> <p>c. The Diameter of the circle</p>	
<p data-bbox="407 852 526 877"><b>Distance</b></p> 	<p>a. The horizontal and vertical distances between the two points.</p> <p>b. The straight line distance between the two points.</p>	

\* In the Cartesian Mode distances are given in X and Y coordinates as well as straight Line Distances


Feature Stamp	Represents	Part View Representation
---------------	------------	--------------------------

**Angle**



- a. The Included angle between the two lines

Part View representations of Angles will differ for each Angle type.




**Arc**



- a. The X & Y location of the center point.
- b. The Radius of the arc.
- c.. The Arc length in degrees.



## *The Part View*



The Part View Window is not only movable, sizable and closeable, it is also scrollable. The Part view on the QC-4000 is the graphical representation of the part being measured. In essence, it is the graphical display of all the displayable objects within the feature list.

The Part View contains a Crosshair, known as the "*Position Indicator*." Its function is to show you the position of your stage. Each time you measure a feature, you will notice that the position indicator moves to the same position that was targeted.

The Part View can also be used to select, delete or construct new features, just as you would do in the feature list.


## *Selecting the features from the Part View*

### **\* To Select a single feature from the Part View:**

- a) Place the mouse pointer over the feature you wish to select.
- b) Click the *left* mouse button once. This will highlight the feature selected.

### **\* To select multiple features:**

- a) Hold down the *left* mouse button and drag the mouse forming a Marquee around the features you wish to select.



**Figure 3 - 9**

- b) Release the mouse button. Notice that the features in the feature list will be highlighted and the selected features in the part view now appear in color. See Figure 3-10.

**OR**


- a) Left Click on and highlight the first feature you wish to select.
- b) Hold down the **Shift** key and click the *left* mouse button on the next feature. This can be done to select 2 or more features in the part view.

### ***Zooming in on Area***

Using the Zoom function can make visual part inspection a lot easier. The QC-4000 allows you to zoom on a selected feature or on a specific area of the part.


**\* To Zoom in on an Area:**

- a) Select the Zoom on Area Icon from the toolbox or select it from the VIEW menu. When this is selected, the mouse pointer will transform into a magnifying glass with a double crosshair (+) in the center. See figure 3-11.
- b) While holding down the *left* mouse button, "**Drag**" the mouse around the feature or features you wish to zoom in on.



**Figure 3 - 10**

- c) Once the area is completely enclosed within the box, (marquee) release the mouse button. The part view will now zoom in on the area that you selected. See figure below.



**Figure 3 - 11**

### ***Show Name***

Feature names can be placed on the part view to easily identify and keep track of your features. You can apply a name to one or all the features in the part view. This is done by selecting a feature or features from the part view, then choosing the "Show Name" command from the VIEW menu, or from the CHANGE button.


### ***Customizing names***

The QC-4000 allows the users to customize the feature names to appear as C1, Cir 1, or Circle 1. This is accomplished in PREFERENCES under the FILE menu. To learn how to customize your feature list, please refer to "Customizing the QC-4000" section.

### ***Refresh Part View***

Some complex parts that have invisible features can result in the part view looking incorrect. Selecting "Refresh Part View" will *Redraw* all the features in the part view correctly.

You can select Refresh from the VIEW menu, or by closing or resizing the Part View Window. As a convenience, you can also Refresh the Part View by left clicking on the small button in the lower right hand corner of the Part View. This is a quick and easy way to Refresh the Part View whenever necessary without going to the menu. See figure 3-13



**Figure 3 - 12 Feature Names and Refresh Part View**

## The Program View




Figure 3 - 13


The Program View window can be opened by choosing Program View from the Windows menu or by opening a program. This window is used to view or Edit program steps. The Program View Window will appear **blank** unless a previously recorded program is opened or while recording a new program.

In Figure 14, you will notice that some program steps have and *ellipsis* (...) and some do not. The steps that contain an *ellipsis* can be opened so that the user may Edit or view the *Substeps*. The steps without the *ellipsis* do not contain any *Substeps*.

### ***Editing a Program***


To view or Edit a program *Substep*, you simply double - click on the step you wish to Edit, or highlight the step you wish to Edit and select Edit from the Program Menu. (See Figure 3-15)

The user is allowed to cut, paste, delete, delay or add messages to any program step.



**Figure 3 - 14**

Double-clicking on a *substep* will open a screen so that the user may change the probing coordinates. (See Figure 3-16).



**Figure 3 - 15**

**Note:** Caution should be used when changing the coordinates because you could end up at an invalid location and the point will not be found.








---

## Chapter Four



### *QC-4000 Demonstration*

Selecting a Function  
Targeting Points  
Getting Started  
Establishing a Reference Frame  
Taking Measurements  
Constructing a Feature  
Skewing on two Circles  
Creating a Feature  
Creating a Tangent Circle  
Using Measure Magic



QC-4000



## *Previous Reading*

Before reading this section, you should have read Essential Information. Refer to it when you need background information to understand the material covered in this section. It is important that you know basic mouse procedures such as "Clicking" and pulling down Menus.

## *About this Section*

The Demonstration Section will lead you step by step through the most used measurement functions of the QC-4000.

The latter portion of this section will introduce some advanced techniques such as constructing features, selecting a measurement function from the Toolbox and Creating a feature.

### **READ ME**

There are some assumptions made here that you should keep in mind. The CARTESIAN/POLAR function should be in the Cartesian mode. Since the part dimensions are in inches, use INCH/MM to set the unit to Inch mode.

## *Conventions*

Throughout this section, we will ask you perform certain actions, like selecting a measurement function or targeting a point. The following three sections will explain how to accomplish these functions so that it will not have to be explained in the actual demonstration.

## *Selecting a measurement function*

When you see the word "SELECT," we are asking you to choose a menu item or measurement function. This is done by **CLICKING** on the **LEFT** mouse button. For example, you may be asked to "Select" POINT from the measurement menu; You would perform the following:

### *Using the Mouse*

QC-4000	
File Edit <u>M</u> Measure Datum Probe Win	
<b>Measure Magic</b>	
Point	F2
Line	F3
Circle	F4
Auto Circle	
Arc	F5
Distance	F7
Angle	F8
Create	▶
Units	▶

- a. Place the mouse arrow over the word "MEASURE" in the Menu Bar.
- b. Click the **left** mouse button once. This will open up the Pull-down menu.
- c. Move the mouse pointer down to the POINT function.
- d. Click the **left** mouse button once. This will SELECT the POINT Measurement Function, and enable you to measure a point.

### *Using the Keyboard*

All menu functions can be accessed by the keyboard. Open the Menu by using the **ALT** key along with the underlined letter. Then, select the measurement just by selecting the underlined letter. For example:

To open the **M Measure Menu** and select the **P Point** function you would:

- \* Hold the **ALT** key and press the **M** key. (It does not have be upper case.) This will open up the MEASURE pull down menu.
- \* Notice that the P in **Point** is underlined. Now, press the P on the keyboard. This will enable the Point Measurement Function.

## *Targeting Points*

Once you have selected a measurement function, it will be necessary to target a point. "Targeting a point" is the process of telling the QC-4000 that you wish to include a particular point in the current measurement calculation. When you are asked to "Target a Point," this means to place your crosshairs on the edge of the feature you wish the measure.

Because the QC-4000 interfaces with many different systems, we will be using the word "crosshairs" in a generic fashion. For instance, if you have a microscope - you will use the redical crosshairs in your microscope lens. If you have a camera hook-up, you will use the video crosshairs you see on your monitor and so on.

Whichever system you are utilizing, you will be using the crosshairs on your system.

### *Entering a Point*

There are **3** different methods for entering points on the QC-4000, two using the mouse and one with the keyboard.

#### *Using the mouse:*

1. Press the **right** mouse button anywhere on the screen. You may find this the easiest choice.

**Note:** *If using the above method, the "Single Click = Enter" item in the Measure screen under PREFERENCES must be selected.*

2. Place the pointer over the **Enter Pt** button in the measurement window and click the **left** mouse button.

#### *From the keyboard*


1. Press the **"E"** key on your keyboard.

Feel free to choose any method you feel comfortable with.

### ***Complete the measurement***

After you Target and Enter the Point, you then must tell the system you have finished. This can be accomplished *two* different ways. Choose the one you feel is the quickest and easiest for you. Complete the measurement by:

1. Moving the mouse pointer over the **"OK"** button on the open measurement window, and click the **left** mouse button once.




OR

2. Simply **Double Click** the **Right** mouse button anyplace on the screen.

**Note:** If using the above method, the **"Double Click = OK"** item in the Measure screen under PREFERENCES must be selected.

### ***Summary***

- \* **Selecting** a function is done by clicking the **left** mouse button once.
- \* When **Targeting a Point** you must place your crosshairs on the edge of the part or feature you wish to measure.
- \* To **Enter a Point** you can use the mouse or keyboard. Choose the one you feel comfortable with.
- \* To **Complete** a measurement function you can either **left click** on **"OK"** or **Double Click** the **right** mouse button.





---

**Figure 4 - 1 QC-QUICKIE SLIDE**

## *Getting Started*

Included with your QC-4000 is a QC-QUICKIE Slide. All the instructions that follow, refer to that part. Start the lesson by turning on your QC-4000. Place the demonstration slide on your system (See Figure 4-1). Perform each step of this demonstration in the order that it is presented. Feel free to repeat any section until you are comfortable with the concepts and the methods used.

**NOTE:** *The dimensions you obtain may be negative numbers. This is due to axis orientation, and means you will have to reverse your axis direction.*

### *Axis Orientation*

Your QC-4000 must be set up for the proper axis orientation. This means that if you move the crosshairs to the right, the **X** count increases from 1 to 2 to 3 and not from -1 to -2 to -3. The same holds true for the **Y** axis. If you move the crosshairs up the count increases from 1 to 2 to 3.

#### *To Check Count direction:*

- Move the crosshair to the right. The number in the **X** display should increase. If the number does not, the **X** axis needs to be reversed.
- Test the **Y** axis by moving the crosshair up. The number in the **Y** display should increase; if it decreases the **Y** axis needs to be reversed.
- If you find that your axes do not need to be reversed, skip the next section and continue to "Reference Marks".

#### *To Reverse Axis:*

- \* From the **FILE** menu choose **Supervisor Setup**.
- \* Enter the **PASSWORD** when prompted.
- \* Select the **Axes** button.
- \* Select the **Options** button.
- \* Left-Click on "Reverse" inserting an X into the box(s) ()
- \* Click on the OK buttons to exit all screens.

## ***About Reference Marks and Machine Zero***

**Reference marks** -- are marks on a linear encoder that can be sensed by a digital readout for the purpose of establishing a known starting location within the measurement envelope. This location is needed to continue measurements of the same part started the previous day, non-linear error correction, or to use the software fence (in CNC systems).

If your machine is equipped with reference marks, you must enable the reference marks in your QC-4000. This will locate the machine zero more repeatably than moving your stage to the fixed location.

\*\*\*\*\*

**Machine Zero** -- is a fixed location on your stage used by the calibration grids, software fence and may also be used in a program. This location is established at startup and can be reset anytime (Except during program recording) by Machine Zero in the datum menu.

Establishing a Machine Zero must be performed for NLEC and software fence to operate properly. If one of these options is installed you will be prompted to locate your machine zero at startup. **Note:** If you are using reference marks to establish your machine zero the reference mark calibration must be performed first.

\*\*\*\*\*

If reference marks are enabled, (in the Axes Setup) you will be prompted to cross them on start up. If reference marks are **not** enabled on an axis, but you have specified that you want to establish machine zero on that axis, then you will be prompted to move to that position fixed location on the stage) at startup. When you press OK, the machine zero for that axis will be established at that position.

**IMPORTANT:** REFERENCE MARKS SHOULD ALWAYS BE CROSSED WHILE GOING IN THE SAME DIRECTION EACH TIME OR YOU MAY OFFSET THE MEASURING ENVELOPE BY THE WIDTH OF THE MARK. This means that you should position the stage before you shut down so that you will cross the reference marks in the correct direction when you restart.

If you do not have the Reference Mark indicators, you may skip this section.

***Enabling Reference Marks:***

1. From the **FILE** menu enter the **Supervisor Setup**.
2. Select the **Axes** button.
3. Select the **Options** button.
4. Left-Click on **Ref Marks** inserting an X into the box ()
5. Click on **OK**.

**Encoder Options**

Resolution					
X Axis	0.001000	<input type="checkbox"/> mm	<input type="checkbox"/> Reverse	<input type="checkbox"/> 5x	<input checked="" type="checkbox"/> Ref Mark
Y Axis	0.001000	<input type="checkbox"/> mm	<input type="checkbox"/> Reverse	<input type="checkbox"/> 5x	<input checked="" type="checkbox"/> Ref Mark

Figure 4 - 2

***Reference Mark Calibration:***

1. Select the Machine Zero button in the Supervisor menu and select the axes you wish to set when using Machine Zero. (X, Y, Z).
2. Move the stage near the reference marks. (SINCE THE USE OF REFERENCE MARKS IS DIRECTION SENSITIVE, YOU MUST CROSS THE MARK IN THE SAME DIRECTION YOU WILL USE ON START Up.)
3. Select **"New Session"** from the File menu.
4. Select **Set Machine Zero** from the Datum menu.

Perform the following instructions:

- ◆ "Cross the X axis reference mark."
- ◆ "Cross the Y axis reference mark." (This will set the Machine Zero at the reference marks.)

*Note: If your system is equipped with a Z axis you would be prompted to "Goto your machine zero point for the Z axis and press "OK".*

You have now completed your Reference Mark Calibration and have established the Machine Zero. **Remember:** Position the stage before you shut down so that you can cross the reference marks in the correct direction when you restart.

## *Establishing a Reference Frame*

A powerful feature of the QC-4000 is the ability to skew and establish a datum. Your first step should always be to align the part, which is done by establishing a Reference Frame.


A Reference Frame has two components:

1. Skew - Two axes, that describe the rotation of the measurement plane.
2. Datum - An Absolute Zero, that is usually tied to a dimensioned point on the part.

The QC-4000 provides you with a procedure for establishing a Reference Frame. While establishing the Reference Frame, you will have to probe or construct two lines. This process is described briefly in the following paragraphs.

### *To Establish a Reference Frame:*

- a) Select **Probe Frame** from the **Datum menu**. The Frame measurement window will appear.
- b) Target between 2 and 50 points along the skew line (X axis). (See figure 3.)
- c) When you have entered enough points, press "**OK**."



**Figure 4 - 3 (Establishing A Reference Frame.)**

- d) Now target between 2 and 50 points along the Y axis spreading the points out along the **left** side of the part.
- e) Press **OK**.


The QC-4000 now knows all it needs to about the placement of the part. Even if the part is not perfectly parallel with the axes of your stage, the QC-4000 will automatically compensate for it.

**NOTE:** During a *FRAME* command, if **Cancel** is used during the measurement of the 2nd line, the original alignment and features will be lost.

If your part is misaligned with respect to the travel of your machine, you will notice that more than one DRO display will change, as you move along one axis only. This is because the QC-4000 knows you are moving diagonally with respect to the part.

Once a Reference Frame has been established, you are in Part Coordinates. The part must be placed within 45° of the correct orientation, or the orientation of the axes may change.

### *Feature List*



After Framing the Part, you will notice that the feature list contains 3 features.

**Line 1** - This is the first line you probed, also known as the *Current Skew*. This indicates the rotation of the part's axes relative to the measuring machine's axes.

**Line 2** - This line, when intersected with the previously probed line, yields the *Absolute Datum* or part zero.

**Point 3** - This point is automatically created by the QC-4000 to show the intersection point between Line 1 and Line 2, also known as your Absolute Datum or Part Zero.

## *Point Measurement*

Points are the easiest features to measure because they require very little interaction between the user and the QC-4000. Follow these steps to measure several points on the part.

Selecting a measurement tool can be done in various ways. For demonstration purposes we will be selecting the measurement tools from the Measure Window. (Refer to Selecting a Function).

- a) Select the **POINT** function (**F2**) from the Measurement Window.
- b) When the Point Measurement Window appears, Target any point on the part and click on "**Enter Pt.**" Notice that the "**Pts Entered = 0**" (in the measurement window) now changes to **1**.
- c) Now click "**OK.**" This finishes the Point measurement and closes the Point Measurement Window.
- d) Repeat steps a. thru c. and target 2 more points.





Figure 4 - 4 (Point Measurement)



### **Feature List**

Notice that the list contains all the points that have been measured. The number in the **right** hand corner implies that there are (6) features in the Feature List. (Three from the FRAME measurement and three from the 3 points just taken.)



### **Part View**

The Part View Window now includes the 3 features from your Frame command along with three '+'s. These are the Points that you have targeted and entered.

### **Results Window**


The result of a point function is a single two dimension point that represents the points entered into that function. .

## *Average Point*

The average point, or "Multi-point point" is a way to obtain more accuracy in point measurements by targeting the point two times and then averaging the positions entered when generating the POINT feature.

Average points may also be constructed by selecting two features from the feature list or part view. For more information, refer to Constructions.

- a) Select the **POINT** function (**F2**) from the Measurement Window. The Point Measurement Window appears.



- b) Target two points on the part or select the features from the feature list and click on OK.

This finishes the Average Point measurement and closes the Point Measurement Window.

## *Line Measurement*

The QC-4000 can also measure lines. Taking between 2 and 50 points, the QC-4000 will calculate the line that best fits those points as well as providing Form Tolerance.

Let's measure the line formed by the part's measurement plane and the right face. Proceed as follows:

- a) Select LINE (**F3**) from the Measure Window. The Line measurement box appears.
- b) Target Points along the line clicking on "Enter Pt" after each target.

**Note:** *You must target at least 2 points to define a line and you may target up to 50 if you wish.*

- c) Click on "OK" to signal the end of the line measurement.




Figure 4 - 5 (Line Measurement)

### Feature List

The new line feature is placed at the bottom of the Feature List, and the information about the line is displayed in the Results Window.

### Part View

In the part view you will now see the line that you just measured (in color). Notice that the features that have been measured previously are still there, but they are now shown in black.

### Results Window




Figure 4 - 6

The result of a line function is a two dimension line that is the best fit line calculated from the points entered into the function. The information from the results window is as follows:

1. The amount of points entered for the line measurement.
2. The  $\angle$  entry is the angle the line makes with the positive X axis
3. The endpoint on the line that is the closest to the current origin. Also know as the: (X, Y point on the line that lies closest to the Reference Frame's Absolute Datum).
4. The +T and -T bound and unbound

When you measure this feature, you will see +T and -T in the Feature Expansion Window. These numbers tell how close the worst "outside" and "inside" points were to the best-fit construction. The +T measurement tells you where the "worst outside point" was; -T tells where the "worst inside point" was located.

The +T and -T meaning for this feature is as follows:

+T: Straight-line distance from worst point (on side of line *away* from the current datum) to best-fit line.

-T: Straight-line distance from worst point (on side of line *facing* the current datum) to best-fit line.

## *Circle Measurement*

The QC-4000 enables you to make very precise calculations about any circle or arc of circle. Given anywhere from 3 to 50 points, the QC-4000 can calculate the circle's center and radius, as well as Form Tolerance.

For most 3-dimensional parts, circles are actually the intersection of a cylinder and the measurement plane. For this example use the large circle in the demonstration part and follow these steps:

- a. Select the CIRCLE function (**F4**) from the Measure Menu.
- b. Target between 3 and 50 points along the circle, clicking on "Enter Pt" after each target.
- c. When you have entered enough points, click on "OK."




Figure 4 - 7(Circle Measurement)

### ***Feature List***

After you click "OK," the QC-4000 will place the resulting circle feature at the bottom of the Feature List. Notice the number in the right hand corner, has changed, matching the amount of features stored on the feature list.

### ***Part View***

In the part view you will now see the CIRCLE that you just measured (in color). You also might have noticed that your part has been "redrawn" to fit the Window. This is because the QC-4000 has a great feature known as "AUTO ZOOM." After each feature is added to the part view, dynamic scaling will take place and the part view will be redrawn if it is necessary to fit new features within the view. More details about "Auto zoom" can be found later in the manual.

### ***Results Window***

The circle function calculates the least squares best fit circle from the points entered into the function. The output is as follows:

1. The number of points taken for the circle measurement.
2. The X & Y location of the center point of the circle.
3. The Radius of the circle.
4. The Diameter of the circle.
5. The +T and -T meaning is as follows:
  - +T. Distance from worst point *outside* best-fit circle to best-fit circle.
  - T. Distance from worst point *inside* best-fit circle to best-fit circle.



## *Distance Measurement*

Another function performed by the QC-4000 is distance measurement. The QC-4000 can calculate the X and Y distance between two points.

In this example of the part demonstration we will measure the height of the part (the dimension of the part along the Y axis) using the following steps.

- a) Select **Distance (F7)** from Measurement Menu.
- b) Target any point on the edge near point 1 of Figure 4-8. clicking on "Enter Pt" after you have targeted your point.
- c) Target any other point on the edge near point 2 of Figure 4-8, again clicking on "Enter Pt" after you have made your selection.
- d) Click OK to indicate the completion of the distance measurement.




Figure 4 - 8 (Distance Measurement)

### **Feature List**

The new distance relation is placed on the bottom of the Feature List.

### **Part View**

The Distance Representation that you just measured now appears in the Part View Window, as Dashed Lines. Since distances are *relations* between existing features and not true entities, they appear on the Part View as *Phantoms*. They also include arrows, that show the direction in which to measurement took place. You can *Change* the direction of the arrows by clicking on the "Change" button in the Results Window. (Refer to the Change button section.)

### **Results Window**

The horizontal and vertical distances between the two points in the Cartesian mode, distances are given in X and Y coordinates as well as straight line distance readings in the Results Window.

1. The X & Y location of the Distance measurement relative to the zero datum.
2. The length of the distance measurement.

In this example, the Y distance representing the part, is what we're interested in. The X distance is meaningless, since it depends upon which two points we used for the measurement. The Y distance should be the same regardless of where the two points fall on the top and bottom edge.

The order of entry of the two points is most important. If the Y distance display is 1.8 inches, it would have been -1.8 inches if the points had been entered in reverse order.

## *Arc Measurement*

The QC-4000 enables you to make very precise calculations about any circle or arc of circle. Given anywhere from 3 to 50 points, the QC-4000 can calculate the Arc's center and radius, as well as Form Tolerance. To measure an arc:

- a. Select the ARC function (**F5**) from the Measure Menu.
- b. To determine an ARC you must target between 3 and 50 points along the arc, clicking on "Enter Pt" after each target.
- c. When you have entered enough points, click on "OK."


### **Feature List**

After you click "OK," the QC-4000 will place the resulting arc feature at the bottom of the Feature List. Notice the number in the right hand corner, has changed, matching the amount of features stored on the feature list.

### **Part View**

In the part view you will now see the ARC that you just measured (in color).

### **Results Window**



The ARC function calculates the least squares best fit arc from the points entered. The output is as follows:

1. The number of points taken for the arc measurement.
2. The Radius of the arc..
3. The X & Y location of the center point
4. The Degrees of arc length.
5. The arc orientation which is from the center of the arc to the center point of the arc segment express in degrees from the positive X axis.
6. The +T and -T would be calculated for a circle.
  - +T : Distance from worst point *outside* best-fit circle to best-fit arc.
  - T : Distance from worst point *inside* best-fit circle to best-fit arc.

## *Angle Measurement*

Your QC-4000 can also measure angles. The angle function calculates the angle and vertex point between two lines that are probed within the function.

For this exercise use the side and bottom of the demonstration part as shown in Figure 4-9 and follow these steps:

*Note: Angles are usually generated as relations between existing features (usually two lines).*

- a. Select ANGLE from the Measure Menu. A prompt appears instructing the user to probe the 1st leg of the angle.
- b. Target between 2 and 50 points on leg 1 on the part for the part's angle face (see Figure 4-9).




Figure 4 - 9 (Angle - Leg 1)

- c. Press OK when you have entered enough points.

Another prompt appears instructing the user to probe the 2nd leg.




Figure 4 - 10 (Angle - Leg 2)

- d. Target between 2 and 50 points on leg 2 on the right face of the part (see Figure 4-10).
- e. Press OK when you have entered enough points.


---

The Angle listed in the Results Window is the Included angle. If you press the change button in the Results window, you will be able to change the results to show other angles. These angles include the Complementary Angle, the Excluded Angle, and  $180^\circ$  plus the Included Angle. All other angles have a geometric relationship to the first angle. (See figure 4-11.)




**Results Window**


1. The number of points taken for the angle measurement.
2. The Included angle between the two lines.
3. The X & Y coordinates of the vertex of the angle. This is shown as a point measurement located on the feature list below the angle just measured. If selected, it will appear in the results window as a point.




Included Angle = less than  $180^\circ$



Excluded angle =  $360^\circ$  minus the included angle



Complementary Angles =  $180^\circ$




$180^\circ$  plus the included angle

Figure 4-11 (Finished Angle)




**Feature List**

After you press OK the second time, the QC-4000 will perform a few calculations and place the resulting angle relation on the bottom of the Feature List. Notice that a Point is also added to the bottom of the feature list as well. This Point is the X and Y coordinates of the vertex of the angle just measured.

**Part View**

In the part view you will now see the Angle that you just measured.



You have now concluded the BASIC portion of the Demonstration Section. You may want to go back and repeat any steps that you might have found confusing.

## ***ADVANCED DEMONSTRATION***

Now that you have become a PRO at measuring features, this portion of the manual will take you one step further. This section will walk you through the following:

- \* Construct a feature from existing features.
- \* Skewing on two circles.
- \* Creating a feature.
- \* Creating a Tangent Circle
- \* Using Measure Magic.

### ***Constructing a Feature***

Constructing a feature is merely the process of combining existing features to generate a new feature.

As an example, let's construct the distance between two circles found on the Quickie Slide. If your feature list does not already contain two circles, follow the instructions earlier in the demonstration section for probing circles.



1. Select the Distance Tool from the toolbox or Measure menu.
2. Move the mouse pointer over a circle in the part view.
3. **Left** click on the mouse button. *That feature will change color in the part view and will be highlighted in the feature list.*
4. While holding down the SHIFT KEY on the keyboard, move the mouse cursor over second circle and **Left** click on the mouse button.
5. Click on OK in the measure window.

Your Distance will now appear on the Part View as a dotted line and will appear at the bottom of the feature list.

## ***Angle Construction***

As mentioned in the Angle Measurement section, angles are usually generated as relations between existing features, instead of probing them from scratch. Now we'll see how to construct the angle between two line features. First we must place two line features in the Feature List.



1. Select the LINE from the tool box.
2. The LINE Measurement window now appears.
3. Probe points along the first line.
4. Select "OK" when you are done probing the line.
5. Repeat steps 1 – 4 for the second line.



6. Select the ANGLE Key from the toolbox.
7. Select the two lines from the part view by **left** clicking on them.
8. Select "OK."

A new angle relation appears on the Feature List and on the Results Window. This is the angle between the two separately measured line features.

In all measurements, there is a simple rule to remember. There are two basic ways to generate features -- Probe or Construct.

To **Probe** a feature, you must first target and Enter the points of the feature you wish to generate.

To **Construct** a feature, you must first select the type of *feature* you wish to generate (i.e., Line from 2 points or Angle from 2 lines) then select the previously generated features from the feature list or part view.

**Note:** *If you are using Auto Construct, you must first select the features, then select the feature type. (Refer to Preference Menu section.)*

## *Skewing On Two Circles*

In the beginning of the Demonstration Section, you were shown how to "Establish a Reference Frame." Framing your part, eliminates the need for time consuming, costly, manual alignment or fixturing.

There are times that the part you are measuring will consist only of radii, but still must be skewed to insure correct measurement. If you didn't perform a Skew Alignment before measuring, and instead tried to "eyeball," your chances of finding the correct measurements are slim.

The procedure for skewing on two circles is quite simple, and will insure proper measurements.

- a. Select the CIRCLE function from the Measure Menu or toolbox.
- b. Target between 3 and 50 points along the circle, clicking on "Enter Pt" after each target.
- c. When you have entered enough points, click on "OK."
- d. Repeat steps a, b and c for the second circle.



- e. Choose the SKEW function from the toolbox or DATUM menu.
- f. Select the 2 circles from the part view or feature list.
- g. Press OK on the measurement window.

The Skew function is now completed. The feature list will now contain **Line # (Current Zero & Skew)**. The DATUM menu will contain that skew line number next to the words Skew and Zero.

## Creating features

Sometimes you need to be able to reference a feature without actually probing it. One such instance is when you have an off-the-part Absolute Datum--you could generate this datum by *creating* it manually.

The QC-4000 allows the user the create Points, lines, angles, and circle features.

QC-4		
Measure	Datum	Prob
Measure Magic...		F1
<u>P</u> oint...		F2
<u>L</u> ine...		F3
<u>C</u> ircle...		F4
<u>A</u> rc...		F5
<u>D</u> istance...		F7
<u>A</u> ngle...		F8
<b>Create</b>		
<u>U</u> nits		

Point...

Line [2 pts]...

Line (pt, angle, & length)...

Circle...


Arc (start & end angles)...

Arc (start & end pts)...

Figure 4 - 11 (Create Menu)

### ***Create a Point***

When creating a Point, enter the X, Y, Z (if applicable) coordinates of the Point, then press OK or ENTER.




The image shows a dialog box titled "Create Point". It features a "Position" section with three input fields for X, Y, and Z coordinates. To the right of the input fields are two buttons: "OK" and "Cancel".

Figure 4 - 12 (Create a Point)

### ***Create a Line using 2 points***

When creating a Line with 2 points, just enter the X, Y and Z coordinates of both the start and end points of the line.



The image shows a dialog box titled "Create Line". It features two sections: "Start Point" and "End Point", each with three input fields for X, Y, and Z coordinates. To the right of these sections are two buttons: "OK" and "Cancel".


Figure 4 - 13 (Create a Line)



### ***Create a Line***

When creating a line for point, angle & length results, you need to supply a point (X, Y, & Z) through which the line passes, as well as the angle and length that the line makes with the positive X axis.

When this feature is placed on the Feature List, don't worry if the X, Y coordinates change. The point that the QC-4000 stores is the point on the line closest to the Absolute Datum, which may not be the same as the point you entered. It's just a different point on the same line.




**Figure 4 - 14**

*Note: You cannot partially probe and then partially construct a feature or relation. You must completely probe or completely construct a feature or relation.*

### ***To create a Circle***

- Select Circle from the Create pull down menu.



**Figure 4 - 15**

- b. Enter the X, Y and Z (if applicable) coordinates of the circle's center and the radius and/or diameter. Then press **OK** or **ENTER**.

The new feature is placed on the Feature List and Part View, and, since this feature was neither probed nor constructed, the Form Tolerance information for the feature is +T=0 and -T=0.


### *Create an Arc*

Like lines, the Arc can also be created two ways. (Start and end **angles**) or (Start and end **points**).

**Create Arc (Cartesian)**

<p><b>Center Position</b></p> <p>X <input style="width: 50px;" type="text" value="0"/></p> <p>Y <input style="width: 50px;" type="text" value="0"/></p>	<p><b>Size</b></p> <p>r <input style="width: 50px;" type="text" value=".500"/></p>	<input type="button" value="OK"/>  <input type="button" value="Cancel"/>
<p><b>Start Angle</b></p> <p>A <input style="width: 50px;" type="text" value="270"/></p>	<p><b>End Angle</b></p> <p>A <input style="width: 50px;" type="text" value="35"/></p>	

Figure 4 - 16



When creating an Arc using the Start and End angles, you must also supply the X/Y coordinates of the center of the radius, along with the size of the radius.

In this example, we used a 0,0 Center Position, a starting angle of 270° and an ending angle of 35°.

When creating an Arc using the Start and End points, the Arc's final position is somewhat dependent upon its' Center position coordinates.

We say "somewhat dependent" because the center position coordinates do not have to be exact, they are used to give the Arc an approximate placement factor.

To better explain this, let's created two arcs with the same start and end points but different center point coordinates.

First, we'll create two lines without the Arc.

- From the **Measure** menu.
- Select **Create** then **Line (pt, angle, & Length)**.
- Create line 1 use following coordinates:
 

<b>X=0</b>	<b>A=0</b>
<b>Y=1.125</b>	<b>L=1</b>
- Create the line 2 using these coordinates:
 


<b>X=1.125</b>	<b>A=90</b>
<b>Y= 0</b>	<b>L=1</b>

\*\*\*\*\*

Now that we have the lines, let's create an Arc to connect the lines.

- From the **Measure** menu.
- Select **Create** then **Arc (start & end pts)**.

<b><u>A</u>pprox <u>C</u>enter Position</b>	<b><u>S</u>ize</b>
X=1	r =.125
Y=1	
<b><u>S</u>tart Point</b>	<b><u>E</u>nd Point</b>
X=1.125	X=1
Y=1	Y=1.125



In this case, a Center position of 0,0 or 1,1 will place the arc at the same location.

**Figure 4 - 17**  
**(Center Position 1,1)**




Figure 4 - 18 (Center Position 1.125, 1.125)

Notice the placement of the Arc. In this case, using 2 instead of 1.125 would have produced the same result.

### Creating a Tangent Circle

**Tangent** - A line or plane which meets a curve or curved surface at a single point without intersecting it.

Of course this is only one definition of Tangent. And like the definition, tangent Circles can be used for many different applications. Creating a tangent circle is as simple as choosing the Circle Measurement and selecting the two lines that you wish to insert the circle.




Figure 4 - 19

If you already have an angle on your part view, you may use that. If you do not have angle, please probe or create one now. (See figure 4-20.)

- Choose **Circle** from the toolbox or the Measure Menu.
- Select the two lines from the part view or feature list.
- Choose **OK** and enter the radius and/or diameter of the circle.




Figure 4 - 20

Tangent Circle		
r	<input type="text" value=".125"/>	<input type="button" value="OK"/>
d	<input type="text"/>	<input type="button" value="Cancel"/>



## *Using Measure Magic*

This function automatically creates the correct geometric features simply by entering points. Of course, there are some simple rules and probing techniques to follow, but measuring a part will become so fast and easy you'll probably want to use it most of the time.

The following gives a brief description of how to use Measure Magic along with some of the rules. Select Measure Magic by clicking on the Magicians hat icon or double-click to initiate auto repeat mode.

### *Measure Magic Probing Techniques*

As mentioned above, there are some rules and probing techniques that you must follow for Measure Magic to work accurately. Following these simple probing techniques, will allow the Measure Magic function to work at its fullest potential.

#### ***POINT MEASUREMENT***

Enter one point and press OK.

#### ***DISTANCE MEASUREMENT***

Probe two points, then press OK

#### ***LINE MEASUREMENT***

Probe three or more points then press OK. If the line is very irregular the QC-4000 may calculate the line to be an ARC. Don't worry that can be changed once we exit measure magic.

***ARC MEASUREMENT***

Probe at least three points on the arc then press OK. The ARC must be at least 5 degrees but no more than 190 degrees.

***CIRCLE MEASUREMENT***

Probe at least three point on the circle then press OK. There must be at least 190 degrees of arc from the first to the last probed point. Although 3 points is sufficient to measure a circle, a good procedure would be to probe at least 4 points equally spaced around the circle. This will insure accurate circle measurement.

***ANGLE MEASUREMENT***


Probe and Equal number of points (at least 3) on each leg of the angle then press OK.

***"Use Relations" must be turned on for ANGLE measurement. This can be found in the measure area of the PREFERENCE menu.***

***Continue Reading***

The next section of the manual is the Programming section. It will take you through the program capabilities of the QC-4000. These are only basic programs to get you started. Once you learn the full potential of the QC-4000, you will be able to see your productivity soar.

## Chapter Five



### *The Preference Screen*

The Preference Menu

Sound

Measure

Angle

Part View

The Toolbox Maker

Results

Locks



QC-4000







## *Customizing The QC-4000*

Customizing the individual windows within the QC-4000 screen to meet your needs, is another great feature you will find in the QC-4000. As mentioned earlier, the windows can be sized, moved, or closed, but that is just the tip of the iceberg. There is a command under the FILE menu that allows you to customize other items such as Sound, Part View and even your Toolbox.

### *The Preference Menu*

Although closing and sizing is a form of customizing your windows, there is another method of customizing that is unique to the QC-4000 only. This is accomplished by PREFERENCES under the FILE menu.

The following section will walk you through the Preference menu and the different selections you are able to select to customize your QC-4000.

#### *Preferences*

Open the FILE menu, by clicking on it, or press **ALT F** on the keyboard. Select PREFERENCES from the menu. The Preferences menu will appear.




Figure 5 - 1

- ***Sound***

Clicking on "Sound" or pressing the "S" on the keyboard will bring up a screen with a selection of all the different sounds the QC-4000 makes. Your system is defaulted with all sounds turned on. These options are toggles which means, they will turn off (blank box) when selected once, then on if selected again.




Figure 5 - 2

***To turn sound on or off:***

Move the mouse pointer over the appropriate box. *Left click* the mouse button. (The X in each box implies - sound is on)

Selecting the small speaker symbol on the left side of the screen will give a sample of that particular sound. After completing your selection, click on "OK".

- *Measure*

The Measure screen allows you to set up User Preferences. There are 8 different sections within the Measure prompt.

Measure Preferences			
<b>Annotation</b> <input type="radio"/> Forward <input checked="" type="radio"/> Backward		<b>Right Mouse Button</b> <input checked="" type="checkbox"/> Single Click = "Enter" <input type="checkbox"/> Double Click = "OK"	
<b>Safety Net</b> <input type="checkbox"/> Auto Save		<b>Measure Magic</b> <input type="checkbox"/> Allow Relations	
<b>Default Feature Types</b>			
Probed Features	<input type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
Relations	<input checked="" type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
Constructed Features	<input checked="" type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
Created Features	<input checked="" type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
<b>Outlier Detection</b> <input type="checkbox"/> Point Filtration		<b>Preselection</b> <input type="checkbox"/> Auto Construct	
<b>Heights</b> <input type="checkbox"/> Allow Negative Results			

Figure 5 - 3

### 1. *Annotation (Forward and Backward)*

*Forward Annotation* is the process of designating a specific number of points for the targeting of a feature. When Forward Annotation is used for a Circle measurement for instance, **Pts Needed = 3** appears in the measurement function window. The number of points can be changed by clicking on the up or down arrow. When that number of points is reached, the system will automatically advance to the next step. This means it will not be necessary for you to click on "OK".

*Backward Annotation* is the process where the program does not indicate a predetermined number of points to target a feature. When the user has "Entered" enough points, the user would then click "OK" or Double-click the Right mouse button.

## 2. *Right Mouse Button*

*Single or Double Clicking* the Right Mouse button is another method for entering points ("Enter") or completing an application ("OK"). There are times however, that you may want to turn this off so that a point will not be entered by mistake. The X in the box indicates that this option is turned on. Clicking on the box(s) will turn the Right Mouse Button off.

## 3. *Safety Net*

When you are working with the QC-4000 or any other application window, you should "Save" often. *Auto Save* in the QC-4000 will automatically "Save" after any major function has been performed. (Example; adding a new feature to the feature list). If the session is "**Untitled**", it will send a "Save As" prompt asking the user to name the session. This feature will "Save" the user from repeatedly having to select "Save" from the menu or keyboard.

## 4. *Preselection*

*Auto Construct* is a quick and easy way to construct features. To construct a feature with Auto Construct on:

- a. Select 2 features in the feature list.
- b. Select the type of feature you wish to construct.

A few more steps must be added to construct a feature without Auto Construct.

- a. Select the type of feature you wish to create.
- b. Select 2 features from the Feature List, pressing "Enter" after each selection.
- c. Press "OK" in the measurement window or "O" from the keyboard.

## 5. Measure Magic

As you know, the Measure Magic function allows the operator to simply enter points into the function and as a result of various probing rules, will automatically create the correct geometric feature.

Because features are automatically generated, the QC-4000 may confuse a 6 point ANGLE with an ARC measurement. Enabling **Allow Relations**, will force the QC-4000 to measure an ANGLE without confusing it with an ARC measurement.

If *Allow Relations* is disabled, the user may make all other measurements in Measure Magic, then complete all ANGLE measurements by choosing ANGLE from the toolbox or menu.

## 6. Feature default type

Features in the Part View can be customized to appear as Normal (solid) or Phantom (dashed). Since Relations are not true entities, they are defaulted as Phantoms on the Part View. Constructed and Created features are also defaulted as Phantoms so that the User can tell the difference between these features and Probed features.

If you would like to have the names of the features appear next to the features on the Part View, you can set this default by selecting *Show Name*.

Default Feature Types			
<b>Probed Features</b>	<input type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
<b>Relations</b>	<input checked="" type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
<b>Constructed Features</b>	<input checked="" type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name
<b>Created Features</b>	<input checked="" type="checkbox"/> Phantom	<input type="checkbox"/> Hidden	<input type="checkbox"/> Show Name

To change the default settings for each feature type, move the mouse pointer over the preferred default and click on the *left* mouse button. An X in the box, implies that the feature will appear as Phantom, Hidden or will have the feature name appear in the part view. When you are finished making your selections, click the "OK" button. If you wish to *change back* to the original settings, click the "Set Default" button.

## 7. *Outlier Detection*

- The intent of this function is to remove any “Incorrect” points that may have accumulated during a measurement function. Point filtration operates only during program execution (not while recording or when doing non-programmed measurements) A minimum of 8 points must be present for the filter to be used.

**To use Point Filtration:** - Deselect “Lock Point Filtration” under *Locks* in the **Supervisor menu**. Enable the *Point Filtration Function* by clicking on the box in the **Outlier Detection** under the *Measure Button* in the **Preferences menu**. For more information on point filtration, please refer to chapter 7.

### *Point filtering tuning parameters:*

Point filtering works by the following method:

- a) First the least square best fit feature is calculated.
- b) The error of each point is determined (distance of point to best fit).
- c) The worst point is determined.
- d) If all criteria are met, the point is eliminated.
- e) The method is then repeated (goto step a).

In step d, in order for a point to be filtered there are five criteria that must be met simultaneously. One criteria is that point filtering is active in the system (set in measure preferences). Additionally, there are two fixed criteria and two modifiable criteria which may be adjusted in QC4000.INI.

#### **The fixed criteria are:**

1. A **minimum of 8** original points must be present in a feature measurement before filtering is allowed.
2. **No more than 25%** of original points will be filtered out of a measurement.


**The modifiable criteria are:**

1. **Sigma Factor:** Default value = 2.00 This parameter is specified in standard deviation units, or "sigma." When a best fit is calculated, the point errors are evaluated statistically and the standard deviation is determined. Because the sign of error is included, the mean error is nearly zero. In order for the current "worst" point to be eliminated from a measurement, the absolute value of the error of the point must exceed 2.00 times the standard deviation (using the default value of the parameter for example). This parameter ensures that only true statistical outliers are eliminated.
2. **Filtration Threshold:** Default value = 10.000. This tuning parameter is specified in encoder counts or parts of counts. In order for the current "worst" point to be filtered, the error of that point must exceed 10.000 times the X axis encoder resolution. For example, if the encoder resolution was 0.002 mm, the error of the worst point would have to be greater than 0.02 mm. This parameter ensures that the error of a true statistical Outlier which is being considered for filtering is not less than the estimated system repeatability. The system repeatability is not based on the encoder resolution alone, so the Filtration Threshold may need to be modified accordingly.

**8. Heights**

- Heights are normally always positive. Enabling "Allow Negative Results" will allow for negative height measurements

- *Angle*



The Angle display lets you choose between DMS ( Degrees Minutes Seconds ) and DD ( Decimal Degrees ). What's the difference? Suppose you had an angle that was exactly  $10^{\circ} 30'$  (or, in other words,  $10.5^{\circ}$ ). If you select DMS, the angle will be displayed as  $10^{\circ}30' 00''$ . A selection of DD would display  $10.5000^{\circ}$ .

- *Part View*

As you can see, the Part View Preferences has several options in which the user can select from. This will allow the operator to customize the Part View in a way to best fit his/her needs. The following paragraphs will provide a brief description of each selection.




Figure 5 - 4











### 1. Orientation

This allows the user to change the orientation of the part as it appears on the part view.

**Note:** Your system may not show Orientation the same way as the following chart. This chart is only an example of how Orientation Selection works.

#### For Example:


Let's assume that you originally set the orientation for X and Y in the positive direction.

ORIENTATION SELECTION	WHAT THE PART VIEW WOULD LOOK LIKE
<p><b>Normal View =</b> Positive X Positive Y</p> 	
<p><b>Reverse Y =</b> Positive X Negative Y</p> 	
<p><b>Reverse X =</b> Negative X Positive Y</p> 	
<p><b>Reverse X and Y =</b> Negative X Negative Y</p> 	

## 2. Position Indicator

The purpose of a position indicator is to show the current position from Zero. In the QC-4000 however, it also is a representation of what you would see on your monitor or comparator screen. Choosing one of the 3 different type indicators is done by *left clicking* on it.

- **Crosshair Indicator**  
This indicator is a basic Position indicator. The crosshair will move around the part view each time a point is entered, showing the current position.
- **Rectangle Indicator**  
As mentioned above, the Position Indicators are also are presentation of what you would see on your monitor or screen. If you are using a monitor, this Indicator (shaped like a rectangle), would most likely be the one you would choose. The view that you see on your monitor is the same on the part view.
- **Circle Indicator**  
If you are using a comparator, this Indicator (shaped like a circle), would most likely be the one you would choose. The view that you see on your comparator screen is the same as the part view.
- **Show Edge Detector**  
When the Show Edge Detector feature is enabled, you will see two (2) position indicators on your part view. A small green circle will appear along side the crosshair, indicating the edge sensor. When performing a Teach, Teach to Master or Probe Offset, this is the indicator that you will use to calibrate your edge.



**Figure 5 - 5**

All three position indicators can be sized to the Field of View. Please refer to the Calibration section of the manual.

**NOTE:** *If the Position Indicator you have selected, does not appear in the part view, check "Show Position Indicator" under the VIEW menu and/or change Field of View size.*

### 3. Zoom

The Zoom selection box is where you would select or deselect the **Auto Zoom** function. An **X** in the box, indicates that Auto Zoom is initiated.

What is Auto Zoom you ask? Simply, Auto Zoom means the same as "Zoom to Fit". Each time a feature is added, the Part View will automatically redraw if need be, to fit all the features onto the part view.

Because Auto zoom *redraws* the part view frequently, it tends to slow your system down. If you are measuring a large part with a lot of features, it is recommended that you turn Auto Zoom off, and use "Zoom to Fit" under the VIEW menu when you need to view all the features in the part view.

If Auto Zoom is off, and you are measuring a large part, some features may not be visible on the part view; in essence they will "Fall off the page". Zoom to Fit will redraw all the features to their perspective place on the part view.

### 4. Grid

For those of you who prefer working on a grid, the QC-4000 allows you to set your own grid spacing for inches or millimeters.

### 5. Feature Name Display

As mention earlier, the part view can also have the name of the feature appear next to the feature. *Feature Name Display* is where you choose how you would like the name to appear.

If you choose:	It appears on the part view as:
Long	Circle 1
Med	Cir 1
Short	C1

*If you customized a feature name such as "Big Circle" it will always appear as Big Circle, no matter what the default is.*

- ***The Toolbox Maker***

The Toolbox Maker is used to add or remove tools that appear in the toolbox. The following procedure describes how to accomplish this:

- a. Choose PREFERENCE from the FILE menu. A menu will appear.
- b. Place the mouse pointer over "Toolbox Maker" and click the *left* mouse button.

A new screen appears showing all available icons, and the Icons that currently appear in your toolbox.




Figure 5 - 6

***To add a Tool***

- a. Select an Icon in the available list.
- b. Left click on COPY. This will place the icon in your toolbox.
- c. Press OK or ENTER on your keyboard.

***To delete a Tool***


- a. Select an Icon in the Current Items list.
- b. Left click on REMOVE. This will remove the icon from your toolbox.
- c. Press OK or ENTER on your keyboard.

## • RESULTS

This window is one that is limited in how small it can be sized. For your convenience, there are two different size formats to select from.


### *To change formats*

1. Select the RESULTS button under Preferences. A new screen appears.




2. Deselect the Wide Format by *left clicking* on the Wide Format box.

**Note:** After deselecting the Wide format box, you must Size the Results Window.



**Wide Format**  
4 X 1.5 Inches



**Narrow Format**  
1.5 X 4 Inches.


## • **LOCKS**

Choosing this button allows the user to lock all windows residing within a QC-4000 session. Once LOCK is initiated, the user cannot move or size any of the individual windows.

### ***To Lock the window positions:***

Using the mouse - Left click on the lock window box then click on OK.

Using the keyboard - Depress the W on the keyboard then ENTER.



**Note:** Even though window positions are locked, you are able to size the QC-4000 window as a whole.

## • **LANGUAGE**

The language window allows the user to select from English, French or German. This will make all QC-4000 menus and screens to appear in that language.



**Figure 5 - 7**

**Note:** This will only change the QC-4000. If you do not have the DOS version for the selected language, you will not be able to enter any text for the selected language into the QC-4000.


---

## *Chapter Six*



## *Measure Magic*

**Measure Magic  
Before you Begin  
Using Measure Magic  
Using the Change Button**



## ***Measure Magic***



Measure Magic is a unique and revolutionary inspection technique that will dramatically reduce the time required to inspect your parts.

With any other geometric computational system that you may have been familiar with, you must first select a geometric function such as a line, circle etc., then probe points on that feature. The results are then calculated and displayed for that feature.

This is a perfectly acceptable technique and is a convention that is currently utilized by the QC-4000. The one drawback of this method of inspection is that you must continually reach for the readout, select a measurement function and then probe.

For an inspector using a measuring microscope, this involves constantly looking away from the eyepieces of the microscope, looking at the readout controls and back to the eyepieces.

Measure Magic allows you to simply probe any geometric feature and Measure Magic will automatically determine the type of geometric feature you have probed.

When coupled with a foot switch, your hands and eyes never have to leave your inspection machine. By following a few simple rules, Measure Magic will think with you, and allow you to push the work, not the buttons

At last, a readout with real intelligence!




## ***Before you Begin***

Before you begin using Measure Magic, the user must decide whether they wish to include *RELATIONS* in the session. To include relations when using Measure Magic, you **must** turn on **Allow Relations** from the *MEASURE* dialog box in PREFERENCES under the FILE menu. (An X in the box indicates "Allow Relations" is on.)

If Allow Relations is off, Measure Magic will not generate any Distances or Angles. When it is on, a 2 point line will be generated as a Distance, and Angles will now be generated if probing technique is correct.

## ***Using Measure Magic***

Measure Magic operates in two different modes. By selecting the Measure Magic icon from the toolbox (or from the measure menu or the F1 button), you will see a prompt window with instructions on using Measure Magic along with OK, Enter Pt, Remove Last (Point) and Cancel buttons.







- In this **singular mode**, you will be able to probe points on one feature, and Measure Magic will calculate information on that one feature. Measure Magic is now deactivated and you can now select any other measurement function.

- By **Double-Clicking** on the Measure Magic icon, you are now in the **Auto Repeat Mode**. You are now able to probe an unlimited number of features until you chose to deactivate Measure Magic. With Measure Magic in the *Auto Repeat Mode*, just probe features then press the OK button or foot switch and see your productivity soar. Measure Magic lets you push the work, not the buttons.



To initiate Measure Magic for multiple feature measurement, move the cursor over the Magicians hat icon, and double click the left mouse button. This will turn the Measure Magic icon green, indicating that you are in the auto repeat mode, thus allowing for multiple feature inspection.

Now probe points on any geometric feature pressing the OK button in the Measure Magic prompt window (or double clicking the right mouse button, or press foot switch) at the completion of probing points on each feature and by following these simple rules:



MEASUREMENT FUNCTION	RESULT
<b>POINT</b> - to measure a point enter <b>ONE</b> point and press OK.	
<b>DISTANCE</b> - to measure a distance (slot width etc.) Probe <b>TWO</b> points, then press OK.	
<b>LINE</b> - to measure a line, probe <b>THREE or more</b> points on the line, then press OK. If the line is very irregular the QC-4000 may calculate the line to be an arc. Don't worry, we can change and recalculate once we exit measure magic.	
<b>ARC</b> - to measure an arc, take <b>at least THREE</b> points on the arc, then press OK. <b>The ARC must be at least 15 degrees but no more than 190 degrees.</b>	

**MEASUREMENT FUNCTION**

**CIRCLE** - to measure circle, probe at least **THREE** points on the circle then press OK. There must be **at least 190 degrees of arc** from the first to the last probed point.

Although 3 points is sufficient to measure a circle, is good practice to probe at least 4 points equally spaced around the circle. This will insure accurate circle measurement

**ANGLE** - to measure an angle, take a minimum of **THREE** points and an **equal number of points on each leg of the angle** then press OK.

**RESULT**

*Note: Angles and Distances will only be generated if "Allow Relations" is initiated and probing techniques are correct.*

**Using the Change Button**

The differentiation between lines, arcs, and circles is where the possibility of an erroneous feature calculation. With Measure Magic this is not a problem. For example, if you have probed three points on a very irregular line, there is the possibility that Measure Magic could interpret the line as an arc. It is very easy to "CHANGE" the Arc into a Line.

- Once you have ended the Measure Magic session, select the feature in question of the part view or feature list.
- The results will now display information about the ARC.
- Click on the "Change button" in the results window and select LINE from the menu.

This will change the feature from an ARC to a Line. The line information will be display in the results window and the part view will be updated accordingly.



---

## *Chapter Seven*

Program View: DEMO (Editing)	
00001	System Settings...
00002	Probe Skew "Line 1"...
00003	Probe Line "Line 2"...
00004	Construct Zero "Point 3"...
00005	Probe Arc "Arc 4"...
00006	Probe Line "Line 7"...
00007	Probe Line "Line 8"...
00008	Construct Angle "Angle 5",

### *User Programming*

**Creating A Program**

**Points to Remember**

**Start A New Session**

**Skew the Part**

**Establishing a ZERO Datum**

**Recording a Program**

**Editing User Programs**

**Systems Settings**

**Running a Program**

**Close The Program**

**Importing AutoCad DXF Files Into The QC-4000**

**Export Of The Partview In DXF Format**

**Creating A Part Program From A Cad File**

**Run the Program**

**Using Record Zoom In A Program**

**Deleting Programs and Sessions**




QC-4000











**Figure 7 - 1**

### ***About User Programs***

The QC-4000 offers extensive programming capabilities. Using different command functions, your system will perform "electronic instruction" that will automatically create programs and measure the features of the parts you commonly deal with. These instructions, called "User Programs" or just "programs," automate the sequence of key presses needed to examine a part, leaving you free to concentrate on targeting points and interpreting the results. To make it even easier, the Part View will show you the area in which you must target the point.

You can also lock programs to prohibit access to any QC-4000 functions other than "Run a Program" and "Shutdown". To Lock programs select **Fixed run Program Mode** under the LOCKS in the Supervisor Setup.

Part programs are created using two different methods. These methods are **Self Teach**, and **Auto Program**; generation from a DXF (CAD) file.

To help you learn to use the programming system, we'll walk through the creation, modification, and execution of a User Program designed to find the distance between two circles located on the Quickie Slide using the **Self Teach Method**. After you become familiar with a basic program and how it works, continue on to learn about Importing from DXF, and using DDE (Dynamic Data Exchange) while creating programs.

Creating a program to measure a feature is almost as easy as measuring the feature itself. The following are the four basic steps for creating a program.

1. Tell the QC-4000 to start recording a program.
2. Name the program.
3. Perform the measurements.
4. Tell the QC-4000 to stop recording the program.

## *Creating A Program -- Self Teach*

### *Points to Remember*

Recording a program is as easy as measuring the part. However, there are several points to remember when recording a program to make the program *run* smoothly each time it is initiated.

1. When recording a program you should use "New Session" in the File menu before you start to record so that there is no part reference frame or features in the system.
2. Prior to recording a program, you must establish a part reference frame. Establishing a reference frame will align the part and insure proper placement of features each time you run the program.
3. Before running a program, you must establish the same part reference that was in effect when you recorded that program. *Programs will always run in the same part reference frame that was present before you started to record.*
4. When running a program, the Machine Zero point must be the same point as when you recorded the program. For simplicity, whenever you are going to record or run a program, use the "Set Machine Zero" function in the datum menu before you start to record or run a program. Always set the machine zero point to a repeatable point on the stage (not the part).
5. Skewing and zeroing are programmable steps. This means that the reference frame may be modified during the course of recording (or running) a program. If you follow rules 1 thru 4 (above), and if you have a fixture that holds the part in the same position every time, then the program will know the part location on the stage and will run correctly.
6. If your program is not running correctly, it is easier to re-record it, than to try to change it by editing (unless your program is very large). Recording a program is quite easy because you simply measure the part as you normally would. You don't have to think about the fact you are recording. Remember to turn off the recorder by "End Recording" in the program menu.

7. You may use Measure Magic when you record a program but you must remember the Measure Magic probing rules. (Please refer to the Measure Magic section of the manual). It will not be possible to modify the type of feature when recording, so use Measure Magic carefully.
8. When recording a probed angle into a program, it's recorded as two lines followed by an angle construction. The sequence will not be exactly as recorded, but the program will still run properly and generate the angle and apex point. We recommend that relations (angles and distances) be constructed rather than probed.
9. Auto Program from features is an advanced function of the QC-4000. You can use it to create a program from previously measured features or to program parts read in from a CAD "DXF" file. There are several extra requirements for using the auto program generator, so do not attempt to use it unless you have a thorough knowledge of the CAD system you are using. (Please refer to "Creating a Program from a CAD file" section of the manual.)

Following these simple rules will make programming a breeze. It will also allow the operator to adapt different parts into a like program by copying and editing a previously written program.

Before we begin programming, we will need something to measure. Place the QC Quickie Demo part that came with your QC-4000, on your measuring machine. You can check any measurements by referring to the Quickie drawing in the beginning of the Chapter.

### ***Start A New Session***


Before recording a program, it is a good practice to start a New Session, which will eliminate all the existing features from the Part View and feature list.

- From the **F**ile menu choose **N**ew **S**ession. A dialog box will appear to confirm your selection.
- **L**eft click on **Y**ES, or press **E**NTER on the keyboard. This will clear your feature list and part view. You are now ready to record a program.

### **SKEW the Part**

The first step of our program will be skewing the part. This procedure will align the part to establish a reference.

- Select SKEW under the DATUM menu. A dialog box appears, prompting you to probe or construct a Line.
- Probe 4 points on line 1 of the Quickie slide. You can probe between 2 and 100 points on the line, however for this program, probe four points that are well spread out on line one then press "OK."



Skewing the Part (Figure 7 - 2)

The Skew function is now complete. The feature list will automatically title Line 1 as Current Zero and Skew, and the DRO header will show which line the user has Skewed on.

### **Establishing a ZERO Datum**

- Select the Line function from the toolbox. Again you are prompted to probe a Line.
- Probe 4 points on line 2 then press "OK."
- Select Zero from the DATUM menu.
- Select Line 1 and Line 2 from the feature list or part view. (Features will turn blue when selected.) Once you have selected the two features, press "OK."




Figure 7 - 3

Once OK has been pressed, the QC-4000 will automatically create an intersection point (Point 3) from the 2 lines and will appear on the feature list as Current Zero. All features measured from now on will be relative to this point.

Feature List (3)	
—	Line 1 (Current Skew)
—	Line 2
•	Point 3 (Current Zero)

Figure 7 - 4


At this time you may want to delete these features by highlighting all the features in the feature list and selecting **Delete Selected Features** from the **Edit** menu. *The deletion is not necessary, but it will avoid any confusion when recording the reference frame inside the program.*

### 1. Start Recording a Program

- From the **Program** menu select **Record New**. A dialog box will appear to prompt the user to name the program.

### 2. Name the Program

- Using the keyboard, enter a program name of up to 8 characters, then press the "OK" button. For this exercise, please name the program DEMO.

You are now recording a part program.  This "Recording" Icon will appear on the Status Bar and any measurements, constructions, or print operations that you make, will be retained in this part program. If you make a mistake or want to make some changes, don't worry, editing a program is fast and easy.

### ***Establish a Reference***

Now establish a Skew and Zero reference just as you did prior to recording the DEMO program.

### ***3. Perform the measurements***

As mentioned earlier, we will measure two circles and construct the distance between them.



#### ***Circle Measurement***

- To measure a circle, select the CIRCLE icon from the toolbox.
- Probe 4 points on one of the circles located on the Quickie, (Circle 4) then press "OK." (See figure 5)
- 




Figure 7 - 5

- Probe a second circle in the same fashion. (Circle 5)



### ***Construct a Distance***

*Constructing* a feature simply means combining existing features to generate a new feature. Refer to Chapter 4 for more information.

- To construct a distance between 2 circles, select the Distance icon from the toolbox.
- Select the 2 circles from the feature list or part view, then press OK. The result will be the center to center distance between Circle 4 and 5. (Distance 6). (See figure 5)

### ***4. End Recording***

- From the **Program** menu select **End Program**. You have now created a basic program.

If you don't already have the Program View showing, select **Program View** from the **Windows** menu.

Program View: DEMO (Editing)	
00001	System Settings
00002	Probe Skew "Line 1"...
00003	Probe Line "Line 2"...
00004	Construct Zero "Point 3"...
00005	Probe Circle "Circle 4"...
00006	Probe Circle "Circle 5"...
00007	Construct Distance "Dist

Figure 7 - 6

This is what your program should look like. Step 00001 is System Settings which will be explained later in this section. Steps 00002 through 00004 is where we established a reference frame and lines 00005 thru 00007 are the actual measurements and constructions that were performed while recording this program.



## *Special Steps*

It is possible to insert "Special Program Steps" into a program. Located under the **Program** menu, this menu item contains a flyout menu with separate commands that can be inserted into a program while recording or edited into a previously created program.




Figure 7 - 7

**Delay** - Pause a program for a specified number of seconds.



**User Message** - Inserts an alpha-numeric string that will be displayed during program execution.

**Run DOS/Windows Program** - Allows the user to execute a DOS/Windows program while running a QC-4000 program.

**Export to ASCII File** - Allows the user to export specific information such as, Time and Date, Position of Selected feature, and text to an ASCII file.

**DDE** - Dynamic Data Exchange is a message protocol for data exchange between Windows programs. It performs actions equivalent to choosing the commands from the windows program. These commands are called *command-equivalent functions*. For example, giving the command **PARTVIEW.OPEN** is the same as opening the Partview from the QC-4000 Windows menu. For more information about DDE, please refer to the Reference Section.

## ***Running a Program***

With the program already open, left clicking on the  button in the status Bar will turn the button into this  and will begin running the program. Or highlight the first step of the program then, select **Run "DEMO"** from the **Program** menu.

If you do not have a program open select **Run** from the **Program** menu. A screen will appear prompting you to select the program you wish to run. After pressing OK, the program will automatically begin to run.

The part view will fill with all the features that are to be inspected. Notice that the features are gray. They will turn black as they are inspected. There will be a flashing green cursor on the first feature to be inspected.

Probe a point in the general vicinity on that first feature where the flashing green cursor indicates. After probing the first point, the cursor will move to the next probing point. After 4 points are probed, the cursor will then go to the next feature. Just follow the flashing cursor and let the QC-4000 guide you through inspection of the DEMO part.

## ***Close The Program***

To store the DEMO program, **left** click on the **Program** menu and select **Close "DEMO"**. If you changed the program, but didn't save it, a "Save As" prompt will appear.



## ***Editing User Programs***

The Program View Window is used to view or Edit program steps. This window will appear **blank** unless a previously recorded program is opened or while recording a new program. There are two types of editing: Line editing and "Record Into".

### ***Line Editing***

Line Editing is changing the parameter of a line, inserting special steps or using the Cut and Paste functions to re-sequence your program. In Figure 7-8, you will notice that the program steps have an *ellipsis* (...). This means that the step can be expanded to view or edit the *Substeps*. Steps without the ellipsis do not contain any *Substeps*.

To view or Edit a program *Substep*, you simply double-click on the step you wish to Edit, or highlight the step you wish to Edit and select **E**dit from the **P**rogram Menu.




Figure 7 - 8

Double-clicking on a *substep* or selecting **E**dit from the **P**rogram menu will open a screen so that the user may change the probing coordinates. Pressing the **H**ere button will "Zero" the X/Y coordinates. (See Figure 7-9)




Figure 7 - 9

**Record Into (Insert a Step)**

This type of editing will allow you to record new steps such as a user message or another feature into your program. For this demonstration, we will add the message Cir,Cir,Dist into the program to let the operator know that they will be constructing the distance between two circles.

1. Highlight Line 00004 in the program view.
2. Select "**Record Into**" from the **Program** menu.
3. From the **Program** menu select **Special Steps**, then **User Message**. The following screen will appear.





Figure 7 - 10

4. Using the keyboard, type the message you wish to display. Initiating the Pause function will display the message and prompt the operator press OK before the program will continue. Selecting the Print and Print Date/Time will of course print the message and/or the date and time via the RS232 port.
5. Press OK.

6. Now from the **Program** menu, choose **End Recording**. Notice in Figure 7-11 that a new line was added.



Program View: DEMO (Editing)	
00001	System Settings
00002	Probe Skew "Line 1"...
00003	Probe Line "Line 2"...
00004	Construct Zero "Point 3"...
00005	User Message...
00006	Probe Circle "Circle 4"...
00007	Probe Circle "Circle 5"...
00008	Construct Distance "Dist 6"...

Figure 7 - 11


#### **Delete A Step**

You can delete a step in a program easily by opening the desired program and program view. Select a line in the program you wish to delete, by moving the mouse pointer over the line and left click the mouse button.

Select "Delete Step XXX" from the EDIT menu.

**Note:** It is advisable to regenerate features after editing a program. You could end up at an invalid location and the point will not be found. **Regenerate Features** will re-sequences your Feature list to reflect the changes. This function is located in the Program menu.

## *System Settings*



System Settings will always appear as the first line in a program and cannot be cut, copied or deleted. You can view the System Setting screen by double-clicking on it, or Selecting **E**dit from the **P**rogram menu. Items such as *Times to Execute* and *Use As Recorded* are selectable from this screen only. (See Figure 7-12)




Figure 7 - 12

### ***Use Machine Skew***

If no other Skew has been established, "Use Machine Skew" will be selected automatically.

### ***Use Machine Zero***

If no other Zero has been established, "Use Machine Zero" will be automatically selected.

***Clear Features***

Having this selected will clear the feature list before the program begins to run.

***Use As Recorded***

If "Use As Recorded" is on, the program will run using the same edge type, light levels or other calibrations you may have performed when recording this program.

***Ignore Errors***

This will allow a program to run complete without pausing and displaying an error message.

***Palletize function***

This allows the user to measure several fixtured (same) parts with one program. The fixture holds the parts at a known distance from each other in a row or column or both.

**To use this function** - first skew and zero on the first part. Record a program which has a skew and zero as the first two steps. After making all the measurements, stop recording. It is good practice to run the program at least once to make sure all measurements are correct before setting up the Palletize function. After checking the program, double-click on "System Settings" (the first program step in the program view window). The System Settings screen will appear. Enter the number of rows and columns in the fixture and the X and Y distance between the parts. (Columns = X axis and Rows = Y axis.) Save and close the Program. Start "New Session." (This is not a necessity but it's good practice clear any unwanted datum's.)

Skew and zero on the first part. Now run the program. The program will loop and reset the datum by the offset specified. The program will measure in a Serpentine scan path. That is, it will measure all the columns of a row, and then move up and do the next row.

***Manual Execution Mode***

Manual Execution Mode pertains to CNC option only. If your system is equipped with the CNC option, please refer to the CNC manual.

**Lock**

This locks the program -- A locked program cannot be edited in any way and only opened by entering the supervisor password. The "Lock" will initiate after closing the program. You can run a locked program by choosing **Run** from the **Program** menu.

**Times to Execute**

This of course, is the number of times you wish your program to execute. Using the keyboard, enter a number from 1 to 100.


**Point Filtration**

This enables the Point filtration function. **Caution: Point Filtration can remove valid data.**

***What is Point Filtration?***

The intent of this function is to allow Video Edge Detection programs to measure similar parts more repeatably by automatically removing *Outlier* points from measurements. For example: Some applications require very high magnification. This sometimes will pick up dust particles as points. Point Filtration will remove these undesired points or "False" edges.

Here's the catch -- The removal of these undesired points may also cause valid data to be lost. Caution should always be taken when using the Point Filtration function. (See Figure 7-13)

**Exaggerated View**

With point filtration enabled outlying "valid" points are removed by the filter

Figure 7-13

"How does the filtering work" you ask? The system calculates a threshold based on two times the standard deviation of error and at least 10 times



---

the encoder resolution. It then removes points beyond 2 sigma from the mean and recalculates until no more points lie outside the threshold, or 25% of the points have been deleted. These points are removed from the database and may not be recalled.

### ***Using Point Filtration***

When the QC-4000 is shipped from the factory, access to the Point filtration feature is locked and can only be unlocked in the Supervisor setup under LOCKS.




Figure 7 - 13

After Point Filtration access is unlocked, the point filtration function can be enabled in the "System Settings" screen (Double-click on line 1 of the program view). Enable Point Filtration by left clicking on the Point Filtration box, then press OK.

The point filtration function operates only during program execution (not while recording or when doing non-programmed measurements.) A minimum of 8 points must be present for the filter to be used in a measurement. UP to 25% of the points may be removed by the filter.

Once these points are removed from the database, they cannot be recalled.

In a measurement with normal distribution of errors (no outliers), about one of every twenty points will be removed by the point filter function. The Result window indicates if any point have been removed by filtration. For more information on point filtration please refer to chapter 5.

## ***IMPORTING AUTOCAD DXF FILES INTO THE QC-4000***

1. The QC-4000 has the ability to read AutoCad DXF files although some limitations apply. The information below should be read and understood before importing any files.
2. The Tables section of the DXF file also is currently ignored.
3. Some programs that generate DXF format files may send arc features as a polyline of many segments. This can quickly fill the feature list with many short lines. In this case, the user should make room in the feature list by constructing an equivalent arc within the QC-4000 and delete the group of lines that make up the Polylines.
4. From the imported drawing, strip all points, lines, circles, arcs and unwanted Polylines. Specifically, remove the border, title block, dimension lines and arrows. These items will otherwise, be displayed in the partview and listed in the feature list.
5. The Import function ignores the DXF File Header. Therefore, the drawing must be drawn in the units that are to be imported and without any scale factors. To import a drawing in inches, place the QC-4000 in inch mode and import the DXF file. To import the drawing in MM, place the QC-4000 in MM mode and proceed with the import.
6. **Auto Program from Features** -- This is an advanced feature of the QC-4000 and is used to program parts read in from a CAD "DXF" file. In some ways, it will be easier to "Setup" the part program in the CAD system before you import the CAD file into the QC-4000.
  - a. Be sure that the features of the drawing are in a 1:1 scale with the actual part. Also be sure to place the origin of the drawing of the part at the same datum point you will be using during the measurement.
  - b. Put the features you want to measure on a separate "layer" of the drawing, and export only those features to the DXF file.
  - c. If there are arcs and circles in the drawing, make sure that they have not been drawn with Polylines. The program generator will measure all Polylines as lines, not circles.

### ***EXPORT OF THE PART VIEW IN DXF FORMAT***

The partview and feature list can be exported in the DXF format for editing by a drawing editor. The resulting file will not contain the Tables, Blocks, or Header section. The export file also will not include polylines; they convert to lines and arcs during the import of the file.

Select the features from the Part View or Feature list, then from the **File** menu choose **Export to DXF**.

Now that you have read the import and export information, please continue to the next portion of the manual (Creating a Part Program). Please feel free to refer back to this page whenever necessary. (This information will not be mentioned in the proceeding pages.)

### ***CREATING A PART PROGRAM FROM A CAD FILE***

By now you have become familiar with the operation and programming a system of the QC-4000. One of the key features of the QC-4000 is the PART VIEW that acts as visual road map for repetitive part inspection. Up to this point you had to create a part program by doing a first piece inspection. There is a very powerful alternative to this method.

The QC-4000 has the capability of creating a part program from a DXF file. A DXF file is a common format utilized by many CAD programs such as AUTO CAD by AUTO DESK. This will dramatically reduce the amount of time to create a part program. Here's how:

1. We have included a sample DXF file with your QC-4000 to help demonstrate. The Quickie Slide is the sample DXF file.
2. Select NEW SESSION and then OK from the FILE menu.
3. Pull down the FILE menu and select IMPORT FROM DXF. A dialog box will appear prompting the user to choose a file.
4. Double click on **quicky.dxf**
5. The part view will now fill up with a drawing of the quickie slide.
6. The quickie slide was drawn with the intersection of line A and B as the ZERO point. This is fine for our demonstration, however, the zero point can be moved anywhere on the part by constructing features on the part view as we have done previously.

7. Now hold down the SHIFT key on the keyboard, move the mouse pointer over the features you wish to select and **left** click on all the features in the part view that you want to measure. As the features become selected they will change color. For our demonstration select circles C, D, line E, and arc F. (See Figure 7-15)




Figure 7 - 14

8. Now pull down the PROGRAM menu and select AUTO GENERATE FROM FEATURES.
9. A dialog box appears and asks for the number of points on a line, circle and arc. When the QC-4000 auto generates a part program from the DXF it will evenly space the selected number of points for each geometric feature. For example, enter 3 points for a circle. Now when we run this program we will be prompted to take 3 evenly spaced points on every circle.




Figure 7 - 15

10. A dialog box now appears prompting you to name the program. Enter CADDEMO then OK.
11. The program view will now appear. We have just created a part program.




Figure 7 - 16

### ***Run the Program***

To run the program, first save and close program CADDEMO, then select new session. Now place the Quickie Slide on the stage and skew on line A. Measure line B and construct a zero point at the intersection.

Now pull down the PROGRAM menu and select RUN and CADDEMO. The part view will fill with the features that we selected from the CAD drawing and prompt us to measure the specified number of points on each feature.

By using the program editing system we can add Tolerancing, print commands and special steps to a program generated from a DXF file. Remember, when editing tolerancing steps the nominal information is already there. This information is required to create the part drawing.

**NOTE:** *It is important that DXF files are drawn to scale. It is impossible for the QC-4000 to create a correct part program unless the DXF is 1:1.*

### ***Using Record Zoom In A Program***

While performing an inspection routine, it may be necessary to take a close-up look at a particular feature(s). Inserting this command into a program after completing the zoom function, will conveniently store the zoom into the program. This allows the operator to take a closer look without pausing the program.

If your program contains a large amount of features, it may become difficult for an operator to remember which features to zoom while recording the program. It is recommended that the "Record Zoom" function be **Edited** into a previously recorded program.

The "Record Zoom" function will zoom one feature at a time. So if you want only one feature zoomed, you must record a "Zoom to Fit" after that feature. If the "Zoom to Fit" is not performed, and **Auto Zoom** is selected in *Preferences*, your feature will stay zoomed until **after** the next feature is measured. If **Auto Zoom** is not selected, then only that feature will remain in the part view until a Zoom to Fit is performed.

The following will walk you through a program using the "Record Zoom" function. Since you know how to write a program, the instructions given will not be as detailed as before. If you need assistance recording a program, please refer to the previous sections.

In this program Auto Zoom is turned on. For Demonstration purposes we will call this program ZOOM. We will measure some features on the Quickie Slide and Zoom one feature using the Zoom to Fit command and one without so that you may see the difference.

1. Begin the recording of the Zoom program.




Figure 7 - 17

2. Measure Line A, Circles B & C, and Arc D, then End Recording. (See figure 18)

Your program should look like this:

Program View: ZOOM (Editing)	
00001	System Settings
00002	Probe Line "Line 1"...
00003	Probe Circle "Circle 2"...
00004	Probe Circle "Circle 3"...
00005	Probe Arc "Arc 4"...

Figure 7 - 18

**Note:** For a Record Zoom to work properly, the Zoom must be performed first. After the Zoom is performed, it is recorded into the program.

3. Highlight Line 1 from the Part view or feature list.
4. From the View menu choose **Zoom to "Line 1"**.


*We want this to zoom while we measure it. This means we have to insert the Record Zoom before the Probe Line step.*

5. Highlight the step before Probe Line 1 -- System Settings.
6. From the Program menu, choose **Record into "ZOOM"**.
7. From the View menu, choose **Record Zoom**.
8. From the Program menu, choose **End Recording**.
9. Now Select Circle 3 from the feature list
10. From the View menu choose **Zoom to "Circle 3"**.
11. Highlight the step before Circle 3 -- "Probe Circle 2."
12. From the Program menu, choose **Record into "ZOOM"**.
13. From the View menu, choose **Record Zoom**.
14. From the Program menu, choose **End Recording**.



15. Select Circle 3 from the feature list
16. From the View menu choose "**Zoom to Fit**".
17. Highlight Probe Circle "Circle 3" from the program view.
18. From the Program menu, choose **Record into "ZOOM"**.
19. From the View menu, choose **Record Zoom**.
20. From the Program menu, choose **End Recording**.

Your program should now look similar to Figure 7-20.



Program View: ZOOM (Editing)	
00001	System Settings
00002	Record Zoom
00003	Probe Line "Line 1"...
00004	Probe Circle "Circle 2"...
00005	Record Zoom
00006	Probe Circle "Circle 3"...
00007	Record Zoom
00008	Probe Arc "Arc 4"...

Figure 7 - 19

Run the program. You will notice that Line 1 will stay Zoomed until Circle 2 is measured. Circle 3 will zoom in to measure then Zoom to fit after the measurement.


**Note:** If your part view is too small, it will automatically zoom out after the measurement of line 1.


## *Deleting Programs and Sessions*

When you no longer need a program or session, you should delete it to make the disk space available for other programs. Always use caution when deleting a program or session.

The deletion of programs or sessions is accomplished using the Windows File Manager. You should minimize the QC-4000 to an icon or close it completely.

### To delete a file, or group of files:

1. The File Manager is located in the **Main** window in the **Program Manager**. Its' icon will look like a file cabinet. Double click on the icon to open the File Manager.
2. Select the C Drive  from the status bar by clicking on it once.
3. From the View menu, choose **T**ree and **D**irectory. This will show your directories on the left and all your files on the right.
4. Highlight the QC-4000 directory by clicking on it once. All the QC-4000 files will appear on the right hand side.
5. Select the file or group of files you want to delete. Session files will have an extension of **.ses** and programs with **.prg**.
6. From the File menu, choose Delete. The following screen will appear.



7. Press OK. Another screen will appear to Confirm your choose. Press Yes if you are sure that you want to delete that file.

You have now deleted a program. You can now exit the file manager.

## ***Programming Summary***

In this section you have learned how to Create, Edit and Run a Self Teach program as well as creating a part program from a CAD file.

The Auto Program from features is not limited to CAD files. It can also be applied to previously recorded programs or a measured part that you did not record a program while measuring.

Please reference "Points to Remember" while recording a program and the Import DXF information. It will allow your programs to run smoothly as well as making your programs adapt more easily to product updates or other part programs.


You also learned how to use Record Zoom which you can apply to any or all features measured within a program.

Deleting unwanted programs and sessions from the File Manager will save disk space.




---

## *Chapter Eight*



### *Reference Section*

**This section provides detailed information about the functions and capabilities of the QC-4000 and expands upon topics covered in the other sections.**





## *About this Section*

This section provides detailed information about the functions and capabilities of the QC-4000 and expands upon topics covered in the other chapters.

### *What is a Session?*

A dictionary definition for a **Session** is "a period of time spent in some activity." Thanks Mr. Webster, but the QC-4000 is a unique system, and therefore, has its own definition.

**Session** - A screen in which the user spends time configuring and customizing the QC-4000 for the measuring of his/her particular part or parts.

The QC-4000 allows you to save and name a session with the "Save Session As" command. This allows the user to always keep his/her setup.

*NOTE; It is highly recommended that you use "New Session" in the file menu before you start to record a program, so that there is no part reference frame or features in the system.*

### *What is a Feature?*

The geometric entities that you can generate with a QC-4000 include points, lines, circles, angles, distances, and lengths. Each time you complete one of these elements, you will have created a *feature*. Each feature has different distinguishing information. For instance, circles have a center and radius, angles have a degree reading, and points have an X, Y location.

## *Polar Coordinates*

Polar coordinates offer an alternative way to display 2-dimensional positional information.

Don't let polar measurement confuse you. Polar coordinates merely change the way information is displayed, but it's still the same information, just as 1 inch and 25.4 millimeters are two different ways of expressing the same length.

In Cartesian coordinates, distance is expressed with a pair of coordinates named X and Y. This is the system with which we are most familiar. In polar coordinates, we also express a distance with a pair of coordinates, but these are named R and A. These terms represent the radial (straight line) distance and angle magnitude.

Surveyors use polar coordinates all the time. When land is surveyed the plot is not defined by Latitude and Longitude (a version of Cartesian coordinates) for all the corners of the property. Rather, it is defined by polar measurement. The survey will read from boundary marker X23 (the origin) northeast  $36^{\circ} 52'$  for a distance of 65.1 feet, and so on. This is polar measurement, where distances are denoted by traveling some distance in some direction from an origin. Surveyors use north a  $0^{\circ}$ , but north isn't a standard direction when it comes to comparators. We use the positive X axis as our  $0^{\circ}$  line.

Scientific convention dictates that we use the counterclockwise direction (left hand rule) to measure angles. So if you swing from the positive X axis around past the positive Y axis the angle increases.

Polar measurement can be very useful for things like straight line measurements (when the line isn't aligned with the X or Y axis of the part) and for quick angle measurement.



## *Datuming*

When creating a part program, or just measuring a few parts, it is very important to establish a reference point. The QC-4000 allows for establishing Datum's or Part Zeros. The QC-4000 will also allow for Part Skewing. This enables an operator to set a part on the stage and mathematically correct for the offset angle of the part as it sits on the stage. This eliminates time consuming manual alignment and enables more accurate part inspection.

### *Frame Command*


The FRAME command is used to Skew a part and establish an Absolute Zero for the X and Y axes. This routine will skew the part from the first probed line. The user will then be prompted to probe a second line. The vertex point of these two lines will then become the absolute zero. These features will be added to the part view and feature list. The Title Bar of the DRO will indicate that the part skew has been established from the first measured line of the FRAME procedure.

**Note:** *Constructing a FRAME can be accomplished by using the SKEW and ZERO function under the DATUM menu.*

Now let's walk through Probe Frame procedure.

1. Select **Probe Frame** from the DATUM menu. You will be prompted to probe a skew line.
2. Probe the first line, then press "OK." You will be prompted to probe a second line.
3. Probe the second line, then press "OK."


The Frame command is now complete and all future measurements will be relative to the vertex point. The Part View, Feature list and DRO have all been updated. (See figures 1, 2 and 3.)



Frame Command (Figure 8 - 1)



DRO (Figure 8 - 2)



Feature List (Figure 8 - 3)


**Note:** A FRAME command is not allowed during part programming.

## Skewing

The Skew function is a very powerful and useful function that eliminates costly fixturing and time consuming part alignment.

**Note:** To Unskew a part, choose "Use Machine" in the Skew dialog box. (Refer to Use Machine later in this chapter.)


1. Select SKEW under the DATUM menu. A dialog box appears, prompting you to probe or construct a Line.
2. Probe a line on the part in either the horizontal or vertical axis.
3. Press "OK."



**Figure 8 - 4**

The Skew function is now complete. The feature list will automatically title Line 1 as Current Zero and Skew, and the DRO header will show which line the user has Skewed on.

**Note:** To avoid confusion, try not to place the skew line of the part near the 45 degree mark of your stage. ( See Figure 8-5).



**Positioning the part (Figure 8 - 5)**


## Zero

To set a new ZERO point, you may use any method for probing or constructing a single point. (See POINT measurement or construction.) This will create a point feature on the feature list that can be identified as "Current Zero." All future measurements will reflect the current zero.

One powerful application to construct a ZERO Datum, would be to use the intersection of two lines.

### Example:

1. Select **Zero** from the DATUM menu.
2. Select Line 1 and Line 2 from the feature list or part view by holding down the SHIFT key while left clicking the mouse button. (When the features are selected; they will turn blue). Once you have selected the two features, press "OK."




*Zero Point (Figure 8 - 6)*


Once OK has been pressed, the QC-4000 will automatically create an intersection point (Point 3) from the 2 lines and will appear on the feature list as Current Zero. All features measured from now on will be relative to this point.

***Use Machine***

Machine Zero is actually the "Current Position" of your stage when you turn on the QC-4000. The "Use Machine" button, that appears on both the Zero and Skew functions, allows the user to **Unskew** and **Unzero** his/her current zero or skew positions.



*Figure 8 - 7*



*Figure 8 - 8*

Once the "Use Machine" button is pressed, the Zero and Skew commands under the DATUM menu will appear as:


<b>Zero...</b>	<b>I Machine</b>
<b>Skew...</b>	<b>I Machine</b>

## *Set Machine Zero*

The "Set Machine Zero" function is utilized in systems that are equipped with the NON Linear error correction (NLEC) and CNC options.

With these options installed, it is essential to establish a Machine Zero in order for correct and accurate part measurement.

When Set Machine Zero is selected, a screen appears, prompting the user to go to the established machine zero points and press OK. (See figure 8 - 9).



*Figure 8 - 9*

After the user completes this function, he/she will be able to quickly and accurately measure features and/or create fast and easy part programs.

**Note:** If Reference Marks are enabled, you will be asked to Cross your Reference Marks.

## *Multi-Point Measurements*

When you measure a circle, any three non-collinear points are sufficient to fully define that circle. So, when you use 50 points to define a circle, what happens to the other 47 points?

Every point is weighted equally and counts no more than any of the other points. The first three points are used to form a "guesstimation" of the circle.




In effect, the circle is "shifted" around until its circumference is as close to every point as it can be. Any further shifting to better accommodate a few points would lead to greater distances from other points.

One reason for using more than the mathematically needed 3 points to measure a circle is to average out unavoidable inconsistency. Using three points to measure a circle means that each point contributes approximately 33% to the answer; using 50 points gives each point, on average, a 2% weight. Any single stray point will not severely change the measurement of the circle as a whole.

Similarly, a part with rough edges would be difficult to measure accurately without the QC-4000's Multi-point capabilities. When more than 3 points are used, a rough edge can be measured with greater repeatability.

This entire discussion can be applied equally to all multi-point features. Pictured on the next pages are illustrations of the multi-point features: angles, circles, and lines. (Although, to be precise, angles are relations, not features.)

The quantization error that exists in all geometric measuring systems also exists in the QC-4000 system. A small arc less than 90 degrees may cause a repeatability problem (similar to measuring a small arc on an overlay screen versus measuring a complete circle). An arc less than 30 degrees may cause serious repeatability problems. The very short legs of angles may also induce an error factor into the system calculation capability.





The following chart shows the mathematical effects of the number of points taken on a circle with a radius of .250" and .00008" (2 Micron) resolution scales. (This chart assumes no system error). As you can see the average error above 90° arc is the scale resolution and the repeatability of the calculation is +/- 1 count of the scale.

**Circle Radius = .250" Encoder Resolution = .00008" (2 Micron)**

**Degrees of Arc Segment**

Points	<u>10°</u>		<u>30°</u>		<u>45°</u>		<u>60°</u>	
	Mean	Max	Mean	Max	Mean	Max	Mean	Max
<b>3</b>	.0060	.0186	.0007	.0020	.0003	.0009	.0002	.0006
<b>4</b>	.0053	.0174	.0006	.0018	.0002	.0008	.0002	.0004
<b>10</b>	.0041	.0143	.0005	.0017	.0002	.0007	.0001	.0004
<b>15</b>	.0035	.0126	.0004	.0015	.0002	.0006	.0001	.0004
<b>20</b>	.0032	.0107	.0004	.0013	.0002	.0006	.0001	.0003
<b>30</b>	.0027	.0108	.0003	.0010	.0002	.0005	.0001	.0003

Points	<u>90°</u>		<u>120°</u>		<u>180°</u>	
	Mean	Max	Mean	Max	Mean	Max
<b>3</b>	.0001	.0003	.0001	.0002	.0000	.0001
<b>4</b>	.0001	.0002	.0001	.0002	.0000	.0001
<b>7</b>	.0001	.0002	.0001	.0002	.0000	.0001
<b>10</b>	.0001	.0002	.0001	.0002	.0000	.0001
<b>15</b>	.0001	.0002	.0001	.0001	.0000	.0001
<b>20</b>	.0001	.0002	.0001	.0001	.0000	.0001
<b>30</b>	.0001	.0002	.0000	.0001	.0000	.0001

Unless shown differently, the numbers in this chart are shown to the nearest .0001" because of Metric scale resolution.

**Mean** = The average true position of the calculated circles center for 0,0.

**Max** = The total repeatability error that can be expected from the calculated circles' center.

## *Find Feature*


By now you're probably familiar with most of the basics of the QC-4000-- how to open, close and save sessions and programs. This section will teach you the convenience of the Find Feature command.

Trying to find a particular feature by scrolling through a very long list of features could become very tedious and time consuming.

Being able to find and select a single feature or certain type features without having to scroll through the feature list is an important time-saver. The Find Feature command finds and selects one or all features you specify, making it fast and easy to locate the features you want.

### **To search for a feature:**

1. From the **EDIT** menu, choose Find Feature. The Find Feature dialog box will appear (See figure 13).



*Figure 8 - 10*

2. Type the feature name you wish to search for, then press ENTER or left click on the Find button.

*Use wildcards (\*.\*) to initiate the search for all features of a specific type. Example: Type **Circle**.\* to search for **all** circles listed in the feature list.*

## *Specifying Search Criteria*

Some part measurements or programs can be quite long, resulting in a rather lengthy feature list. Choosing the *Find Feature Options* button provides a convenience alternative to scrolling through the feature list to find and select specific features. By specifying certain criteria's for features that have similar coefficients or a specified coefficient range, you can pinpoint the exact feature or features you want in a flash.

## *Feature Types*

One of the question you must ask yourself when using the find feature command is -- "*What Feature Type shall I choose?*" Various ranges and types can be selected. It is also possible to select one certain criteria, then go back and ADD another without losing any of the other features already selected. (See "Adding and Removing Features")

The following is a list of Feature Types you can select. Only one can be selected at a time. Left clicking on the word will fill the circle next to the feature type. In this sample, Circle is the feature type that is selected. This means that *all* Circles on the feature list will be selected, unless certain criteria's apply. See Logic Operators.

- Selected feature type* →
- P**oint
  - L**ine
  - C**ircle
  - A**rc
  - D**istance
  - A**ngle
  - H**eight
  - A**ll

*Find Feature Types (Figure 8 - 11)*

If **All** is selected, then *all* features or all features with a specified criterion will be selected on the feature list.

## Logic Operators

The logic operators are used to select the specified feature or coefficient range. For example, by selecting the equal sign in the distance column, and choose the Distance Feature Type, you can find all Distances with a length equal to 1 inch.

The following table helps explain how the Find Feature Options window works.

Greater than or Equal to the #.		Coefficient		Less than or Equal to the #.
Greater than the #.		Coefficient		Less than the #.
Equal to the #.		Coefficient		Equal to the #.
Not equal to the #.		Coefficient		Not equal to the #.

The Find Feature Command also allows the user to choose a specific feature number or a range of features. In this sample, we are looking for features numbered 1 to 10.

1		Feature #		10
---	--	-----------	--	----

The Logic Operators in the Feat.# box can also be changed to Greater than, Less than or Equal to. This will allow you to select a single feature or a range of features.

**To find specified features:**

For this demonstration, we will find all Circles having a radius equal to (=) 1 with a +/- Tolerance greater than (<) .005.

1. Choose the Options button in the find feature display window. The following screen will appear.

*Find Feature Options Screen (Figure 8 - 12)*

2. Choose the Circle feature type.
3. Left click on the *right* logic operator beside the word Radius until just the equal (=) sign appears.
4. Type 1.0 in the box to the right of the button.
5. Left click on the *left* logic button beside the +/- T until just the greater than (<) sign appears.
6. Type .005 in the left column beside the +/- T.
7. Press OK.

The QC-4000 will now search the feature list for all circles with the Radius of 1 and a tolerance greater than .005.

## **Adding and Removing Features**

The Find Feature Option allows more than one type of feature or criteria to be selected. You can also deselect features that have been chosen previously.

Since all circles with the Radius of 1 and a tolerance greater than .005 are selected, let's go back and include **all** features that have a tolerance greater than .005.

### **Adding other Criteria.**

1. From the EDIT menu, choose Find Feature. The Find Feature dialog box will appear.
2. Choose the Options button in the find feature display window.
3. Choose CLEAR to erase any unwanted numbers.
4. Select ALL from the Feature Type column.
5. Left click on the left logic button beside the +/- T until just the greater than (<) sign appears.
6. Type .005 in the left column beside the +/- T.
7. Left click on the ADD button.

All features with a tolerance greater than .005 including circles with a radius of 1 will now be selected.

Now let's remove all the Circles and just look at the tolerances.

### **Removing features**

1. From the EDIT menu, choose Find Feature. The Find Feature dialog box will appear.
2. Choose the Options button in the find feature display window.
3. Choose CLEAR to erase any unwanted numbers.
4. Select Circle from the Feature Type column.
5. Left click on the left logic button beside the +/- T until just the greater than (<) sign appears.
6. Type .005 in the left column beside the +/- T.
7. Left click on the REMOVE button.

All circles with a +/- T of .005 will be deselected from the feature list.

## ***Tolerancing***

Tolerancing a feature allows the user to determine if the position and size of the feature(s) is in accordance with blueprint specifications. The Tolerance button can be found in the *Results Window*.

The QC-4000 has the capability of doing full feature tolerancing including: Cartesian, True Position, Maximum Material Condition (MMC), Least Material Condition (LMC), Runout, Concentricity, Circularity, Angle, Straightness, Parallelism, and Perpendicularity.

Although you can tolerance a feature with as few as 10 points, it is recommended that you enter as many points as feasible to insure accurate tolerancing.

Different feature types have different tolerancing data. The following paragraphs will go through the allowed tolerances for each feature.

### ***Valid Tolerance Types (More than 10 points)***

<b>FEATURES</b>	<b>ALLOWED TOLERANCES</b>
Point	Cartesian, True Position
Line	Angle, Straightness, Parallelism, Perpendicularity
Circle	Cartesian, True Position, MMC, LMC, Runout Concentricity, Circularity.
Arc	Cartesian, True Position, MMC, LMC, Concentricity, Circularity.
Distance	Width (X, Y & L)
Angle	Angle

## Tolerancing Information

**Cartesian Circle Tolerance For "Circle 10"**

Position		Nominal	+ Tol.	- Tol.	+ Limit	- Limit
X						
Y						
Tolerance Name					Del Tol.	

Size		Nominal	+ Tol.	- Tol.	+ Limit	- Limit
r						
d						
Tolerance Name					Del Tol.	

Datum		Action
Skew	Machine	<input type="checkbox"/> Print Pass <input checked="" type="checkbox"/> Pause Pass
Zero	Machine	<input type="checkbox"/> Print Fail <input checked="" type="checkbox"/> Pause Fail

*Cartesian Tolerance Screen (Figure 8 - 13)*

Each tolerance program step includes the following information:

1. Nominal values.
  2. Tolerance values.
  3. Print/Pause directive.
  4. Tolerance Name
- Once a Tolerance Type is selected, you must enter the *nominal values* for the X, Y position and radius or diameter (when tolerancing circles).
  - The *tolerance values* may be entered as either plus and minus values or as the dimension maximum and minimum (+/- Limit).



- The *Print/Pause directive* is identical for all tolerances. This may be set to either PRINT or PAUSE after each tolerance for both the PASS and FAIL conditions. Left mouse click on each directive to enable/disable the condition.


*Note: If PAUSE is set, then, when running programs, continue after the pause by press the Continue button in the tolerance screen.*

- Assigning names to frequently used tolerance values will save the user a considerable amount of time. The user just selects a previously saved *tolerance name* and the values will automatically appear in its proper designated area. A feature name can be used for different features so long as the *tolerance type* is the same. Please refer to "Tolerance Type" later in this section.

After tolerance values are entered, just type a name in the Tolerance Name box. Up to 20 characters can be used to identify a tolerance. When assigning a tolerance name, it is recommended you use characters that will show a relationship between the tolerance values and its name.

Once a tolerance name has been created, the values can no longer be edited. You can however, delete unwanted tolerance names.

### **To Choose a previously named tolerance:**

- \*  Left-click on the down arrow at the end of the box. A list of available names will appear. Left click on the appropriate one.

You can also select tolerance names using the keyboard. Tab over to the box then use the down arrow key on your keyboard.

### **To Delete a Tolerance Name:**

- \* Choose the tolerance name as mentioned above.
- \* Press the Delete Tolerance button (Del Tol).

## ***Tolerance Types***

There are several different types of tolerances. The QC-4000 follows the terms in the ANSI Y14.5M Specification for Location, Orientation, Size, Runout and Form Tolerances. However, when applied to discrete point measurements, the QC-4000 is unable to conform totally to this code. Please read the Disclaimer below.

### ***DISCLAIMER***

Some types of measurements (straightness, flatness, etc.) is difficult to perform on the Optical Comparator or CMM because of the relatively small number of points that are used to measure (estimate) a feature. In addition to this problem, the specific definition of these terms in the ANSI Y14.5M Specification (Dimensioning and Tolerancing), is subject to some interpretation when applied to discrete point measurement. There are, in fact, other methods for calculating fit that may be used to determine feature form. One example is the "largest Inscribed/Smallest Circumscribed circle. This method duplicates the pin or ring gage technique used to measure the size of pins or holes. For further information refer to ANSI B89.3.1.

### ***Tolerance of Location***

Tolerance *Locations* are relative to the current incremental zero and may be "Cartesian," "True Position," "LMC" or "MMC" type. In the QC-4000 system, these tolerances are applied to points, arcs or circles.

Before a tolerance test is applied, the nominal position of the feature must be entered. Then the actual position is measured and compared and the tolerance report is displayed. The feature position is always displayed in relation to the current datum which is either absolute or incremental zero. This same position data is used when the tolerance tests are done. Always be sure that you enter the nominal position in relation to the appropriate datum.

Concentricity (shown below) is just one example of a Location Tolerance. This figure is a visual representation of what the concentricity tolerance screen indicates after a tolerance is performed.

### Concentricity




Figure 8 - 14

### *Size Tolerance*

Distance is an example of a Size Tolerance. This function works in essentially the same way as the POINT Cart Tolerance. When a distance is generated by probing, construction, or the CREATE function, and "Tolerance" is selected (with the distance as the current feature) the QC-4000 will display the same tolerance screen as in POINT Cart except the screen heading will read "Distance Width Tolerance". As in POINT Cartesian Tolerances, you must enter the Nominal position, the plus and minus values or the dimension maximum and minimum. The missing fields will be filled in automatically.

Distance Width Tolerance For "Dist 12"					
<b>Position</b>					
	Nominal	+ Tol.	- Tol.	+ Limit	- Limit
X					
Y					
Tolerance Name <input type="text"/>					<input type="button" value="±"/> <input type="button" value="Del Tol."/>
<b>Datum</b>			<b>Action</b>		
Skew	<input type="text" value="Machine"/>		<input type="checkbox"/> Print Pass	<input checked="" type="checkbox"/> Pause Pass	
Zero	<input type="text" value="Machine"/>		<input type="checkbox"/> Print Fail	<input checked="" type="checkbox"/> Pause Fail	
<input type="button" value="OK"/> <input type="button" value="Cancel"/>					

Width Tolerance Screen (Figure 8 - 15)

## ***Orientation Tolerances***

The Orientation tolerance for lines gives and estimate of how parallel, perpendicular or angular a LINE is compared to the datum alignment. We say estimate because when a line is measured, the line itself is estimated (by the least squares best fit method) and the datum alignment is also estimated. The same limitations apply to the RUNOUT tolerance for circles.

The least squares best fit method uses discrete probed points. If a larger number of points are used, we can apply statistics to the point data information and get a more practical measure of orientation. For any critical tolerance, a **minimum** of fifty (50) points should be taken when probing the feature.

*Note: The least squares best fit method is used to estimate part alignment, therefore, it is a good idea to use a large number of points when doing the part alignment.*

The screen for Parallelism and Perpendicularity are the same (except for the heading of course).

### **To perform a LINE Orientation Tolerance:**

1. Probe a line using at least 10 points (more is recommended).
2. Select the appropriate tolerance type from the Results Window. The tolerance screen will appear.

Line Parallelism Tolerance For "Line 18"									
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <b>Tolerance Zone Size</b>  <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%; border-bottom: 1px solid black;">Tol. Zone</td> <td style="width: 40%; border-bottom: 1px solid black;">Tolerance Name</td> <td style="width: 10%; text-align: center;">↓</td> <td style="width: 20%; text-align: center;">Dgt Tol.</td> </tr> <tr> <td style="border-bottom: 1px solid black;"><input style="width: 90%;" type="text"/></td> <td style="border-bottom: 1px solid black;"><input style="width: 90%;" type="text"/></td> <td style="text-align: center;">↓</td> <td style="text-align: center;">Dgt Tol.</td> </tr> </table> </div>		Tol. Zone	Tolerance Name	↓	Dgt Tol.	<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	↓	Dgt Tol.
Tol. Zone	Tolerance Name	↓	Dgt Tol.						
<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	↓	Dgt Tol.						
<div style="border: 1px solid black; padding: 5px;"> <b>Reference Feature</b>  <input style="width: 90%;" type="text"/>  <div style="text-align: center; margin-top: 5px;"> <input type="button" value="Select"/> </div> </div>	<div style="border: 1px solid black; padding: 5px;"> <b>Action</b>  <input checked="" type="checkbox"/> Print Pass    <input checked="" type="checkbox"/> Pause Pass  <input checked="" type="checkbox"/> Print Fail    <input checked="" type="checkbox"/> Pause Fail         </div>								
<input type="button" value="OK"/> <input type="button" value="Cancel"/>									

***Tolerance Setup Screen for Parallelism(Figure 8 - 16)***

3. Indicate your choice for Print/Pause for any tolerance.
4. Enter the nominal value. This is the width of the "Tolerance Zone" which defines the parallelism or perpendicularity.
5. Enter the feature is which it will be referenced by, or press the SELECT button to choose the feature from the feature list, then press OK.




The orientation tolerances are displayed as well as the PASS/FAIL condition. Press "Continue", to proceed to the next measurement or "Edit Tol." to (you guessed it), Edit the Tolerance.

Line Parallelism Tolerance Result For "Line 12"							
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: left;">Orientation</th> </tr> <tr> <th style="width: 50%;">Tol. Zone</th> <th style="width: 50%;">Actual</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0.7500</td> <td style="text-align: center;">0.7415</td> </tr> </tbody> </table>	Orientation		Tol. Zone	Actual	0.7500	0.7415	<div style="text-align: center; margin-bottom: 10px;"> <input type="button" value="Continue"/> </div> <div style="text-align: center;"> <input type="button" value="Edit Tol."/> </div>
Orientation							
Tol. Zone	Actual						
0.7500	0.7415						
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: left;">Reference</th> </tr> <tr> <th style="width: 50%;">Feature</th> <th style="width: 50%;"></th> </tr> </thead> <tbody> <tr> <td></td> <td style="text-align: center;">Line 11</td> </tr> </tbody> </table>		Reference		Feature			Line 11
Reference							
Feature							
	Line 11						

*Result Screen(Figure 8 - 17)*

RUNOUT tolerance for a circle is performed in essentially the same manner as that for the parallelism/perpendicularity of a LINE. The same types of statistics are used for the points that were probed on the circle.

The next page shows a visual representation of how Parallelism, Perpendicularity and Runout are determined.



## ***Form Tolerance***

Form Tolerance is method of estimating the straightness of a line or the roundness (Circularity) of a circle. Please refer to the "Form Disclosure" at the beginning of the Tolerance section.

This type of report displays statistical information for two different fitting algorithms. The fitting methods are "Least Squares Best Fit" (LSFB) and "Constrained Best Fit" (CBF).

The LSFB is the method used in virtually all Optical Comparators. In this method, all the points used in multi-point measurement are treated as being equally important. The resultant feature is an "average" of all the points. With LSFB a line is calculated which minimizes the sum of the errors of all the squares.

The CBF is another, equally valid, method of estimating the position and size of features. In this method the "high and low" points which were probed on the feature surface, are used to calculate the best fit. With CBF we are calculating a line for which the worst error is minimized.

## ***GROUP TOLERANCING***

The QC-4000 also allows the user to perform group tolerancing. This is generally used as a programming step when creating a program. It does **not** show "group" results, but will show the tolerance results of each individual feature when the program is run.

This is where the **F**ind **F**eature command under the **E**dit menu, comes in real handy. By choosing **F**ind Feature and selecting the **O**ptions button, you are able to select specific features to tolerance. If you have one hundred circles to tolerance, using the **F**ind Feature command will find and select all the circles necessary for you. It definitely beats having to select them out of the feature list one at a time. (Refer to the **F**ind Features section).

After completing all the measurements in the program, simply select the features you would like to tolerance, then select **Tolerance All** from pull-down menu in the Results Window, and select the tolerance type from the second pull-down menu. When your program is run, you will get the results for each feature toleranced.


***About Print/Pause Pass/Fail***

When performing a Group Tolerance, the Print/Pause command becomes a tri-state control. In other words the check box can have one of three choices:

1.  **Clear** - Set all tolerances in the selected group to OFF.
2.  **Checked** - Set all tolerances in the selected group to ON.
3.  **Grayed** - Leave all tolerances in the selected group to the state that they are currently in.

***To perform a Group Tolerance:***

1. Create a program.
2. After all features are measured, select features you wish to tolerance from the feature list or by the Find Feature command. and press OK.
3. Select Tolerance All from the Results Window.
4. Select tolerance type from the pull down menu.



5. A group tolerance screen will appear.

Group Angle Tolerance				
Angle				
Nominal	+ Tol.	- Tol.	+ Limit	- Limit
*****				
Tolerance Name				Dgt Tol.
Datum		Action		
Skew	Machine	<input type="checkbox"/> Print Pass	<input checked="" type="checkbox"/> Pause Pass	
		<input type="checkbox"/> Print Fail	<input checked="" type="checkbox"/> Pause Fail	

***Group Tolerance Screen (Figure 8 - 18)***



Notice that in this screen; the "Nominal" box already contains asterisks (\*). This is because the features that have been selected have different nominal values.

*Note: When performing a group tolerances, the Nominal box **should** be filled with asterisks.*

6. Choose your tolerance dimensions and the Print/Pass directive.
7. Press OK.
8. End Program.

### ***USING TOLERANCE IN A PROGRAM***

By now you should be able to record a program like a Professional. This portion will walk you through a small tolerance program so that you may see for yourself how easy Tolerancing can be with the QC-4000.

Start recording a program and measure the large circle on the Quickie slide. Remember, you should skew and zero the part before measuring the circle.

Once the Circle measurement is completed:

- Select the circle so that it appears in the results window.
- In the results window, you will see a "Tolerance" button. Left-click the button. A menu will appear with the various types of Tolerancing.
- For demonstration purposes, select CARTESIAN. The Cartesian set screen will now appear (See figure 22). Note that the nominal for the X and Y coordinates and the radius and diameter are the actual values from the features just measured.
- The X coordinate nominal box should be highlighted. At this time, enter the nominal dimension from the blue print. (Use the QC-Quickie Slide as your print, located at the end of this chapter.)

X = 3.000 inches

Y = 0.500 inches

**Cartesian Circle Tolerance For "Circle 12"**

Position		Nominal	+ Tol.	- Tol.	+ Limit	- Limit
X		3.000	0.005	0.005		
Y		0.500	0.005	0.005		

Tolerance Name

---

Size		Nominal	+ Tol.	- Tol.	+ Limit	- Limit
r		0.250				
d						

Tolerance Name

---

Datum		Action
Skew	<input type="text" value="Line 3"/>	<input type="checkbox"/> Print Pass <input checked="" type="checkbox"/> Pause Pass
Zero	<input type="text" value="Point 3"/>	<input type="checkbox"/> Print Fail <input checked="" type="checkbox"/> Pause Fail

*Figure 8 - 19*

**Note:** When entering numbers using the keyboard, you may use the tab key to get around the screen or use the mouse by placing the I-beam in front of the number. Hold down the left mouse button and drag the mouse to highlight the number; then type the number from the keyboard.

- Now tab over or use the mouse, and go to the X +TOL box. Enter **.005**. For demonstration purposes, we will use .005 as our limits.
- Now tab over to the X -TOL box and enter .005.
- Tab over to the Y + and - boxes and enter .005. This will establish our upper and lower limits.
- Now tab down to the nominal RADIUS box.
- Enter the nominal dimension from the Quickie Slide of **0.250** inches.
- Enter **0.005** in the + and - TOL boxes.

In the Action Setup area, be sure that both PAUSE PASS and PAUSE FAIL are selected. An X in the box indicates they are selected and will allow you to view the tolerance results.

- Press "OK." The Tolerance results screen will appear. Notice the green and red warning lights indicating whether the feature passed or failed.

**Circle Cartesian Tolerance Result For "Circle 9"**

Position						
	Nominal	Actual	Deviation	+ Limit	- Limit	
X	3.0000	2.9983	-0.0017	3.0050	2.9950	P
Y	0.5000	-0.4979	-0.9979	0.5050	0.4950	F

Size						
	Nominal	Actual	Deviation	+ Limit	- Limit	
r	0.2500	0.2515	0.0015	0.2550	0.2450	P
d	0.5000	0.5030	0.0030	0.5100	0.4900	P

Datum	
Skew	Line 1
Zero	Point 3

- To continue recording, press the CONTINUE button.
- End Recording.

### *What happens when the program is run?*

When a toleranced feature is measured, the tolerance calculation will be done. If the tolerance data specifies that the program should pause on PASS or FAIL conditions, the tolerance report will be displayed. If print on PASS or FAIL is specified, the report will be printed. Press Continue to proceed.

**Angle Tolerance Result For "Line 6"**

Angle				
Nominal	Actual	Deviation	+ Limit	- Limit
91°39'20"	92°25'13"	0°45'52"	92°39'20"	90°39'20"

P

<b>Datum</b>	<input type="text" value="Machine"/>	<input type="button" value="Continue"/>	<input type="button" value="Exit"/>
<b>Skew</b>	<input type="text"/>		

*Results Screen (Figure 8 - 20)*

***When Tolerancing Remember:***

- A minimum of 10 points is need to perform tolerances.
- Tolerance values must be entered as plus & minus values or as dimensions MIN/MAX.
- Print/Pause command is identical for all tolerances.
- To save time, assign names to frequently used tolerances. The names can contain up to 20 characters.
- Using the "Find Feature" command can save valuable time when performing Group Tolerances.

## *Tolerance Report Sample*

The tolerance report shows the nominal values, the actual feature coefficients, the deviation from the nominal, and the PASS or FAIL condition. For CIRCLE tolerances, the report also indicates whether the size tolerance passed, whether the position tolerance passed and, for MMC and LMC, whether the CIRCLE feature passed overall.

QC-4000 Feature Print Out					
Quickie Printing 30 Anywhere Road Someplace, USA 03110					
Date: 7-27-93		Part: QC Quickie		Time: 3:12 p.m.	
Job: Printout				Operator: Q.T.	
FEATURE	ACTUAL	NOMINAL	FLG	DEVIATION	FORM
Point 1 True Pos Inch	X = -0.6066 Y = -0.5450	-0.6066 -0.5450		0.0000 P	
Line 2 Angle Inch	A = 90.34'28"	90.34'28"		0.00'00" P	+T = 0.0000 -T = 0.0000
Circle 3 MMC Inch	X = -0.5492 Y = -0.1529 R = -0.0925 D = -0.1850	-0.5492 -0.1529 -0.0925 -0.1850		0.0000 P 0.0000 P 0.0000 P	+T = 0.0000 -T = 0.0000
				Bonus = 0.0100	
				Bonus + Dia. = *****P	

## *Report Header*

**Report Header**

**Fields**  
 **Company**  
 **Date**    **Time**  
 **Job**    **Part**    **Operator**

**ID**  
**Job:**     
**Part:**     
**Operator:**

**Company**  
**Name:**     
**Address:**

---

*Report Header Screen (Figure 8 - 21)*

There are two ways a feature printout can be generated. The first is the "*Print Selected Features*" function and the second is the "*Report*" (wizard), both of which are located under the **FILE** menu. No matter which format you are using, you can customize the information on your Report header.

Selecting **Report Header** from the **File** menu will bring up the Report Header screen (See Figure 8-24). Choose the field types you wish to appear on your header, then using the keyboard, type the information as you want it to appear.

## ***Print Selected Features***

It is very important to understand the differences between "*Print Selected Features*" and *Report Wizard*.

- Print Selected Features allows you to print one feature at a time or several selected features.
- Unlike the Report Wizard, the Print Selected Features printout format is a fixed format and cannot be customized. (Except the Header).
- This format does not include an automatic form feed. It must be performed manually (on the printer) or by selecting the Form Feed button from the report header screen.
- Normally, this format is to be printed out on an Epson compatible printer. If you try to print this format on a laser printer you may get garbage at the end of your printout.

### **To try the *Print Selected Feature* function:**

Select a feature or several features from the feature list.

From the file menu select **Print Selected Features** function. (ALT F, R)

One of two standard printout formats will be used for these features depending on whether or not the feature was toleranced (see figures 25 and 26 on next page).

QC-4000 Feature Print Out					
Quickie Printing 30 Anywhere Road Someplace, USA 03110					
Date: 7-27-93		Part: QC Quickie		Time: 3:12 p.m.	
Job: Printout				Operator: Q.T.	
FEATURE	#	UNITS	POSITION	DIMENSION	FORM
Point 1 point	1 pt	Inch	X = -0.6066 Y = -0.5450		
Line 2 line	2 pts	Inch	X = -0.8448 Y = -0.0085	A = 90°34'28"	+T = 0.0000 -T = 0.0000
Circle 3 circle	3 pts	Inch	X = -0.5492 Y = 0.1529	R = -0.0925 D = -0.1850	+T = 0.0000 -T = 0.0000
Dist 5 distance	2 fts	Inch	X = -0.8448 Y = -0.0085	X = 0.2972 Y = 0.0030 L = 0.2972	

**Feature Print Out (Figure 8 - 22)**

QC-4000 Feature Print Out					
Quickie Printing 30 Anywhere Road Someplace, USA 03110					
Date: 7-27-93		Part: QC Quickie		Time: 3:12 p.m.	
Job: Printout				Operator: Q.T.	
FEATURE	ACTUAL	NOMINAL	FLG	DEVIATION	FORM
Point 1 True Pos Inch	X = -0.6066 Y = -0.5450	-0.6066 -0.5450		0.0000 P	
Line 2 Angle Inch	A = 90°34'28"	90°34'28"		0°00'00"	+T = 0.0000 -T = 0.0000
Circle 3 MMC Inch	X = -0.5492 Y = -0.1529 R = -0.0925 D = -0.1850	-0.5492 -0.1529 -0.0925 -0.1850		0.0000 P 0.0000 P Bonus = 0.0100 Bonus + Dia. = *****P	+T = 0.0000 -T = 0.0000

**Tolerance Printout Format (Figure 8 - 23)**




## *Exporting to Excel*

As mentioned earlier in this manual, the SPC Link function can be used to export features to other software packages. Exporting to Excel will allow the user to print all the features out at one time or create a graph.

### *To Export to Excel:*

1. Open Excel. Excel *must* be opened to export data from SPC link. You can minimize Excel to an icon and still have it running.
2. From the QC-4000 select a feature. The SPC Link command allows you to export up to eight features at one time.
3. From the **F**ile menu choose SPC Link. The following screen will appear. (See figure 8-27) This screen will only appear once.-- The first time during a session that a link is made.




SPC Link Options		
Application Name	<input type="text" value="excel"/>	<input type="button" value="OK"/>
File Name	<input type="text" value="book1"/>	<input type="button" value="Cancel"/>

*Figure 8 - 24*

4. Since EXCEL is the application we are using, type Excel in the "Application Name" box.
5. If you have a previously saved file, you may type the name of the program in the File name box. (Example -- Demo.xls.) If this is the first time opening Excel and you do not have any files, you may type **book1** like in figure 4-27. (You can "Save As" later.)

6. Press OK. A new screen will appear (See figure 4-28).



The image shows a dialog box titled "SPC Link". It contains three input fields on the left and three buttons on the right. The first field is labeled "Feature Coefficient" and contains the letter "X". The second field is labeled "File Column" and contains the letter "A". The third field is labeled "Row" and is empty. The buttons are labeled "OK", "Cancel", and "Options...".

*Figure 8 - 25*

7. This screen is used to send certain feature information to a specified column on the Excel data sheet. Choose the feature coefficient and column from the arrow on the side of the box.
8. Enter the Row that you wish the coefficient to appear.
9. Press OK. The information will now be sent to the Excel program that is open. Wasn't that simple?

Choosing the **Options** button will bring you back to the SPC Link Options screen, to allow you to change your file name.

*Note: The SPC Link function will allow 8 features but only one Feature Coefficient to be exported at a time. It is advisable to name your Excel worksheet columns the same as your feature coefficients to avoid any confusion between them.*

## ***DDE***

Dynamic Data Exchange is a message protocol for data exchange between Windows programs.

While Windows DDE is a very powerful tool, It is important to understand some concepts and terminology before using DDE. Dynamic data exchange is actually a “conversation” between two applications.

When using the QC-4000, we can simplify this explanation by characterizing the two applications as, “The Talker”-- one sending a command, and the “The Listener”-- the one responding to the command.

**QC4000 RESULTS**  
**DRO**  
**PARTVIEW**

**FEATURELIST**  
**STATUSBAR**  
**TOOLBOX**

Each of the above can precede the following text:

- .OPEN** - This opens the corresponding window.
- .CLOSE** - This closes the corresponding window.
- .MINIMIZE** - This minimizes the corresponding window.
- .MAXIMIZE** - This maximizes the corresponding window.
- .RESTORE** - This restores the corresponding window to a non minimized/maximized size.
- CNC.GOTO** - (X position units, Y position units, Z position units, relative move). This causes CNC GOTO to happen. Units can be either MM or Inch. Relative move can be either TRUE (Relative to **Current Position**) or FALSE.

### **Example:**

CNC.GOTO (1.25mm, 2.871mm, -3.411mm, FALSE)

### **PROGRAM.WAITFORCONTINUE**

WaitForContinue causes a program that is running to stop at the current step and wait for a Continue Command.

### **PROGRAM.CONTINUE**

### **PROGRAM.RUN** (Program name)


This runs the program given as a parameter.

### **PROGRAM.PAUSEPROGRAM**

This will act as if the Pause Program menu item was pressed.

If you need more in-depth information about DDE, you may want to refer to your Microsoft® manuals or contact the Microsoft support network.








---

## Chapter Nine



### *Supervisor Setup*

Display  
Axes  
LEC  
Axis Board Test  
NLEC  
Locks  
CNC I/O Test  
Edge IO Test  
Footswitch  
Print your settings



QC-4000







## Supervisor Setup





Figure 9 - 1 SUPERVISOR SETUP SCREEN

The *Supervisor Setup Screen* is used to setup and calibrate the QC-4000. These setups are performed at the factory and by your distributor. **Changing the parameters may cause severe degradation of your system**

To enter the Supervisor Setup menu select "**Supervisor Setup**" under the **FILE** menu. (ALT F, V). A message will be displayed, prompting you to enter the special Supervisor Code. Supervisor codes are available only through a dealer.

When typed, the password will appear as asterisks (\*). Press OK. The Supervisor Setup screen will appear. (See figure 9-1).



This section will describe the specifics of the Supervisor Setup screen. It is used to set such items as resolution, display, and to test your Axis, I/O and Edge board.

**Display**
*Figure 9 - 2 DISPLAY SETUP SCREEN*

As you can see, this is where you would 1) Set your display resolution, 2) Set your DRO as Decimal Degrees (DD) or Degrees, Minutes, Seconds (DMS), 3) Type of time (military or standard), 4) How the date will be displayed on the status bar. 5) Set how you would like your features in the Results Window to read.

**Axes**
*Figure 9 - 3 AXES SETUP SCREEN*

This screen allows you to select your encoder type. Setting your Encoder resolution has never been easier. Just left click on the arrow to the right of the box, scroll through the selections and choose one for each axis.

Encoder Options	
<b>Resolution</b>	
X Axis	<input type="text" value="0.001"/> <input checked="" type="checkbox"/> mm <input type="checkbox"/> Reverse <input type="checkbox"/> 5x <input type="checkbox"/> Ref Mark
Y Axis	<input type="text" value="0.001"/> <input checked="" type="checkbox"/> mm <input type="checkbox"/> Reverse <input type="checkbox"/> 5x <input type="checkbox"/> Ref Mark
<input type="button" value="OK"/> <input type="button" value="Cancel"/>	

*Figure 9 - 4 ENCODER OPTIONS SCREEN*

The Options button is a second way to set Encoder resolution. It is also where you would enable **mm** if you have a metric encoder, reverse axis count direction, activate the 5X circuit, and enable the Reference Marks.

## LEC

Linear Error Correction Setup		
<b>Standard Lengths</b>	<b>Observed Lengths</b>	<input type="button" value="OK"/> <input type="button" value="Cancel"/>
X <input type="text" value="0.2500"/> Y <input type="text" value="0.2500"/> Z <input type="text" value="0.0394"/>	X <input type="text" value="0.1500"/> Y <input type="text" value="0.1500"/> Z <input type="text" value="0.0394"/>	
<input checked="" type="checkbox"/> LEC On		

*Figure 9 - 5 LEC SETUP SCREEN*

Linear Error Compensation allows you to correct for small linear errors in your stage. An error is linear if it is the same wherever you are on the travel of your machine--if you find that you have 0.0002" error in 1 inch of travel, you will have 0.0012" error in any 6 inches of travel.

To use Linear Error compensation you must first have a reference standard available for each axis of motion, namely X and Y. Next, you need to measure this standard on your system, noting the measured distance (or "observed Lengths"). If your measurement is repeatedly too short or too long compared to the standard's length, then you need to use LEC.

**CAUTION:** You must clear the previous error compensation from the axis you wish to correct before you attempt to calibrate that axis.

**To clear LEC:**

Enter a non-zero standard length (such as 1 inch) and then enter the same number (1 inch) for the observed length.

If you have determined that you need to use LEC, measure your standard in the X and Y axes to obtain your "observed lengths."

Once you have your numbers:

1. Choose *Supervisor Setup* under the **F**ile menu.
2. Enter the Supervisor Password when prompted. Then press **ENTER**.
3. Select LEC from the setup screen.
4. Enter the Standard and Observed lengths in the appropriate space.
5. Enable LEC by left clicking on the box.
6. Press **ENTER** or left click on **OK**.

## ***Axis Board Test***

This initiates a self test of the Axis board circuitry. The self test checks a large portion of non-CNC circuitry but not all. When selecting this test, a message will appear. *"Performing an axis board test will change the current scale position and thus render any previous feature and datum information incorrect. Do you still want to continue?"* Press **Yes** to continue or **No** to exit the test.

If Yes is selected, the following screen will appear.

Axis Board Test				
Axis Board #1			<b>End Test</b>	
	Detected	Times Passed		Times Failed
X Axis	<input checked="" type="radio"/>	27		0
Y Axis	<input checked="" type="radio"/>	27		0
Axis Board #2				
	Detected	Times Passed	Times Failed	
Z Axis	<input type="radio"/>	0	0	
Q Axis	<input type="radio"/>	0	0	

***Figure 9 - 6 AXIS BOARD TEST SCREEN***

What the screen is telling you, is that it has detected the X and Y axis, it has run the test and passed 27 times. Select End Test to exit the screen.

If, out of several passes, the board fails only one time, end the test and try it again. (It could have been a glitch.)

If all the tests pass, but there is still something wrong, check all your cabling and connectors to insure proper seating and connection.


If the test failed several times, then there may be something wrong with your axis board.

## ***NLEC***

The Non-Linear Error Correction button will only appear if your system includes this option. If so, please refer to the NLEC portion of the Options Section.

## ***Locks***

The **LOCKS** button in the Supervisor Setup, allows you to lock (or unlock) certain QC-4000 features. When these features are unlocked, it is possible that they may fall prey to a curious user.




*Figure 9 - 7*

**Lock Preferences** - Some customers would prefer the QC-4000 to remain in one particular setup. Enabling "Lock Preferences" would gray *Preferences* under the **File** menu making it inaccessible to users. It can only be unlocked by re-entering the *Supervisor Setup* and deselecting "Lock Preferences."

**Lock Access to Point Filtration** - Point Filtration is enabled or disabled in the System Settings step of the program view. Enabling this will lock Point Filtration in the same state (enabled or disabled) which is selected from the System Settings. Please refer to the Programming Section for more information on Point Filtration.

The normal default for Point Filtration is Locked.

**Fixed Run Program Mode** - Locking the Program Mode will only allow the user to **Run** a program or **Shutdown** the QC-4000. The only other menu selection from the **File** menu is the **Supervisor Setup**. Going into the Supervisor Setup is the only way to unlock this mode.




**Lock Calibration Data** - Enabling this function will remove the **Edit Calibration** menu item from the **Probe** menu. The user is allowed to perform **New Calibrations**, but not allowed to edit any calibrations previously performed.

**Lock QC4000 at Full Size** - This title may be a bit confusing. When this is enabled, it will lock the QC4000 window at the same size as it is at the time you selected the lock function. For example, if the QC-4000 is only taking up half the screen and you enable this lock then, that will be the size it will be locked in. (That will be considered "Full Size") You will be able to move and size all windows within the QC-4000, but you will not be allowed to size the QC-4000 window itself.


### ***CNC I/O Test***

For Non-CNC systems, this is a footswitch test. This tells you if your footswitch is connected and working properly.

When the CNC I/O test button is pressed, the following screen appears.



Pressing on the footswitch, will change "Normal" to "Depressed," indicating that the incoming signal is working properly.




## ***Edge IQ Test***

This button is for engineering purposes only.

## ***Footswitch***

This is the Footswitch setup screen. Left clicking on the down arrow will allow you to map *Enter Point* or *Done Measurement* to your footswitch.




*Figure 9 - 8 FOOTSWITCH SETUP*

## ***Software Fence***

The function is for CNC option only. Please refer to the CNC insert for more information on Software Fence.

## ***Machine Zero***

Selecting this button will allow the user to choose all or one axes to establish a Machine Zero at Startup. After selecting the Axes, you must shutdown the QC-4000 in order to initiate the “Set Machine Zero” prompt.



Each time you power up the QC-4000, the following prompt will appear:

**“Goto your machine zero point  
for the X, Y axes and press OK.”**

**Note:** *If Reference Marks are enabled, you will be prompted to cross your X and Y Reference Marks.*




## ***Print***

*If all your settings work well, we recommend that you print them out and put them in a safe place for future reference. Once parameters are set, do not change them. Changing the parameters may cause severe degradation of your system.*

There are two different ways to print your settings. One method is to press the **Print** button in the Supervisor Setup screen. Not everyone is allowed to access the Supervisor Setup, so we recommend you try the second method.

### ***Second Method***

From the **F**ile menu, choose **A**bout. The following screen will appear. Please note that your software version, date and Installed Options may be different than the screen shown here.




Choose **V**iew Settings. A Windows Application (NOTEPAD) will appear with all the QC-4000 setup information. The QC-4000 will not recognize any changes made to these settings, so don't worry if you accidentally change something.

From the **F**ile menu choose the **P**rint Command. This will send all the information shown to a printer via the RS-232.



---

## *Chapter Ten*



### *Options*

**Option Overview**  
**Foot Switch**  
**Electronic Protractor**  
**Non-Linear Error Correction**  
**Optical Edge Detection**  
**Probe Offset**  
**Force Teach**  
**SPC**



QC-4000





## *Option Overview*

The QC-4000 may be equipped with the following options. These options are available at the time of purchase or any time afterward. The installation of some options for the QC-4000 systems may need to be returned to the factory for reconfiguration of the software and hardware. For additional information about many of these option, please refer to the Options Section.

*Not included in this section, will be additional information on the QC-CNC, VED2 and Auto Focus options. These options have manual inserts of their own and will be supplied with the purchase of that option.*

**TWO BUTTON FOOT SWITCH** - A two button foot switch that will reduce operator fatigue. The foot switch can be programmed it to "Enter a Point" or as a "Finish" button, available at the tap of a foot.

**ELECTRONIC PROTRACTOR** - The Electronic Protractor displays stage rotation via a Q axis on the QC-4000 screen. May also be configured for linear display for use with a height gage.

**NON-LINEAR ERROR CORRECTION** - NLEC is a program that automatically corrects for most non-linear measurement errors. Vibration or differential expansion error is not corrected by this program.

**OPTICAL EDGE DETECTOR** - Edge Detector senses changes of light intensity from the profile screen image and interprets the change as a light to dark or dark to light edge crossing.

**LIGHT CONTROL** - This programmable option allows control of an external light source. Up to 4 light control channels can be added.

## OPTIONS (CONTD.)

*WINDOWS® BASED SPC* - Affords internal process control, lets you generate histograms, X-bar, Range and Sigma charts, and other pertinent capability and process control data.

*VED2* - Accurate, repeatable video edge detection in color or monochrome for your video measuring machine, CMM or toolmakers microscope. User-defined tools, set by using our unique *Magic Wand®*. Tools include line buffer, nearest, farthest, average points, circle and arc buffer tools and Auto Focus.

*AUTO FOCUS* - Is a multi-pass video based system which analyzes image contrast. The focus location is determined by passing through focus and then comparing the contrast of video images from in-focus and out-of-focus. This system requires a motorized Z axis.

*PC-CNC* - "Hands-off" automatic part inspection for your QC-4000. High speed repetitive inspection will dramatically increase productivity, when coupled with optical or video edge detection. After first piece inspection, measurement function and stage movements are driven by the QC-4000's closed loop stage position system and take place automatically, without operator intervention or subjectivity.

*Q-CNC* - Although it's not an autofocus, the Q-CNC will drive your focal axis for measurements on different planes or allow you to do planar alignments on your part.

## Foot Switch

The one button foot switch allows the operator to utilize the QC-4000 without having to repeatedly press ENTER or OK. In other words, all point entries can be made with the tap of the foot, without ever having to look away from what you are doing.

The following steps describe how to set up the foot switch.

1. Attach the foot switch to the foot switch connector on the back of the QC-4000. (See figure 10-1.)




Figure 10 - 1

2. Select *Supervisor Setup* under the FILE menu.
3. Enter the Supervisor code. Press ENTER or left click on OK.

(The supervisor setup selections will now appear on the screen.)



4. Left click on the FOOT SWITCH button. The foot switch dialog box will appear.




Figure 10 - 2

5. Left click on the pull down menu to view the setting selections.




Figure 10 - 3

6. Left click the selection of your choice. Press OK to exit the Foot switch Setup, then OK to exit the supervisor setup.

**No meaning** = Not in use.

**Enter Point** = Enter Pt on measurement window.

**Done Measurement** = OK on the measurement window.

The foot switch is now ready to work for you, entering points or completing measurements at the tap of your foot.

## Electronic Protractor

The Electronic Protractor is an extremely useful option providing you have encoders installed on your system. If the system is configured as an optical comparator with a rotating screen, it becomes a rotary display. It can be used for a screen rotation indicator or a linear movement indicator on an appropriate gage.

A microscope is another configuration for the Electronic Protractor option. Here the Q Axis is used as a linear display to calculate the Z travel (simulating a height gage) plus having zeroing and information printing capabilities.

The Electronic Protractor displays stage rotations using the Q axis on the QC-4000's DRO. The Q axis is a 3rd axis in the QC-4000 which may be defined as either a linear or rotary display.

*NOTE: This axis is used for display purpose only and is not part of the feature reference frame.*

### SETTING THE Q AXIS ENCODER (LINEAR OR ROTARY)

1. Select *Supervisor Setup* under the **FILE** menu.
2. Enter the Supervisor Code. Press **ENTER** or left click on **OK**.
3. Left click on the **AXES** button.
4. Select scale type from Q axis pull down menu. (See figure below)





Figure 10 - 4

5. Select the Options button. The Encoder Options dialog box will appear. (See figure below)



The Encoder Options dialog box has a title bar "Encoder Options". It contains three rows for axis resolution settings:

- X Axis:** Resolution input field with "0.001", checked  mm, unchecked  Reverse, and unchecked  5x.
- Y Axis:** Resolution input field with "0.001", checked  mm, unchecked  Reverse, and unchecked  5x.
- Q Axis:** Resolution input field with "0.001", checked  mm, unchecked  Reverse, and unchecked  5x. Below this row is a **Teach** button and a checked  Angular Display option.


On the right side of the dialog are **OK** and **Cancel** buttons.

Figure 10 - 5

6. If you are using **Linear** encoder resolution, enter the resolution in the Q axis dialog box. Then, press OK.

For **Rotary Encoders** do the following:

- a) Left click on the TEACH button. The following screen appears:



The Rotary Encoder Setup dialog box has a title bar "Rotary Encoder Setup". It contains a text box with the following instructions:

To learn the resolution of a rotary axis place the number of degrees of rotation in the degrees box (usually 360). Align the encoder to a known location and press Start. Rotate the encoder thru the specified number of degrees and press End.

Below the text box are two input fields labeled **Counts** and **Per Degrees**, and a **Start** button.

On the right side of the dialog are **OK** and **Cancel** buttons.

Figure 10 - 6

- b) To teach the QC-4000 the Q axis resolution, enter the number of degrees of rotation in the degrees box (usually 360). Align the encoder to a known location and press Start. Rotate the encoder through the specified number of degrees and press End. The QC-4000 now knows the Q axis resolution.
- c) Press OK to exit all setup screens.

### ***Continue Reading***

The following pages will contain a quick overview of NLEC, SPC, VED, CNC and Edge Detector options. This will give you some idea on how they work and will help you along until the released version of the manual is published.

## *Non-Linear Error Correction*

### *The Theory*

NLEC is different from our standard linear error compensation. Linear error compensation is an incremental error compensation. With *linear error compensation*, if you move along the X or Y axis, the linear error compensation will add or subtract the appropriate correction factor for the distance traveled. This correction is applied linearly along the **full** travel of the axis. In contrast the NLEC allows you to have up to 30 different correction factors per axis each with its own linear correction for that segment.

NLEC works by dividing your optical comparator's area into a grid of up to 29 x 29 blocks. You choose the number and size of the grids. Each grid area has its own compensation factor built in and the QC-4000 remembers each factor. This optional feature allows you to electronically compensate for any inaccuracies that your optical comparator may have developed.

The electronic correction grid must be physically tied to the machine travel. For example, the correction for the lower left corner of travel is only valid for that corner. In order to realign this electronic grid with the physical travel of your machine, you must assign a landmark or "Reference Point" on the machine. This point is called **Machine 0,0**. Once NLEC is setup and enabled, the QC-4000 will automatically prompt the user to GOTO Machine 0,0 when the system is turned ON.

*NOTE: You must return to this same point and press ENTER every time you turn your system on.*

Please note the following:

- If a power failure should occur, the Machine 0,0 must be re-established.
- If you get an axis error while take a measurement, it means your NLEC has been corrupted. You **must** clear the error and start over at 0,0.

### ***NON-LINEAR ERROR CORRECTION***

This section is intended for those who have purchased the NLEC option. You may skip this section if you do not have NLEC. Your dealer will have electronically compensated your system when he/she installed your QC-4000. Therefore, this section is for informational purposes; however, you may use it to perform periodic realignments if necessary.

The NLEC feature is a software program that will automatically correct for most small linear measurement equipment errors such as axis squareness or straightness. Linear errors caused by vibration or differential thermal expansions are not corrected by this program.

As you know, optical comparators tend to need frequent adjustment to maintain their accuracy. To correct this problem, NLEC lets you map out the errors inherent in your comparator and remembers where these errors are located. Each time you pass through an error the QC-4000 automatically adds or subtracts the appropriate error factor.

The NLEC program must be provided with correction data in order to do its job. The following illustration shows a NLEC "Grid" as it might appear on a typical measuring stage.

	0,3	1,3	2,3	3,3	4,3
	0,2	1,2	2,2	3,2	4,2
	0,1	1,1	2,1	3,1	4,1
NLEC Grid ↗	0,0	1,0	2,0	3,0	4,0

↖ Machine 0,0

**Figure 10 - 7: NLEC Grid**

Each small rectangle is delineated by four "stations." The grid may be plotted for a maximum of 30 x 30 rows and columns. If there are 3 rows and 4 columns, as in the proceeding illustration, then there are 20 stations that must be qualified; that is, each station is a point which must be measured against a standard.

After NLEC setup is complete, the NLEC program corrects the DRO display by using a weighted average of the error at each of the four stations surrounding the current position.

### ***Setting up NLEC***

To properly set up NLEC, you should:

- \* *Make sure you have established a "Machine 0,0."*
- \*\* *Start a "New Session"*
- \*\*\* *Make sure that NLEC is NOT currently active.*

#### ***Establish a "Machine 0,0."***

To determine the grid location and station errors you **must** establish a Reference Point. This reference point (Machine 0,0) is a convenient, repeatable, known point by which the NLEC grid will be located.

- a. From the DATUM menu select "Set Machine Zero" (ALT D, M).  
A "Goto Machine zero" prompt will appear
- b. Place you crosshairs at the Extreme lower left corner of the stage movement (see the illustration), then press OK.

#### ***Start a "New Session."***

It is always a good idea to start a New Session when performing any calibration task. Don't worry, you won't lose your Machine 0,0.

- a. From the FILE menu, choose "**New Session.**" (ALT F, N).

***Make sure NLEC is not active***

If NLEC had been previously setup and is active, you must go into the setup screen and disable NLEC.

- a. Choose "**Supervisor Setup**" from the FILE menu. (ALT F, V)
- b. Enter the password.
- c. Left click on NLEC (TAB, E). The following screen will appear.

**Figure 10 - 8**

- d. Make sure the block next to NLEC On is blank; if not, left click on the block now.

***Align Grid***

The glass alignment grid must be "manually" aligned: with either the X or Y axis. Before actually performing setup, be sure that NLEC is turned off and then align the grid in its proper location as close as possible.

Once your grid is aligned, enter the number of grid points and block size and go to town. See next page.



### ***Setting Grid Size***

- a) Enter the number of grid points for the X and Y axis. (In this demonstration it will be 5 in the X axis and 4 in the Y.)
- b) Enter the Grid block size. (1 inch in X and Y)
- c) Left click on "Measure Grid..." (TAB, M)
- d) Click on OK in the Supervisor Setup screen

### ***Measuring the Grid***

When measuring a grid, you must have a 0,0 point. This is the lower left corner of the glass grid and is the first point that you calibrate when you are using the normal automatic calibration procedure. The NLEC 0,0 point must be in the "most negative" corner of the grid. "Most negative" means that if you move to the left and the distance displayed is decreasing, then your NLEC 0,0 will be near the side where you run out of grid in that direction.

*Note: Establishing an NLEC 0,0 can be accomplished at any time during this procedure. However, establishing your first point **as** the Zero will eliminate any chance of duplicating the same point.*

- a) Select **Z**ero from the DATUM menu.
- b) Position your crosshair at the most negative corner of the grid.
- c) Right click to enter a point or left click on Enter Point.
- d) Left click on OK. You have now taken the first point of Station 0,0 and set NLEC 0,0.
- e) Now select Measure Magic or Point measurement from the Toolbox. Double click for auto repeat mode.
- f) Position your crosshair at the next intersection point and take the next point.
- g) Select OK

- h) Continue to target all the intersection points on the grid. You must take the exact amount of points as indicated in your setup.

### ***Completing the Procedure***

Once all the points have been targeted, you must return to the Non-Linear Error Correction Setup display window. (See below)

The screenshot shows a dialog box titled "Non-Linear Error Correction Setup". It contains two input sections: "Number of Grid Points" with X=5 and Y=4, and "Grid Block Size" with X=1.0000 and Y=1.0000. A checkbox for "NLEC On" is checked. Buttons for "Measure Grid...", "Import From Feature List...", "OK", "Cancel", and "Edit..." are visible.

**Figure 10 - 9**

- Left click on "Import From Feature List..."
- Turn NLEC on by left clicking on the empty box.
- Choose OK to exit the Correction and Supervisor setups.

Non-Linear error correction is now complete. Choosing the Edit will show you the offset or station errors from the notepad. If a printer is installed, you may print a NLEC report by selecting "Print" from the FILE menu while in the notepad.

**Note:** It is a general recommendation NOT to change any numbers within the Edit screen. Use this only to view or print NLEC.

## ***Optical Edge Detection***

### ***Edge Detection Operation***

If you did not purchase the Edge Detector Option with your QC-4000, you may skip this section. It is included for the benefit of those who have purchased an Edge Detector.

This section gives you a brief explanation of how Optical Edge Detection works, explains how to hook up your edge detection to your QC-4000, and illustrates several examples of additional functionality the Edge Detector provides.

Before reading this section you should read Essential Information, The QC-4000 Demonstration, and, if necessary, the Reference Guide. Please refer to these sections when you need background information.

### ***About Edge Detection***

The QC-4000 may be purchased with an Optical Edge Detector which greatly enhances your comparator or other projection-based measuring machine. The Edge Detector senses changes in the comparator screen's brightness and interprets such a change as a profile edge crossing.

The QC-4000 can recognize both light-to-dark and dark-to-light edge crossings. Please note that the Edge Detector requires a consistent bright and a consistent dark and as such, will only perform well in the profile mode.

### ***What is Optical Edge Detection?***

Optical edge detection permits the QC-4000 to recognize different levels of intensity of light from your comparator's view screen. Therefore, the QC-4000 can determine exactly where you crossed a shadow on the comparator's screen.

### ***How Edge Detection Works***


Two fiber optic cables are attached from the QC-4000 to your comparator. One cable is for the Screen Sensor that is connected to the view screen and the other is for the Reference Sensor that points directly at the lamp.

The reference sensor automatically corrects for slight changes in light intensity and filters out the A.C. noise common in projection lamps.

The screen sensor measures the amount of light directly beneath it on the screen. The reference sensor provides a bright standard to measure the screen sensor against. The sensors are attached to the comparator using two fiber optic cables; the screen sensor connects to the viewing screen and the reference sensor points directly at the lamp.

### ***The Sensors***

After setting up your QC-4000 according to the Operator's Manual, examine the two black optic cables packaged with the QC-4000. Notice that one end of each cable contains a curved metal piece. This curved metal piece is the collecting end of the cable where the light from the screen or lamp enters the cable. The other end of the cable, the depositing end, plugs into your QC-4000.



**Figure 10 - 10**

### Connecting the Edge Detector to the QC-4000

When you order Edge Detection, you receive a separate shipping container that contains the Edge Box, an interface cable, 2 Fiber Optic Cables (2 meter for the Screen Sensor and 6 meter for the Reference Sensor) and of course, a power cord.

On the back of your QC-4000, you will have an Edge I/O Card that contains a 15pin connector (Edge) and a 44pin connector (Light Control). (See figure below)

\* **Edge Detector Interface Box**




Figure 10 - 11

\* **Edge Interface Cable [15pin (M) to 15pin (M) connector]**




Figure 10 - 12

\* **QC-4000 Edge Input/Output Card**




Figure 10 - 13

---

### ***Cautions about Fiber Optic Cables***

1. The Fiber Optic Cable is not a wire and cannot be bent smaller than a one inch radius without effecting its performance.
2. The cable has a maximum safe operating temperature of 100 degrees centigrade.

### ***Connecting the Screen Sensor***

1. On the front of the Edge Box, you will find two matching Photo Diodes. Securely attach the 2 meter fiber optic cable to one marked "SCREEN".
2. Enclosed with your edge box is a plastic ruler. The ruler is used to hold the screen sensor in place against the view screen. Make sure the hole in the plastic ruler is free of debris and your view screen is clean.
3. Place the plastic ruler under your comparator's chart clips so that the small hole in the ruler is located over an unobscured portion of your viewing screen.
4. If necessary, gently clean the collecting end of the screen sensor with a soft lint free cloth.
5. Place the tip of the screen sensor through the hole in the plastic ruler with the sensor's metal tip flush against the screen. Be careful not to scratch the view screen with the metal collecting tip.
6. Secure the optic cable to the ruler using the plastic stick-on clamp provided.

### ***Connecting the Reference Sensor***

The reference sensor must point directly at the comparator's lamp. One way would be to secure the sensor on the outside of the lamp housing facing inward. The other way is to place the sensor inside the lamp housing.

The second approach is recommended, but the first is acceptable. Both methods are presented following a description of the optic cable characteristics.

***Placing the Reference Sensor Outside the Lamp Housing.***

1. On the front of the Edge Box, you will find two matching Photo Diodes. Securely attach the 6 meter fiber optic cable to one marked "REFERENCE".
2. The trick is to secure the Reference Sensor tightly enough so that it cannot be moved by casually bumping the optic cables. There is no easy method to do this because each comparator is different. The Reference Sensor must point directly at the lamp and the excess optic cable must be kept out of the operator's way. Three methods we have used are:
  - 1) Using stainless steel hose clamps around the condenser lens housing to secure the cable
  - 2) Snaking the cable through the lamp housing and securing it with nylon cable ties.
  - 3) Drill 2 holes in the lamp housing and secure the optic cable to it using a metal tie pulled through the holes. This tie "hugs" the optic cable to the housing and point the sensor at the light source.

The optic cable must be secure, receive plenty of light, and stay relatively cool. Installing the cable so it receives cooling air from the lamp fan is a good idea since the cable maximum operating temperature is 100 degrees centigrade.

***Placing the Reference Sensor Inside the Lamp Housing.***

In many cases, it is easier to place the sensor cable inside the lamp housing but caution is required with respect to temperature. The same general restrictions apply, and the installation must provide a stable sample of the light source. This method provides a much cleaner installation because the cable is completely out of the way of the operator.

### ***Connecting the Edge Box to the QC-4000***

- \* On the back of the edge box you will find a 15pin connector marked "INTERFACE". Plug one end of the 15pin cable into the connector.
- \* Plug the other end of the cable to the 15pin connector located on the back of the QC-4000.
- \* Check the power switch and make sure that it is in the 0 (OFF) position.
- \* Insert one end of the power cord into the back of the edge box, and the other end into a **grounded** power strip or outlet.

### ***Continuing On***

This completes the basic Edge Detector installation. Be sure to check all your connections and then continue with the next section.

### ***Powering up the QC-4000 with Edge Detection***

- \* Before you power up the QC-4000, you must turn on your Edge Box by switching the power switch to the 1 (ON) position. When the QC-4000 powers up ("boots"), it executes a series of commands. One of the command functions performed, is to ensure that the edge is turned on and connected to the QC-4000.
- \* If the Edge is not detected the following error message will occur during power up:


<b>Edge Detector is not responding. Please exit the QC4000 and make sure all cables are connected and the power is on.</b>
--

### ***Checking the Light Source***

To insure accurate edge crossings, it is very important that the light source going into the edge detector is not too much or too little. (0 being not enough and 12 being too much). The best results are achieved when the numbers are between 3 and 8.



To check the light level, select **Light Level** under the PROBE menu.



**Figure 10 - 14**

If it is above 11 or below 1, check to make sure that the depositing end of the reference sensor cable is firmly connected to the lower optic connector on the back of the QC-4000. If the number is still out of range, perform the following steps:

- If the number is below 1, not enough light entering the cable. Adjust the cable so the collecting end is pointing more directly at the light source. Continue adjusting the cable until the number is between 3 and 8.
- If the number is 11 or more, too much light entering the optic cable. Turn the collecting end of the cable slightly away from the light source, so the number falls between 3 and 8.

You are now ready to calibrate the Edge Detector. This calibration is called **TEACH**.

*NOTE: TEACH should be repeated every time you turn on the QC-4000 and every time you change magnification.*

**To TEACH the light levels to the QC-4000:**

- Select TEACH from the Probe menu. The following prompt appears:

**Move the edge sensor into a DARK area on the screen and press OK.**

- Once this is done, a new prompt appears:

**Move the edge sensor to a LIGHT area on the screen and then press OK.**

The Edge Detector now knows the difference between the light and dark on you screen.

***Editing the Teach Command***

Double-clicking on the TEACH program step allows the user to enter in edge values manually. This is a convenience feature, and is typically used when you want the exact same edge values for more that one program.

Edge Calibration Data		
Screen Gain	<input type="text" value="5"/>	<input type="button" value="OK"/>
Reference Gain	<input type="text" value="5"/>	<input type="button" value="Cancel"/>
Clip Point	<input type="text" value="600"/>	
Clip Point Offset	<input type="text" value="167"/>	
Screen Offset	<input type="text" value="124"/>	

Figure 10 - 15

## Teach to Master

The Teach to Master Calibration, fine tunes your Edge Detector to properly read the “Fuzzy” non-distinct edges.

To perform a Teach to Master you must:

- a) Enter the size of your standard,
- b) Choose which axis you wish to calibrate,
- c) Perform a Teach so the edge detector knows the light levels, and
- d) Cross the edges on your standard.

This calibration procedure should be performed when the light source of the comparator is not well columned. For instance, if you change from measuring a very flat part with distinct sharp shadows to a part with fuzzy edges, you must perform a Teach to Master procedure. If you change from highly reflective parts to dark non-reflective parts or vice-versa, repeat the procedure.

You will need a sample part from those you are going to check. Position the part on the comparator so it is aligned with the comparator's axis. Carefully measure the part using the crosshair (you must know the part's exact dimension).

1. From the Probe menu choose Teach to Master. A screen will appear prompting the user to enter the standard and choose one axis to calibrate. (See below)

Calibrate To Master

Standard Size

Fill in the Standard Size field, and then align the known dimension of your standard with the X or Y axis. Press Cal. Using X or Cal. Using Y and measure the Calibrated distance.

Cal. Using X

Cal. Using Y

Cancel

Figure 10 - 16

2. Once the standard Size has been entered and a *Cal.* button selected, a new screen appears prompting the user to “Teach” the edge probe.
3. Follow the instructions in the message window and press OK.




Figure 10 - 17

4. Again, follow the instructions in the message window and press OK.
5. Once OK is pressed, another message appears prompting the user to *Prepare for first edge crossing*. In other words, position the edge sensor near but not over the first edge of the standard. This is to avoid any improper edge crossings. Press OK.




Figure 10 - 18

6. A new message window appears prompting the user to cross the sample part. If you selected "*Cal. Using X*," you must move the stage in the X axis direction only (right to left). If "*Cal. Using Y*" was selected, move the Y axis only.




Figure 10 - 19

7. Move the edge sensor across both edges of the sample part.




Figure 10 - 20

8. Once both edges are crossed, The "Calibrate To Master" screen appears. If the "Measured Size" is not exactly the same as the "Standard Size," or if an incorrect point was entered, left click on the Try Again button and cross the edges again.
9. Repeat steps 7 and 8 until the Standard and Measured Size numbers are identical.
10. Left click on the Acept button. The screen will disappear indicating the Teach To Master procedure is complete.

If you can not get the numbers to match, your target value is too far from the actual measurement. Perform a Teach and repeat the Teach to Master procedure.

## Other Edge Features

### Show Edge Detector

When the Show Edge Detector feature is enabled, you will see two (2) position indicators on your part view. A small green circle will appear along side the crosshair, indicating the edge sensor. When performing a Teach, Teach to Master or Probe Offset, this is the indicator that you will use to calibrate your edge.

Pictured below is a view of how your part view will appear when the Show Edge Detector feature is enabled (without the descriptive words of course).




Figure 10 - 21

#### To Enable the "Show Edge Detector":

1. Select Preferences from the FILE menu.
2. Select Part View from the Preferences screen.
3. Left Click on the *Show Edge Detector* box under the Position Indicator section.
4. Click on OK to exit the menus.

### Edit Edge Point Measurements

The QC-4000 makes it possible to edit a program and change the direction that the edge detector crosses the point.

Program View: A (Editing)	
00001	System Settings
00002	Teach...
00003	Probe Point "Point 1"...
s001	Probe Point (0.3150 , 0.4350 )...
s002	End Measure

Figure 10 - 22

Double-clicking on the points' substep will enable the Probe Edge Point screen. Use the arrows or enter the position change manually.




Figure 10 - 23

By adjusting the direction of the edge crossing, your part view can go:




Figure 10 - 24

**Note:** To view the edge path, you must choose **Show Path** from the Program menu.

### Probe Offset

The QC-4000 allows the user to switch back and forth between using either the crosshairs or the edge detector. But to do this, the QC-4000 must know how far apart the edge detector's screen sensor and the crosshairs are. This calibration must be done every time you move the edge detector's screen sensor or change magnification. It is called PROBE OFFSET.

*To set Probe Offset perform the following:*

- Select **Edit Calibration** from the PROBE menu. The Calibration dialog box will appear.

Figure 10 - 25

- If you know your probe offset in the X and Y location, type the numbers in, then press OK. But why not let the QC-4000 do the work for you.
- Left click on the LEARN button under the Probe Offset box. A circle measure prompt will appear, instructing the user to Probe a CIRCLE using the Edge Detector. (You may use any circle on the Quickie slide to perform this calibration.)
- Probe the circle using the Edge Detector and press OK.
- A new prompt will instruct you to probe the same circle, this time using the cross hairs.



- Probe the circle, then press OK.

The QC-4000 will now know the distance between the Edge Sensor and the cross hairs. This allows the user to switch back and forth between edge and cross hairs, and *still* obtain accurate measurements.

### ***Force Teach***


As mentioned previously, you will have to *remember* to do a TEACH each time you change calibrations or turn your system ON. The QC-4000 is so smart, that you can set it to do the remembering for you. This is called *Force Teach*.

#### ***To enable Force Teach, perform the following:***

- If you only have one calibration type listed, then select **Edit Calibration** from the PROBE menu.
- If more than one calibration type is listed, then select the calibration session you wish to change making sure that there is a check mark next to it, then choose **Edit Calibration**.

**NOTE:** If you wish to change calibration sessions, repeat the following steps for each one.

- Left click on the Options button in the calibration screen. The Options dialog box will appear.



**Figure 10 - 26**

- Left click on *Force Teach Yes*, then press OK.

Now every time you change calibrations, the prompts will appear to calibrate the edge detector.

# QC-4000 Light Control

This is an “option” that allows control of an external light source has been added. The Light Control menu command will be located under the Program, Special Steps menus. Up to 4 light sources may be configured into the QC-4000 and can be added at any time.




Figure 10 - 27

## The Toolbox

Configuring the toolbox with the light control features, is a fast and easy way to adjust your lighting.





Figure 10 - 28



Pressing  in the toolbox or selecting Light Control from “Special Steps” under the PROGRAM menu will introduce the light control channel screen.

**Lighting Control**

---

**Light Channel #1**

←

→

1

OK

Cancel

---

**Light Channel #2**


←



→

1

Adjust the lighting by dragging the box in the scroll bar or clicking on the appropriate arrow. This can also be used to insert a light control step into a program.

### *Light control Quick-Sliders*



Pressing buttons  through  will bring up the light control quick-slides.

To adjust the lighting from a quick-slide, click and hold down the left mouse button.

The only movement your mouse is capable of performing at this time is the up and down movement you must make to adjust the lighting. Once released, the quick-slide will disappear.

### *Programming with light control*

Light Control is a recordable program step. Click on light bulb in the toolbox or select it from the *Special Steps* in the PROGRAM menu. We suggest you record a light control step in the beginning of your program. This will allow the user to adjust lighting for the entire program at one time if necessary.

Program View: LIGHT (Recording)	
00001	System Settings
00002	Light Control (74, 135)...
00003	Probe Circle "Circle 1"...

Figure 10 - 29

Double-clicking on the Light Control step in a previously recorded program allows the user to re-adjust the lighting without "Recording Into" the program. After pressing the OK button, the numbers within the program will change.

Program View: LIGHT (Editing)	
00001	System Settings
00002	Light Control (124, 135)...
00003	Probe Circle "Circle 1"...

Figure 10 - 30

**Note:** Although programmable, Quick-sliders will not be inserted into a program step until another step is recorded (usually a measurement step).

# *SPC*

## *Statistical Process Control*

SPC - is an extremely powerful analysis tool. However, it has added capabilities made possible by the Windows environment. For instance, up to 120 different variables, attributes or Pareto classification can be analyzed in a single data file in SPC.

One of the features found with SPC is the ability to view charts and data on the same screen. This allows you to see changes on the control chart when changes are made in your analysis options or your data file.

SPC give you simple, uncluttered menu selections.

Current analysis options Include:

- X Bar and R
- X Bar and Sigma
- Individuals Chart
- Histograms with Capability Analysis
- Pareto Analysis
- P Chart
- U Chart
- Np Chart
- C Chart
- CuSum Chart
- Multi-variate Analysis
- Moving Average Range & Sigma

The SPC option is a modified version of SPC-IV by Quality America , a popular Windows based Statistical package. By using the SPC-LINK command the QC-4000 uses D.D.E. (Dynamic Data Exchange) to automatically transfer data into a data base.

The chart portion of the SPC then uses this data base to calculate and draw the statistical graphs. This gives you the advantage of running Real Time, On-Line SPC. The SPC-Link commands may also be included in a part program to be transparent to the operator. The flexibility of Windows also enables you to resize the QC-4000 and have your SPC chart on screen and updating every time you add data.

### ***SPC DEMONSTRATION***

By now you should be comfortable with using windows so we won't get into a click by click (or step by step) routine.

The first thing we need to do is set up an application to accept the data coming from the QC-4000.

#### To do this:

- Double-click on the SPC-PC IV window to start the SPCWIN program
- Then from the **F**ile menu open a **N**ew database. A "Create New Data Set" window will open listing the available layouts.
- Choose *Standard Variables*, then choose **C**reate Data Set.






Figure 10 - 31

You should now have an empty data base in the SPC window.



- Select the DATA1 column.
- Choose **Column Format** from the **Edit** menu.
- Change the **Title** to RADIUS.
- Set the *Column Type* to **Numeric**, the *Width* to **8**, with *4 Decimal Places*, and the *Sub-group Size* to **3**.
- Choose **OK** or press Enter.
- Save this Data Set as BIGCIR.QDB. (You can also use any other D Base compatible extension EXAMPLE:BIGCIR.DBF).




You have now created a data base to collect data from the QC-4000. At this point you may close the data base, but SPC-PC IV must remain running to interface with the QC-4000.

### ***Performing the SPC Link***

We are now ready to start measuring with the QC-4000 and Linking our data to the SPC application.

- Open the Demo Stage and start the QC-4000.
- Measure the big circle on the Demo Stage. (See figure below)



**Figure 10 - 23**

- From the QC-4000 **File** menu and choose **SPC Link...**

The first time you activate the SPC Link an **SPC Link Options** window will appear. See figure below.

- The **Application Name** for this SPC software must be **SPCWIN**.
- For the file name enter BIGCIR.QDB (the same name we used for the data base).
- Choose **OK** or press Enter.

SPC Link Options		
Application Name	<input type="text" value="SPCWIN"/>	<input type="button" value="OK"/>
File Name	<input type="text" value="BIGCIR.QDB"/>	<input type="button" value="Cancel"/>

**Figure 10 - 24**



If your SPC application has been setup properly you will now have an **SPC Link** window.

- For the **Feature Coefficient** select **RADIUS** from the pull down list of available coefficients. *This is the data we want to send to the SPC application.*
- For the **File Column** select **RADIUS**, then press **OK**.. *This is the name we gave to the DATA1 column in SPCWIN.*

The image shows a dialog box titled "SPC Link". It has three input fields on the left: "Feature Coefficient" with a dropdown menu showing "X", "File Column" with a dropdown menu showing "RADIUS", and "Row" with an empty text box. To the right of these fields are three buttons: "OK", "Cancel", and "Options...".

Figure 10 - 25

*When you choose OK, the radius of the circle that you measured on the Demo stage will be automatically sent to the SPC application.*

- Measure the same circle again and repeat the SPC Link Command until you have a sufficiently large sample of data to calculate an SPC chart. *(In this example the circle was measured 36 times. You can do it with less, but the more samples you have the more realistic the results.)*

Now we can go to the SPC application and create an SPC chart. You can close the QC-4000 and the Demo Stage. For the rest of this demonstration they won't be needed.

### Creating the SPC Chart

- Go to the SPC application.

If you had closed the data base you'll notice that the SPC Link opened it up again. Your application should look something like the picture below.

- Move the cursor to the first line in the DATE column and press the left mouse button to select this space.
- Now press CTRL D and the date will be automatically filled in. Now do the same for the TIME but press CTRL T.

BIGCIR.DBF			
DATE	TIME	RADIUS	DATA2
09/01/92	11.25	0.1486	
		0.1497	
		0.1481	
		0.1521	
		0.1492	
09/05/92	2.15	0.1478	
		0.1505	
		0.1486	
		0.1506	
		0.1495	
09/15/92	8.30	0.1511	
		0.1504	
		0.1489	
		0.1475	

Line 35, Group 12

Figure 10 - 26

The SPC application is capable of calculating many different charts. For this example we will do the X-Bar & R Chart. For other charts and analysis refer to your SPC manual.

- In your SPC data base, highlight the RADIUS column.
- Select **X-Bar & R** from the **Chart** Menu. A window will open, prompting you for the **Variable** name, **Sub-group** size, **Group Range**, **Use Nominal Col**, **Chart Output**, and type of analysis.
- If everything was set up properly, the window will look like figure 10-27. If you have something different, change it to match figure 10-27.
- Then select **OK** or press Enter.

**X-bar R Chart: BIGCIR.DBF**

Variable:

Sub-group size:

Group Range

All

Range(s):

Chart Output

Summary

Screen

Printer or File

Detailed (Printer or File)

Statistics

Advanced Chart

Use Nominals Col:

Figure 10 - 27

You should now have a **Process Capability Options** window like figure 10-28. The values you get may be different but don't change them yet. These are the defaults for the values in the data base and the type of analysis you chose. Once you've succeeded in producing an SPC chart you can come back to this window and change the values to see what effect it has on your chart. For now just select **OK** or press Enter.

**Process Capability Options**

± sigma for capability indices:  (1.00 - 9.99)

Number of cells:  (3 - 20)

Low cell boundary:  < 0.1464

Cell size:

Figure 10 - 28

Well, if everything went according to plan you should now have a chart similar to the one in figure 10-29. Don't worry if the curve or graph looks drastically different then the example. Your results will only be the same if your values just happen to match the ones used for the demonstration.

Now it's time to go back and play with the other types of charts. Be brave and experiment a little, change some values and recalculate the charts. And don't be afraid to pick up the SPC manual. It's full of useful information about SPC.

*To see all of the output clearly, it may help to click on the maximize button when viewing SPC charts.*




Figure 10 - 29

This concludes the demonstration of the SPC option of the QC-4000. For further information about SPC refer to your SPC manual.

# Chapter Eleven

QC-4000 Report Wizard : c:\qc4000\default						
File Edit						
Feature	# Pts	Units	Position	Dimension	Form	
Point NT	#pts	unit	X/R = ACTUAL			
Type			Y/A = ACTUAL			
Pt. Circ	#pts	unit	X/R = ACTUAL			
Type			Y/A = ACTUAL			
Pt. TP	#pts	unit	X/R = ACTUAL			
Type			Y/A = ACTUAL			
Line NT	#pts	unit	X/R = ACTUAL	< = ACTUAL	Az =	+T
Type			Y/A = ACTUAL		Az =	-T
Line < Tol	#pts	unit	X/R = ACTUAL	< = ACTUAL	Az =	+T
Type			Y/A = ACTUAL		Az =	-T
Line Form	#pts	unit	X/R = ACTUAL	< = ACTUAL	Az =	+T
Type			Y/A = ACTUAL		Az =	-T
Line OrLen	#pts	unit	X/R = ACTUAL	< = ACTUAL		
Type			Y/A = ACTUAL			

## REPORT WIZARD

What Is It?  
 Creating A Form  
 Editing the Header  
 Writing To An ASCII File  
 Menu Explanations



QC-4000



# ***REPORT WIZARD***

## ***WHAT IS IT?***

The Report Wizard is a powerful tool that has two primary purposes. Primarily the report wizard is used to customize the print out of measurement information. Think of the Report Wizard as a template maker. It simply allows you to create a printout in any format that you need. By using the Report Wizard you can customize the print out to your exact requirements. Whether you need a special printout to conform to your ISO 9000 specification or providing documentation to your customers, the Report Wizard is the solution.

The other purpose of the report generator is to allow you to send data directly from the QC-4000 to an ASCII file. This enables you to store massive amounts of data in a file.

Another benefit is the ability to send data to a Statistical Process Control (SPC) program that you may already have in use at your facility.

## ***How easy is it to use?***

As with many new concepts, it can be very confusing to the first time user. But with a little practice, you will become a Whiz at making new forms.

The Report Wizard template is similar to what you would find in a spread sheet. You can size it, add columns, add a custom header, format the data, output to files or a feature column. If you are familiar with windows, then you know the basics of drop down menus. These work the same way except that the menus displayed and the selections in them will vary depending on the feature type selected in the feature column.

When you select a cell, you are really choosing a feature type from the feature column such as Point NT (non-toleranced points), Circle TP (circles with true position tolerance), etc. Depending on the feature type selected, the data available from the drop down menus will apply only to that feature type. The order that the feature appear in the feature column is arbitrary and has no affect on printing. The order of printing is determined by the order in which features appear in the feature list and only the selected features will be printed.

---

## ***PRINTING FEATURES***

There are two ways a feature printout can be generated. The first is the "*Print Selected Features*" function located under the **FILE** menu. The second is *Report Wizard*.

Before we get started with the Report Wizard, it is very important to understand the differences between "*Print Selected Features*" and *Report Wizard*.

- *Print Selected Features* allows you to print one feature at a time without form feeding.
- When printing with the *Report Wizard*, one feature is also one page.
- Unlike the Report Wizard, the Print Selected Features printout format is a fixed format and cannot be customized. (Except the Header).
- *Print Selected Features* format does not include an automatic form feed. It must be performed manually (on the printer) or by selecting the Form Feed button from the report header screen.
- With *Report Wizard* you can select "Pre" or "Post" Form feed to be performed automatically.
- Normally, an Epson or Epson compatible printer is used with the Print Selected Feature format. If you try to print this format on a laser printer you may get garbage at the end of your printout.
- The Report Wizard is capable for printing to a *File, Printer or clipboard*. You can use any printer that is compatible with you Windows setup. Please refer to your Windows manual to set up your printer.

## ***REPORT***

The other method of generating a printout the Report function. Choosing **Report** under the **File** menu will gain you access to the *Report Wizard*.

The QC-4000 is equipped with two Default templates. One for normal feature printouts called **Default.rpt**, and the other for toleranced features called **Tol.rpt**. These forms contain the most commonly used feature coefficients.

Selecting the **Edit Form** command allows you to make changes in a previously created form, and use the **Save Form As** command to create a whole new form.

Let's get into the fun stuff and try to print using the default form. We will assume your printer is properly setup and tested.

- ◆ Measure and select several features.
- ◆ Now choose **Report** from the **File** menu a dialog box will appear.

The screenshot shows a dialog box titled "Report". It has a standard Windows-style title bar with a close button. The main content area is divided into several sections:


- Report Form:** A sub-section containing a text field labeled "Name" with the value "DEFAULT". To the right of this field is an "Ok" button. Below the text field are two buttons: "Browse..." and "Edit Form...". To the right of these two buttons is a "Cancel" button.
- Output Device:** A sub-section containing three radio buttons: "Printer", "File" (which is selected), and "Clipboard".
- Checkboxes:** At the bottom of the dialog, there are three checkboxes: "Pre Form Feed", "Post Form Feed", and "Toleranced Features Only". All three are currently unchecked.

*Figure 11 - 1 Report Setup Screen*



**Browse**

The browse button will prompt the "File Open" screen. This is where you would select previously created reports by clicking on the report you wish to open, then press OK. Since we haven't created any reports yet, the only file you will see, is the default files.



*Figure 11 - 2 File Open Screen*

**Edit Form**

Choosing this will open the form that appears in the Report Form Name box. The last form that was created will always be the one to appear in this box. When you open **Report** for the first time however, "default" will appear in the Name box.

You can also choose the **Browse** button to select a different form.

**Printer**

Sends information to printer via your printer port. Your printer is set up through WINDOWS, not though the QC-4000.

**File**

Sends information to a specified file. Please refer to "Writing to an ASCII File" section later in this manual.

**Clipboard**

Sends information to a Clipboard, used to transfer data between the QC-4000 and other WINDOWS applications. (EXAMPLE: WORD FOR WINDOWS)

***Pre Form Feed***

Will issue a for feed before the report prints

***Post Form Feed***

Will issue a form feed after the report prints.

***Toleranced Features Only***

Selecting this will print only features that are toleranced; even when non-toleranced features are selected.

- ◆ For our demonstration please check off **Printer** and **Pre Form Feed**.
- ◆ Press **OK**.
- ◆ You have now printed out your first report.

*If the Report did not print:*

- ◆ *Make sure that you have selected features in the feature list or part view.*
- ◆ *Check you printer setup. Try to print with another application such as NotePad.*

QC-4000 Report Wizard : c:\qc4000\default						
Feature	# Pts	Units	Position	Dimension	Form	
Point NT Type	#pts	unit	X/R = ACTUAL Y/A = ACTUAL			
Pt. Circ Type	#pcs	unit	X/R = ACTUAL Y/A = ACTUAL			
Pt. TP Type	#pcs	unit	X/R = ACTUAL Y/A = ACTUAL			
Line NT Type	#pts	unit	X/R = ACTUAL Y/A = ACTUAL	< = ACTUAL	Az =	+T -T
Line < Tol Type	#pts	unit	X/R = ACTUAL Y/A = ACTUAL	< = ACTUAL	Az =	+T -T
Line Form Type	#pts	unit	X/R = ACTUAL Y/A = ACTUAL	< = ACTUAL	Az =	+T -T
Line Orien Type	#pcs	unit	X/R = ACTUAL Y/A = ACTUAL	< = ACTUAL		

*Figure 11 - 3 Report Wizard Default Template*

## ***CREATING A FORM***

OK, so you don't like the default form. You need to have more information or you may want Nominals followed by Actuals and Deviations while others may want Deviation first followed by Actuals then Nominals.

With Report Wizard, you have complete control of the layout of your report. Create your own form to suit your needs.

The following information will walk you through opening, creating, saving and printing a new form. For this demonstration we will be printing to a printer. Make sure you have setup and tested your printer.

1. From the **F**ile menu choose **R**eport. The Report setup screen will appear. For this demonstration, choose **P**rinter and **P**ost **F**orm **F**eed.
2. Now click on **E**dit **F**orm. The default form (or the last form that was created), will appear.
3. From the **F**ile menu, choose **N**ew **F**orm. A template will appear and is the starting point for creating your custom form.

Feature	Column 2
Point NT	
Pt. Cart	
Pt. TP	
Line NT	
Line < Tol	
Line Form	
Line Orien	
Circle NT	
Cir Cart	
Cir TP	

*Figure 11 - 4 Untitled Template*

In the first column (Feature) you will see all of the possible feature types and tolerancing conditions that can be applied. The feature column will appear as you see it, every time you select "**New Form**".

This column is use to select which types of features you want to appear in the report. You can also customize this column as any other by highlighting a specific feature or the whole column.

As the report is generated, the feature column will automatically print the feature types you have selected from the feature list. Features that are not contained in the feature list will *not* print on the report.


To the right of the feature type list, you will see abbreviations for the different tolerance types. The following information will list what the abbreviations stand for.

- NT = No Tolerance
- Cart = Cartesian Tolerance
- TP = True Position Tolerance
- <Tol = Angle Tolerance of a Line
- Form = Form Tolerance
- Orien = Orientation Tolerance
- Runout = Runout Tolerance
- XY = X and Y tolerance for a Distance.
- L = Length Tolerance on a Distance.

To the right side of the report, you will notice a RED dotted line. This line indicates the page width. If any portion of your report extends beyond that line, it will not print out.

To the bottom of the report, you will see a status bar indicating the Version number of the Report Wizard as well as the page size. (See figure 5).

The page size status bar is also your printer indicator. Since this feature is linked to the Microsoft print manager, clicking on it will allow you to change orientation and size of the paper just as if you were to select PRINT.



*Figure 11 - 5*

For a practice round, let's create a form that must have Actuals, Nominals, deviation and a pass /fail indication.

4. To begin, move your cursor in the box containing the words COLUMN 2 and press the left mouse key. This will select the entire column (and turn it a nice shade of blue) and bring up several new menu items. At this time we can choose the information that we want to appear. (See Figure 6)




Figure 11 - 6

5. The first thing we want to do is properly name the column. To do this select **Column Header** from the **Edit** menu.
6. A dialog box will pop up and the words COLUMN 2 will be highlighted. Press the back space key to erase (See figure 7).




Figure 11 - 7

7. Using the keyboard, type in NOMINALS and press OK. You can see that the second column has now been renamed.

*In the NOMINALS column, we want to see the X, Y and diameter nominals.*

8. From the **Position** menu select **Nominals**, a new fly out menu will appear.

9. Select **X** from the menu. As you can see, tolerancing can be applied to any X value that is marked with X NOMINAL.

Part of the word nominal may be obstructed because the column is not wide enough. To make the column wider, move the cursor to the right hand edge of the NOMINALS column on the template. As you can see the cursor now changes into a bi-directional arrow. When you see the bi-directional arrow, hold down the left mouse button and drag the cursor to the right. Do this until all entire word NOMINAL is displayed.

10. From the **Position** menu, select **Nominals**, and then **Y**. Be sure the column is still selected!

*Please note that numbers will not appear while creating a form. We are laying out the template. For our example we also want diameter values.*

11. To set up for Diameter nominals, select **Size** (Vs position as diameters have size) then **Nominals** and then **d** (for diameter).

At this point your template should have two columns one with FEATURE and the next with NOMINAL. If you don't please reread this section of the manual and try again.

Now we want to set up the ACTUALS column. Please be sure the nominals column is still selected (blue).

12. From the **Edit** menu, select **New Column**. A new column to the right of the selected column called COLUMN 3 will appear.
13. Select Column 3 by moving the cursor to the box containing the words COLUMN 3 and press the left mouse. That column will turn blue.
14. Name Column 3 by selecting **Column Header** under the **Edit** menu. Using the keyboard, type in ACTUALS then hit OK.
15. Now select **Position**, then **Actual**, then **X**. Do the same for **Y**.
16. Now select **Size**, then **Actuals**, then **d** for diameter.

Your template is now starting to take shape. You may need to widen this column as you did with the nominals column. Now it is time to set up the deviation column.

17. First, be sure that the ACTUALS column is selected (blue). From the **E**dit menu, select **N**ew Column, then select column 4. From the **E**dit menu select **C**olumn **H**eader and type in DEVIATION.
  18. Now select the **P**osition menu then **D**eviation, then **X**. Now do the same for **Y**.
  19. Now select the **S**ize menu, then **D**eviation, then **d**.
- To finish out our template, we must add in the PASS/FAIL column. Be sure that the Deviation Column is selected (blue).*
20. From the **E**dit menu, select **N**ew Column. Select and rename this column PASS/FAIL.
  21. Now select **P**osition, then **Pass/Fail** then **X** ; do the same for **Y**.
  22. Now select the **S**ize menu item, then **Pass/Fail**, then **d** for diameter.
- Your template should look like the following form. (See Figure 8).

QC-4000 Report Wizard : c:\qc4000\test				
File Edit				
Feature	NOMINALS	ACTUALS	DEVIATION	PASS/FAIL
Point NT		X = ACTUAL Y = ACTUAL		
Pt. Cart	X = NOMINAL Y = NOMINAL	X = ACTUAL Y = ACTUAL	X = DEVIATION Y = DEVIATION	X = P/F Y = P/F
Pt. TP	X = NOMINAL Y = NOMINAL	X = ACTUAL Y = ACTUAL		
Line NT		X = ACTUAL Y = ACTUAL		
Line < Tol		X = ACTUAL Y = ACTUAL		
Line Form		X = ACTUAL Y = ACTUAL		

*Figure 11 - 8*

## *Editing the Header*

Now that you have created the template, you can edit the Header information for the printout, this will include information such as customer name, address, etc. Do not confuse this Header with the Print Selected Features Header. Although they may look alike, they are two different screens.

- ◆ Select **Edit Header** the **File** menu of the **Report Wizard**. A dialog box will appear with a series of fields that can be customized to fit your company's requirements. Using the keyboard, enter the applicable information. If you do not wish a certain field to print, simply disable it by clicking on the appropriate field (leaving the box blank).
- ◆ Press okay to get out of the Edit Header page.

The screenshot shows a dialog box titled "Report Header". It is divided into three main sections:

- Fields:** A list of fields with checkboxes. All checkboxes are checked:  Company,  Date,  Time,  Job,  Part, and  Operator.
- ID:** Three input fields labeled "Job:", "Part:", and "Operator:".
- Company:** Two input fields labeled "Name:" and "Address:". The "Address:" field is represented by three stacked input boxes.

On the right side of the dialog, there are two buttons: "OK" and "Cancel".

*Figure 11 - 9 Report Header Screen*



## Preferences

The Preferences Screen located under the **File** menu in a Report allows you to further customize you report.

The image shows a 'Preferences' dialog box with the following options:

- Print Gridlines
- Print Header
- Header On Each Page
- Print Column Headings
- Numbers Only

Below these options is a 'Delimiter' sub-dialog with the following radio button options:

- Comma
- Space
- Tab
- Custom

Buttons for 'OK' and 'Cancel' are located on the right side of the dialog.

Figure 11 - 10

### ***Print Gridlines***

The default for *Print Gridlines* is *enabled*. Disabling this feature will print the Report without the separations between the columns.

### ***Print Header***

Enabling *Print Header* will print the header information on the first page of the printed report.

### ***Header On Each Page***

Selecting this function will print the header information on each page of the printed report.

### ***Print Column Headings***

Disabling this feature will remove the Column titles from the printed report.

### *Numbers Only*

There are some interactive programs that will only accept raw data. The Report Wizard gives the user the option to turn off all words and just print the numbers on the report.

**For example**, the information under the Position Column normally appears as:

X = 1.2345.  
Y = 6.7891

With *Numbers Only* enabled the data would appear as:

1.2345  
6.7891

Now that we have finished creating and customizing a new template, you'll want to save it.

### **To save the form you have just created:**

- Select **S**ave **F**orm the **F**ile menu. A dialog box will appear with a message "File Name" follow by a blank field with .RPT.
- Hit the backspace Key and type in TEST then, select the OK button (The QC-4000 will automatically put the extension .RPT at the end of the file name "TEST").




Figure 11 - 11

Congratulations, you have just completed your first Report Wizard Form! To check this form and view the results, measure several features including a circle with tolerance information.

Now select all of these features from the feature list or part view. From the **F**ile menu of the QC-4000 and select **R**eport. The QC-4000 will default to the last form you saved and in the report name file it should say test; this is the form we just created. Press OK and the measurement data will be printed out in the format we specified.

**Note:** If TEST does not appear in the "Report Form" name box, choose **B**rowse and select the form name from the list, then press OK.

Obviously this was a very simple form that we just created; however, we have learned a lot about the power of the Report Wizard. You now have the basic understanding to create your own customized report form. The Report Wizard is very flexible and you should go ahead and experiment to get the desired form you require.

### ***Report Summary***

- You can create a series of different report forms that can be used and stored.
- To select a different report form from the list of report forms, select the **B**rowse button. This will bring up a list of the various reports you have created.
- Simply select the report form you desire and that format will now be used to print reports until you change to another report form.
- Use a previously created form to create a whole new form by selecting **E**dit Form then **S**ave Form **A**s.


## ***WRITING TO AN ASCII FILE***

For many of you, the ability to write to an ASCII file will allow you to communicate to a Statistical Process Control (SPC) package that you may already have in house.

To demonstrate this capability we must first create a new report form. For our example we want to send the *feature name*, the *actual X coordinate*, and the *actual Y coordinate* with *commas* between the three fields.

1. First select **R**eport from the **F**ile menu of the QC-4000.
2. Select **E**dit **F**orm from the Report window.
3. From the **F**ile menu, select **N**ew **F**orm.
4. Select the second column by clicking in it.
5. Now go to the **P**osition menu and select **A**ctual and then **X**.
6. Now go to the **E**dit menu again and select **N**ew **C**olumn which will create column 3.
7. Select **P**osition, **A**ctual then **Y**.
8. From the **F**ile menu of Report Wizard, select **P**references.

The Delimiter will allow you to put space, commas, tabs, or special ASCII commands after each field. (See figure 12).



*Figure 11 - 12*

9. For our demo, select *Comma*, then press **OK**.
10. Now go to the **F**ile menu of the report wizard and select **S**ave **F**orm **A**s.
11. Using the keyboard, type **TEST** then press **OK**.
12. Go to the **F**ile menu and select **E**xit.

You are now back at the Report window and we are ready to send data to an ASCII file. First be sure that you have several features selected. You may have to exit REPORT to do so and select Report from the File menu again. The Report Form should currently be TEST. If not go to Browse and select TEST. RPT. (Please note that all forms are give the extension .RPT.)

13. Now from the *Output Device* area, select **File** as we are exporting to a file.
14. Now press **OK** and the *File Open* window will pop up.




Figure 11 - 13

The **Filename** will always be saved as a TEXT file. You can view your files by opening NOTEPAD in Windows.

In figure 13 you will see a column called "File Actions". There are four choices that can be made pertaining to how the data should be added to the ASCII file. They are:

### ***Append***

This will allow you to continuously add information onto the same file. All information can be viewed a one time. EXAMPLE: If the file contains ten features and you send five more you will have a total of 15 features in the file.

***Auto Number***

Every time you send a report, a new file will be created and will consecutively number the files using the same initial file name.

**EXAMPLE** Filename is **file.txt**

1st file will be saved as **c:\QC4000\file 000.txt**


2nd file will be saved as **c:\QC4000\file\_001.txt**

***Overwrite Always***

Selecting this will overwrite a file with the same name. Caution should always be used when selecting the Overwrite Always command; important information could be lost. example: If you have ten features in the file and you send five more features, the ten original features will be purged (lost) and only the five most recent features will be present.

***Warn On Overwrite***

When OK is pressed, a warning prompt appears asking the user "Overwrite File? Press Yes to overwrite the file. Pressing No will exit the report and return to the QC-4000 (See figure 14)



*Figure 11 - 14*

15. For our example select **APPEND**.
16. Type ASCITEST.TXT in the File Name box, then press the OK button. You have just created a file called ASCITEST.TXT and the data from the selected features will now be in that file in the format that we created.

All text files can be view through NOTEPAD, which is a Windows application. The notepad is located in the ACCESSORIES Window.

- a) First minimize the QC-4000 and open the "Accessories" window located in the Program Manager.
- b) Now OPEN the NOTEPAD application by double-clicking on the notepad icon.

- c) Select **O**pen from the **F**ile menu. Now this will get a little tricky.
- d) Our file ASCITEST.TXT was stored in the QC-4000 directory, so we must select that directory first. To do this:
- e) From the **Directories:** List, Double click on the FOLDER marked **c:\**

EXAMPLE:




Figure 11 - 15

- f) Now scroll down until you see QC4000.
- g) Double click on that item and a list of TXT files in the QC-4000 will appear.

EXAMPLE:





Figure 11 - 16

- h) Double click on the file ASCITEST.TXT and the feature name and X and Y values of the features selected will now be present in the file. (See figure 16).



*Figure 11 - 17 Notepad Text File*

Notice that the data is separated by Comma's. Remember that we chose the comma as our DELIMITER in the **Preference** screen.

<b>Delimiter</b>	
<input type="radio"/> <u>C</u> omma	<input type="radio"/> <u>S</u> pace
<input type="radio"/> <u>T</u> ab	<input checked="" type="radio"/> <u>C</u> ustom
ASCII	<input type="text"/>

Let's take a look at the Delimiter. A delimiter is used to separate the data when outputting to a file. Files are sent and received as ASCII characters. For your convenience, the QC-4000 Preference screen contains the

most commonly used delimiters. (i.e. Comma, Space and Tab). If we were to look at a side by side view of a Report Printout and a Notepad file, you would see that the comma makes the separation of each column without empty spaces. The purpose of a delimiter is to save space within a file. If none were present, files be filled with useless spaces.

When Custom is selected, an ASCII block will appear allowing you to enter your own ASCII Character. Since comma, space and tab are selectable items, you will not need to enter these as ASCII codes.

*Note: When **File** is selected as your output, do **not** attempt to write to an open file. The file must be closed for information to be sent.*

For quick reference, the following page contains a list of some common ASCII codes.



## ASCII CODES

8	backspace	46	.	84	T
9	horiz. tab	47	/	85	U
10	line feed	48	0	86	V
11	vert. tab	49	1	87	W
12	form feed	50	2	88	X
13	carr. ret.	51	3	89	Y
14	so	52	4	90	Z
15	si	53	5	91	[
16	dle	54	6	92	\
17	dcl	55	7	93	]
18	dc2	56	8	94	^
19	dc3	57	9	95	~
20	dc4	58	:	96	`
21	nak	59	;	97	a
22	syn	60	<	98	b
23	etb	61	=	99	c
24	can	62	>	100	d
25	em	63	?	101	e
26	sub	64	@	102	f
27	esc	65	A	103	g
28	fs	66	B	104	h
29	gs	67	C	105	i
30	rs	68	D	106	j
31	us	69	E	107	k
32	space	70	F	108	l
33	!	71	G	109	m
34	"	72	H	110	n
35	#	73	I	111	o
36	\$	74	J	112	p
37	%	75	K	113	q
38	&	76	L	114	r
39	'	77	M	115	s
40	(	78	N	116	t
41	)	79	O	117	u
42	*	80	P	118	v
43	+	81	Q	119	w
44	,	82	R	120	x
45	-	83	S	121	y
				122	z

## ***MENU EXPLANATIONS***

### **FILE**

<b><u>N</u>ew Form</b>	Allows you to create a new form.
<b><u>O</u>pen Form</b>	Opens a previously create form.
<b><u>S</u>ave Form</b>	Saves changes to an open form.
<b>Save Form <u>A</u>s</b>	Allows you to name and save a created form. Also allows you to create a new form by editing a previously created form.
<b><u>E</u>dit Header</b>	Add information such as company, part number etc. to a form.
<b><u>P</u>references</b>	Allows the following customization:
<i>Print Grid Lines</i>	Prints the form boundary lines.
<i>Print Header</i>	Prints the header with each report.
<i>Header On Each Page</i>	Prints header on each page of a report.
<i>Print Column Headings</i>	Prints the column titles.
<i>Delimiter</i>	Will put the checked item between each field. (Coma, Space, Tab or Custom)
<i>Custom ASCII</i>	When "Custom" (Delimiter) is selected, another box will appear. This allows you to put custom ASCII commands between each field. Example 13 will give a carriage return. (Refer to ASCII chart on previous page.)
<b><u>E</u>xit</b>	Exits the form and returns to the QC-4000 after asking you to "Save the Current Form".

**EDIT**

<b><u>C</u>ut</b>	Cut a selected block of information from the form.
<b><u>C</u>opy</b>	Copy a selected block of information from the form
<b><u>P</u>aste</b>	Apply information that has been cut or copied to another part of the form.
<b><u>D</u>elete</b>	Deletes the selected item or column information from the form.
<b><u>N</u>ew Column</b>	Places a new column on the form.
<b>Column <u>H</u>ead</b>	Allows you to rename the selected header.
<b><u>F</u>ont Size</b>	Change the font size of the form. (8,10,12)

- When a column is selected, the following menus will appear.

**GENERAL**

<b>Feature Type</b>	Will place the type of feature in the selected block of the form.
<b>Units</b>	Will place the unit of measure in the selected block.( inch, MM)
<b>P/C Flag</b>	Will display the feature as being "Probed" or "Constructed".
<b># of Pts</b>	Will include the number of points measured on that feature.
<b>Text</b>	Will allow user defined text to be added to the report.
<b>Tol Type</b>	Displays the type of feature tolerance. (i.e. Form, True Position, Cartesian etc.)

---

<b>Datum</b>	If Datum is selected, a flyout menu will appear. <b>Zero</b> - Will display the zero reference feature. <b>Skew Feature</b> - Displays the feature used to create a skew.
<b>Pass/Fail</b>	Indicates a Pass/Fail tolerance condition.
<b>Time Stamp</b>	Displays the Time at which the feature was printed.
<b>Date Stamp</b>	Displays the date the feature was printed.

### **Position**

#### **Actual**

ALL	Print all possible actual coordinates.
X	Print X actuals.
Y	Print Y actuals
R	Force print Polar Radius actuals.
A	Force print Polar Angular actuals
X/R	Print the X value if in Cartesian mode and Radius if in Polar
Y/A	Print the Y value if in Cartesian and Angle if in Polar.
Sa	Print the Start Angle of a Radius or Arc.

#### **Nominals**

ALL	Print all possible nominal values.
X	Print X nominal value.
Y	Print Y nominal value.
R	Print Polar Radius nominal value.
A	Print Polar Angle nominal value.
X/R	Print the X nominal if in Cartesian mode and Radius if in Polar
Y/A	Print the Y nominal if in Cartesian and Angle if in Polar.

**Tolerance**

- ALL Will print out all applied tolerances.
- +X Prints the X tolerance Value.  
-X Prints the X tolerance Value.  
Sample:  $+0.005/-0.005$ , will appear as **.005** next to +X or -X.
- +Y Prints the Y tolerance Value.  
-Y Prints the Y tolerance Value.  
Sample:  $+0.005/-0.005$ , will appear as **.005** next to +Y or -Y.
- Tol Dia Prints the tolerance diameter for a feature with True Position tolerancing.
- Concen Prints the Concentricity tolerance for a feature.

**Limits**

- ALL Will print all applied limits.
- +X Prints X tolerance Limits added to nominal.  
-X Prints X tolerance Limits subtracted from the nominal.  
Sample: If a feature with a nominal of 1.000  $+0.005/-0.005$  then the limit will be shown as (+X) 1.005 and (-X) .995.
- +Y Prints Y tolerance Limits added to nominal.  
-Y Prints Y tolerance Limits subtracted from the nominal.  
Sample: If a feature with a nominal of 1.000  $+0.005/-0.005$  then the limit will be shown as (+Y) 1.005 and (-Y) .995.

**Deviation**

- ALL This will print the Deviation (Difference between actual and nominal) of all toleranced features
- X Prints the X deviation.
- Y Print the Y deviation.

**Over/Under**

ErrDia The deviation above or below the tolerance zone of a feature that has true position applied to it.

**Pass/Fail**

ALL Provides Pass/ Fail indication for all toleranced features  
X Provides Pass/Fail indicator for X values  
Y Provides Pass/Fail indicator for Y values  
ToIDia Provides Pass/Fail indicator fro true position tolerancing.

***Size*****Actual**

ALL Prints all actual size values.  
r Prints Radius actual value.  
d Prints Diameter actual value.  
L Prints Length actual values.  
x Prints the X actual value of a distance.  
y Prints the Y actual value of a distance.  
A Print actual values of Polar X and Y.  
X/R Prints X value of a distance if in Cartesian and Radius of in polar  
Y/A Prints Y value of a distance if in Cartesian and Angle if in polar.  
< Prints Angle actual values.  
h Prints the actual Height.  
Al Prints the actual Arc length.  
Sa Prints the actual start angle of an Arc.

**Nominal**

ALL Prints the nominal value of all toleranced features.  
r Print Radius nominal values.  
d Print Diameter nominal values.  
L Print nominal value of a length.  
x Print the X nominal of a distance.  
y Print the Y nominal of a distance.  
< Print the nominal value of an angle.  
h Print the nominal value of a height.

**Tolerance**

- ALL Will print tolerance values for all features that have been toleranced for size.
- +r/-r Prints the positive or negative radius tolerance value.  
Sample:  $+0.005/-0.005$ , will appear as **.005** next to +r or -r
- +d/-d Prints the positive or negative dimension tolerance.  
(See sample above).
- +L/-L Prints the positive or negative length tolerance. (See above).
- +x/-x Prints the positive or negative x tolerance values of a distance  
(See sample above).
- +y/-y Prints the positive or negative y tolerance values of a distance.  
(See sample above).
- +</-< Prints the positive or negative tolerance values of an angle.  
(See sample above).

**Limits**

- All Will print all applied limits
- +r Prints the radius limits added to the nominal.  
-r Print the radius limits subtracted from the nominal.  
Sample: If a radius nominal is  $.500 +0.005/-0.005$  then the limits will be shown as (+r) .505, (-r) .495
- +d Prints the diameter limits added to the nominal.  
-d Prints the diameter limits subtracted from the nominal.  
(See sample above.)
- +L Prints length limits added to the nominal.  
-L Prints length limits subtracted from the nominal.  
(See sample above.)

+x	Prints X tolerance Limits of a distance added to nominal.
-x	Prints X tolerance Limits of a distance subtracted from the nominal. (See sample above.)
+y	Prints X tolerance Limits of a distance added to nominal.
-y	Prints X tolerance Limits of a distance subtracted from the nominal. (See sample above.)
+<	Prints angle Limits added to nominal.
-<	Prints angle Limits subtracted from the nominal. (See sample above.)
+h	Prints height Limits added to nominal.
-h	Prints height Limits subtracted from the nominal. (See sample above.)

### Deviation

ALL	This will print the deviation (Difference from nominal to actual of all toleranced features.
r	Prints the deviation of a Radius.
d	Prints the deviation of a Diameter.
L	Prints deviation of a Length.
x	Prints the X deviation of a distance.
y	Prints the Y deviation of a distance.
<	Prints the deviation of an Angle.
h	Prints the deviation of a Height.

### Pass/Fail

ALL	Provides pass/fail indication for all size features that have been toleranced
r	Provides a pass/fail indication for a Radius.
d	Provides a pass/fail indication for a Diameter.
L	Provides a pass/fail indication for a Length.
x	Provides a pass/fail indication for the X of a distance.
y	Provides a pass/fail indication for the Y of a distance.
<	Provides a pass/fail indication for an Angle.
h	Provides a pass/fail indication for a Height.



***Other*****Actual**

ALL	Provides all of the following:
+ T	The + T form value
-T	The - T form value
+T/-T	The absolute value of the +T is added to the absolute value of the -T giving you a total size of form.
Runout	The Actual Runout value
Paral	The actual Parallelism value
Perp	The actual Perpendicular value

**Tol Zone**

ALL	Will print all of the tolerance zones.
Form	Print the Form zone tolerance.
Runout	Print the Runout zone tolerance.
Orientation	Print the Orientation zone tolerance.
TolDia	Print the Tol. Diameter zone tolerance.

**Pass/Fail**

ALL	Prints PASS/FAIL indication for all zone type tolerances
Form	Prints PASS/FAIL indication for Form zone tolerance.
Runout	Prints PASS/FAIL indication for Runout zone tolerance.
Orientation	Prints PASS/FAIL indication for Orientation zone tolerance.
TolDia	Prints PASS/FAIL indication for Tol. Diameter zone tolerance



## INDEX

# of Pts, 11-22

+T, 3-10

-T, 3-10

### A

About Program, 2-5

Actual, 11-23, 11-25, 11-28

Add a Tool, 5-12

Allow Relations, 5-5, 6-2

An ellipsis, 2-4

Angle, 2-8, 3-4

Angle Construction, 4-26

Angle measurement, 4-21

Angle Tolerance of a Line, 11-7

Angle Tolerance, 8-17

Annotation, 5-3

Append, 11-16

Arc Measurement, 4-20

Arc, 2-8, 3-3, 4-31

ASCII CODES, 11-20

Auto Confirm, 2-9

Auto Construct, 5-4

Auto Focus, 10-2

Auto Number, 11-17

Auto Prog. from Features, 2-14, 7-18

Auto Program, 7-2, 7-4

Auto Repeat Mode, 6-3

Auto Zoom, 2-12, 5-11, 7-22

Average Point, 4-13

Axes, 9-2

Axis Board Test, 9-5

Axis Orientation, 4-6

### B

Backward Annotation, 5-3

Browse button, 11-4

### C

Calibration One, 3-6

Cartesian, 3-4

Cartesian Tolerance, 8-17, 11-7

Cautions about F.O. C.s, 10-17

CBF, 8-25

Center, 3-18

Center on Position Indicator, 2-12, 3-5

Change All, 3-14, 3-15

Change button (Measure Magic), 6-5

Change Button, 3-12

Changing a Distance, 3-17

Changing an Angle, 3-16

Changing Distances, 3-18

### C

Changing Tangents, 3-19

Changing the feature name, 3-9

Check Mark, 2-4

Checking the Light Levels, 10-19

Circle, 2-8, 3-3

Circle Indicator, 5-10

Circle measurement, 4-16 t, 7-7

Circularity, 8-17

Clear Features, 7-15

Click, double-click, or drag, 1-3

Clicking, 3-5

Clipboard, 11-4

Close Program Name, 2-15

Closing a Window, 1-7

CNC I/O Test, 9-7

CNC, 10-2

Column Header, 11-8, 11-22

Command-equivalent functions., 7-9

Complimentary angle, 4-23

Concentricity, 8-17, 8-21

Connecting the Edge Box 10-19

Connecting the Edge Detector, 10-16

Connecting the Ref. Sensor, 10-17

Connecting the Screen Sensor, 10-17

Construct a Distance, 7-8

Constructing a feature, 4-25

Control-menu box, 1-5

Conventions, 4-1

Copy Selected Features, 2-7

Copy, 11-22

Count direction, 4-6

Create, 2-8

Create a Circle, 4-30

Create a Line, 4-29, 4-30

Create a Point, 4-29

Create an Arc, 4-31

Creating A Form, 11-6

Creating features, 4-28

Creating the SPC Chart, 10-37

Crosshair Indicator, 5-10

Crosshair, 2-9

Custom ASCII, 11-21

Customizing names, 3-26

Customizing, 5-1

Cut Selected Features, 2-7

Cut, 11-22

### D

Date Stamp, 11-23

Datum Menu, 2-8

Datum, 4-9, 8-3, 11-23

DDE, 7-9, 8-37

Decimal Degrees, 5-8, 9-2

## INDEX

- Default Calibration, 2-10
  - Degrees Minutes Seconds, 5-8
  - Delay, 7-9
  - Delete A Step, 7-13
  - Delete a Tool, 5-12
  - Delete Selected Features, 2-7, 7-6
  - Delete, 11-22
  - Deleting Programs/
    - Deleting Sessions, 7-25
  - Delimiter, 11-19, 11-21
  - Demonstration slide, 4-6
  - Deselect All Features, 2-7
  - Deviation, 11-24, 11-27
  - Digital Readout, 3-1
  - Dimmed command name, 2-4
  - Display resolution, 9-2
  - Distance Measurement, 4-18
  - Distance to Line, 3-17
  - Distance Width Tolerance, 8-21
  - Distance, 2-8, 3-3
  - Dragging, 3-5
  - DRO, 2-11
  - Dynamic Data Exchange, 10-32
- E**
- Edge Detection Operation, 10-14
  - Edge Detector, 10-1
  - Edge IO Test, 9-8
  - Edge, 2-9
  - Edit Program Step, 2-14
  - Edit (Tolerance), 8-23
  - Edit Button, 7-10
  - Edit Calibration, 2-10, 10-27
  - Edit Form, 11-4, 11-6
  - Edit Header, 11-11, 11-21
  - Edit menu, 2-7, 11-22
  - Edit program steps, 7-10
  - Editing a Program, 3-28
  - Editing Teach, 10-21
  - Editing User Programs, 7-10
  - Electronic Protractor, 10-1, 10-5
  - Ellipsis, 7-10
  - Enabling Reference Marks, 4-8
  - Encoder resolution, 9-2, 9-3
  - End Recording, 2-16, 7-8
- E**
- Enlarging a window, 1-11
  - Entering a Point, 4-3
  - Establish a Ref. Frame, 4-9, 7-3
  - Establish a Reference, 7-7
  - Establish a ZERO Datum, 7-5
  - Excluded angle, 4-23
  - Exit to windows, 1-13, 2-6
  - Exit, 11-21
  - Export to ASCII File, 7-9
  - Export To DXF, 2-6, 7-19
  - Exporting to Excel, 8-35
  - External light source, 10-29
- F**
- Farthest, 3-18
  - Feat.# box, 8-14
  - Feature column, 11-7
  - Feature default type, 5-5
  - Feature List, 2-11, 3-7, 4-10
  - Feature Name Display, 5-11
  - Feature Name, 3-9, 3-14
  - Feature Stamps, 3-20
  - Feature Type, 11-22
  - Feature Types, 8-13
  - Feature, 8-1
  - File menu, 11-21
  - File size, 2-5
  - Filtration Threshold, 5-7
  - Find Feature command, 8-25
  - Find Feature, 2-7, 8-12
  - Fixed run Program Mode, 7-2, 9-7
  - Font Size, 11-22
  - Foot switch button., 10-4
  - Foot switch, 10-1, 10-3
  - Footswitch setup, 9-8
  - Force Teach, 10-28
  - Form Disclaimer, 8-20
  - Form Information, 3-10
  - Form Tolerance, 8-25, 11-7
  - Forward Annotation, 5-3
  - Frame command, 8-3
- G**
- General menu, 11-22
  - Grid, 5-11
  - Group Tolerancing, 8-25
  - Group Tolerance
    - Pause pass/fail, 8-26
    - Print pass/fail, 8-26
- H**
- Header On Each Page, 11-21
  - Height, 2-8, 3-4
  - Heights, 5-7
  - Hidden, 3-13, 5-5
  - Hide Name, 3-13
  - How Edge Detection Works, 10-15
- I**
- Ignore Errors, 7-15
  - Import From DXF, 2-6

## INDEX

Importing Autocad DXF Files, 7-18  
Included angle plus 180°, 4-23  
Included angle, 4-23  
Insert a Step, 7-12

### K

Keyboard, 1-1

### L

Language, 5-14  
Length Tolerance, 11-7  
Level, 2-9  
Light control Quick- Sliders, 10-30  
Light Control step, 10-31  
Light Level, 10-20  
Light Levels, 2-10  
Limits, 11-24, 11-26  
Line Editing, 7-10  
Line measurement, 4-14  
Line, 2-8, 3-3  
Linear Error Compensation, 9-3, 9-4  
LMC Tolerance, 8-17  
Lock Calibration Data, 9-7  
Lock Preferences, 9-6  
Lock programs, 7-2  
Lock QC4000 at Full Size, 9-7  
Lock, 7-16  
Locks Setup, 9-6  
Locks, 5-14, 9-6  
Logic Operators, 8-14  
LSFB, 8-25

### M

Machine 0,0, 10-8  
Machine Zero, 2-8, 4-8, 7-3, 8-7, 9-8  
Manual Execution Mode, 7-15  
Maximize button, 1-5  
Measure Magic  
    Probing Techniques, 4-34  
    Rules, 6-3  
    M Magic, 2-8, 3-3, 4-34, 6-1, 7-4  
Measure menu, 2-8  
Menu bar, 1-5, 2-4  
Menu Conventions, 2-4  
Minimize buttons, 1-5  
MMC Tolerance, 8-17  
Moving a window, 1-9  
Multi-point measurements, 8-9

### N

Name the program, 7-6  
Nearest, 3-18  
New Calibration, 2-10  
New Column, 11-10, 11-9, 11-22  
New Form., 11-6, 11-7, 11-21  
New Session, 2-5, 7-4  
NLEC, 10-1, 10-8  
No Tolerance, 11-7  
Nominal, 11-25  
Nominals, 11-23  
Non-Linear Error Correction, 9-6, 10-8  
Normal, 3-12  
Number of Steps, 2-5

### O

Open Form, 11-21  
Open Session, 2-5  
Open, 2-13  
Opening a window, 1-6  
Optical Edge Detector, 10-14  
Optimize Path, 2-15  
Options, 10-1  
Orientation Tolerance, 8-22, 11-7  
Orientation, 5-9  
Other menu, 11-28  
Outlier Detection, 5-6  
Output Device, 11-16  
Over/Under, 11-25  
Overwrite Always, 11-17

### P

P/C Flag, 11-22  
Palletize, 7-15  
Parallelism, 8-17, 8-22  
Part View, 2-11, 3-23  
Part Zeros, 8-3  
Pass/Fail, 11-10, 11-23, 11-25, 11-27, 11-28  
Paste, 11-22  
Paste, 2-7  
Pause pass/fail, 8-26  
Pause Program Execution, 2-16  
Pause, 7-12  
Perpendicularity, 8-17, 8-22  
Phantom, 3-13, 5-5  
Point filtering tuning parameters, 5-6  
Point Filtration, 5-6, 7-16, 9-6  
Point measurement, 4-11  
Point, 2-8, 3-3  
Polar Coordinates, 8-2

## INDEX

- Polar, 3-4
- Position Indicator, 3-23, 5-10
- Position menu, 11-23
- Position Tolerance
  - (See Tolerance of Location), 8-20
- Position, 11-10
- Post Form Feed, 11-5
- Pre Form Feed, 11-5
- Preference Menu, 5-1
- Preferences, 2-6, 11-21
- Preferences
  - Allow Relations, 5-5
  - Angle, 5-8
  - Circle Indicator, 5-10
  - Crosshair Indicator, 5-10
  - Feature default type, 5-5
  - Feature Name display, 5-11
  - Grid, 5-11
  - Heights, 5-7
  - Language, 5-14
  - Locks, 5-14
  - Measure, 5-3
  - Measure Magic, 5-5
  - Orientation, 5-9
  - Outlier Detection, 5-6
  - Part View, 5-8
  - Position Indicator, 5-10
  - Preselection, 5-4
  - Rectangle Indicator, 5-10
  - Results, 5-13
  - Right mouse button, 5-4
  - Safety Net, 5-4
  - Sound, 5-2
- P**
- Preferences
  - Toolbox, 5-12
  - Zoom, 5-11
- Print Column Headings, 11-21
- Print Date/Time, 7-12
- Print Grid Lines, 11-21
- Print Header, 11-21
- Print Part View, 2-6
- Print pass/fail, 8-26
- Print Selected Features, 2-6, 3-6
- Print settings, 9-9
- Print, 7-12
- Print/Pause directive, 8-19
- Printer, 11-4
- Printing Features, 11-2
- Probe Menu, 2-9
- Probe Offset, 10-27
- Program Menu, 2-13
- Programming
  - Auto Gen. from features, 7-20
  - Delete Steps, 7-13
  - Import from DXF, 7-19
  - Run Program, 7-10, 7-21
  - Store Programs, 7-10
  - Program View window, 3-27
  - Program View, 2-11, 7-8
- Q**
- Q axis, 10-1, 10-5
- Q-CNC, 10-2
- QC4000 SCREEN, 2-1
- Quick- Sliders, 10-30
- Quitting the qc-4000, 1-13
- R**
- Radix, 9-2
- Record a Program, 7-6
- Record Into "Program Name, 2-13
- Record Into, 7-12
- Record New, 2-13
- Record Zoom, 2-12, 7-22
- Recording Icon, 7-7
- Recording a program, 7-3, 7-4
- Rectangle Indicator, 5-10
- Reference Frame, 4-9
- Reference Mark Calibration, 4-8
- Reference Mark indicators, 4-7
- Reference marks, 4-7
- Reference Point, 8-3, 10-8
- R**
- Reference sensor, 10-15
- Refresh Part View, 2-13, 3-26
- Regenerate Features, 2-15, 7-13
- Report function, 11-3
- Report Header, 2-6
- Report Wizard Menu, 11-21
- Report Wizard, 11-1
- Report, 2-6
- Repositioning a Window, 1-9
- Restore button, 1-5
- Restoring an Icon or Window, 1-12
- Results Information, 3-10
- Results Window, 2-11, 3-10
- Results, 5-13
- Reverse Axis, 4-6
- Reverse Direction, 3-17
- Roundness, 8-25
- Run "Program Name, 2-14
- Run DOS/Windows Program, 7-9
- Run, 2-14
- Runout Tolerance, 11-7
- Runout, 8-17, 8-23
- S**
- Save "Program Name, 2-13
- Save As, 2-14
- Save Form As, 11-21

## INDEX

- Save Form, 11-13, 11-21
- Save Session As, 2-3, 2-5
- Save Session, 2-5
- Screen sensor, 10-15
- Scroll bars, 1-6
- Select All Features, 2-7
- Selecting a measurement
  - (keyboard), 4-2
  - (mouse), 4-2
- Selecting features, 3-8, 3-24
- Self Teach, 7-2
- Session, 8-1
- Set Machine Zero, 4-8, 7-3, 8-8, 9-8
- Setting NLEC Grid, 10-12
- Setting the Q Axis, 10-5
- Setting up NLEC, 10-10
- Show Edge Detector, 5-10, 10-25
- Show Feature Names, 2-13
- Show Hidden Features, 2-13
- Show Name, 3-13, 3-26, 5-5
- Show Path, 2-15
- Show Position Indicator, 2-13
- Shrink the QC-4000 to an Icon, 1-10
- Shutdown, 1-13, 2-6
- Sigma Factor, 5-7
- S**
- Singular mode, 6-2
- Size menu, 11-25
- Size Tolerance, 8-21
- Sizing the windows, 1-8
- Skew (On Two Circles), 4-27
- Skew, 2-9, 3-4, 4-9, 7-5, 8-3
- Skewing, 7-3
- Software Fence, 9-8
- SPC Demonstration, 10-33
- SPC Link, 2-6, 10-36
- SPC, 10-2, 10-32
- SPC-Link commands, 10-33
- Special Steps, 2-14, 7-12
- Starting the QC-4000, 1-2
- Statistical Process Control, 10-32
- Status Bar, 2-2, 2-11, 3-1
- Straightness, 8-17, 8-25
- Substep, 3-28, 7-11
- Supervisor Setup menu, 9-1
- Supervisor Setup Screen, 9-1
- Supervisor Setup, 2-6
- System Settings, 7-8
- Systems Settings, 7-14
- T**
- Tangent Circle, 4-33
- Targeting Points, 4-3
- Teach to Master, 2-10
- Teach, 2-10, 3-5, 10-20, 10-21
- The Sensors, 10-15
- Time (military or standard), 9-2
- Time Stamp, 11-23
- Times to Execute, 7-16
- Title Bar, 1-5, 2-2
- Tol Type, 11-22
- Tol Zone, 11-28
- Tolerance All, 8-25
- Tolerance Button, 3-12
- Tolerance for a Distance, 11-7
- Tolerance name, 8-19
- Tolerance of Location, 8-20
- Tolerance Printout, 8-31
- Tolerance report, 8-31
- Tolerance Type, 8-20
- Tolerance, 11-24, 11-26
- Toleranced Features Only, 11-5
- Tolerancing, 8-17
- Toolbox Icons, 3-3
- Toolbox Maker, 5-12
- Toolbox, 2-11, 3-2
- Total Path Length, 2-5
- True Position Tolerance, 8-17, 11-7
- U**
- Units, 2-8, 3-4, 11-22
- Use As Recorded, 7-15
- Use Machine Skew, 7-14
- Use Machine Zero, 7-14
- User Message, 2-1, 7-9, 7-124
- User Programs, 7-2
- Using the Control-menu box, 1-7
- V**
- VED2, 10-2
- View Menu, 2-12
- View Settings, 9-9
- Visible, 3-13
- W**
- Warn On Overwrite, 11-17
- What is Edge Detection, 10-14
- Wildcard, 2-7
- Window border, 1-6
- Window corner, 1-6
- Windows Menu, 2-11
- Writing to an ASCII File, 11-4, 11-15
- X**
- X-Bar & R Chart, 10-37
- Z**
- Zero Datum, 8-6

## *INDEX*

Zero, 2-9, 3-1, 3-4  
Zeroing, 7-3  
Zoom function, 3-25  
Zoom In On Area, 2-12  
Zoom in on Area, 3-5, 3-25  
Zoom In, 2-12, 3-4  
Zoom Out, 2-12, 3-4  
Zoom to Fit, 2-12, 3-5, 7-22, 7-24  
Zoom to Selected Features, 2-12, 3-5  
Zoom, 5-11